HOTEL COST ESTIMATING GUIDE

JN+A & HVS DESIGN

JN+A and HVS DESIGN

HOTEL COST ESTIMATING GUIDE

2020

TABLE OF CONTENTS

HOTEL COST ESTIMATING GUIDE 2020

Introduction	.6
Guide to the Cost Guide	.8
About the Cost Guide1	10
Cost Estimating Summary Sheets1	12
Cost Estimating Tables by Hotel Tier1	14
Economy	14
Extended Stay	22
Midscale	34
Upscale	48
Upper Upscale	34
Luxury	30
Industry Insights	96
Designing to a Schedule	98
Freight and Warehouse Pricing10	00
Sponsor Recognition)2
Glossary of Terms)8



Each of the last 11 years, we have released the update to the Hotel Cost Estimating Guide at the NYU Investment Conference in early June. This year, we won't be seeing everyone at the conference due to the pandemic. I thought it might be helpful to address some questions that are arising relating to design and construction once we emerge from this difficult time.

How will the pandemic affect construction costs?

- 1. Labor rates will likely drop as they generally do following the beginning of a recession. The amount of that drop will vary by market and specific industry, but it generally has been in the 7-10% range in past recessions.
- 2. The new regulations regarding social distancing will likely cause installation inefficiencies, which may offset some or all of the labor rate savings.
- 3. The requirement for temperature monitoring, drop ship deliveries, laborer contact records, etc. will no doubt lead to increasing general conditions costs.

What kinds of delay and additional cost claims and clauses are likely to arise from the pandemic?

- 1. The contractors will be seeking coverage for costs related to the shutdown of jobsites such as paying the salaries of employees dedicated to the project who cannot work remotely, but are not allowed to work to local restrictions.
- 2. Out-of-town contractors imported for a specific project will have housing costs to pay even if no workers are staying in the apartments.
- 3. The "four workers to a room" situation, which some contractors have used in the past, may not be possible going forward, requiring an increase to housing costs.
- 4. The application of Force Majeure clauses to Covid-related shutdowns will be a major contract issue in the near future.

How will the current social distancing and hyper cleaning trends impact hotel design?

- 1. The design of self-service food and beverage outlets is going to be dramatically affected in the short run. Most select-service properties have a self-service breakfast scheme which will be difficult if not impossible under current guidelines.
- 2. The spacing of seating and the use of communal seating will be dramatically different moving forward. This could result in more space being needed to feed guests in the morning in select-service hotels. The capacity of hotel restaurants will be impacted leading to a potential increase in room service demand. Room service had been scaled back in recent years with the advent of grab and go alternatives.
- 3. Group and convention meeting space demands may ask for different spacing of seating resulting in lower seat counts and, therefore, requiring more large spaces. The key will likely be flexible seating that can be rearranged into a variety of seating options. This will likely cause lower margins in existing meeting spaces and food and beverage options.



4. The material choices going forward may be more focused on durability with cleaning supplies.

Are there any other impacts to the Covid crisis?

- 1. Group travel may take years to perhaps return to what it was prior to the crisis. This will impact occupancy numbers, convention center driven markets, and the travel industry in general.
- 2. The "tele-working" acceptance will likely become even more commonplace than it was prior to the pandemic. This will change the way a number of industries operate. Office footprints will likely be smaller. The computer meeting tools and apps will evolve at a super-fast pace. Demand for high speed internet bandwidth will be even higher than before.
- 3. As with all downturns in the hospitality sector, we expect to see some owners with cash taking advantage of the slow times (buying at good prices, renovating while occupancies are low, and leveraging their negotiating power).

We hope all of you are surviving during this difficult time in the industry.

GUIDE TO THE COST GUIDE

by Warren G. Feldman, AIA, ISHC CEO of JN+A / Principal of HVS Design

The 2020 Hotel Cost Estimating Guide is the twelfth edition of this comprehensive planning tool. JN+A and HVS Design developed the Guide to examine construction and FF&E costs for renovations in each hotel tier. The Guide is intended to be just that - a guide to help provide approximate costs for your softgoods or full renovation with flexibility to customize your preliminary budget to fit your scope. As with any generic budgeting tool, the final costs for a specific project should be developed on a case-specific basis. Below are some tips to aid in directing you to get the most out of this helpful tool.

Overall

The Guide is divided into six hotel tiers. Each tier has an assumed hotel size and configuration from which the cost data is derived. The assumptions are a way for you to compare against your property to help determine which tier and hotel size it fits.

Once you have selected a hotel tier, you should determine if you want a quick budget number or want to develop a more detailed version of the budget. For quick numbers use the summary pages (Pages 12 and 13). If you want a detailed budget, then use the detailed numbers within the tier you have selected.

The next step is to apply the scope of your renovation to the forecasted numbers, having determined which tier your hotel falls under and determined your scope of work for the renovation. Let's assume you have a six-story, 200-room hotel that needs a softgoods guestroom renovation, but you are planning to keep the artwork, lighting, and soft seating. Due to the type of hotel, you know that your project falls under the Upper Upscale tier.

Softgoods Renovation

For a quick preliminary budget using the summary page only, you would use the guestroom softgoods renovation price for an Upper Upscale hotel in the cost range of between \$9,061 and \$12,424. Now, skip ahead to the adjustments section.

For a more detailed budget you would skip ahead to the Guestroom Softgoods Renovation for the Upper Upscale (page 66) category, and highlight each item that you are replacing including demo and FF&E installation. Each item has a cost range (low to high) and an average cost. Utilizing the average cost number will provide you with the general idea of the cost. Add up the select items needed for your renovation and multiply by the number of keys. This number will provide you with an approximate idea of how much it will cost to do a basic softgoods renovation including construction and FF&E.

Guestroom Softgoods Renovation				
Assume guestroom area of approximately 15' x 24', plus 8' x 8' bathroom and 7' x 8' entry / closet area (472 SF).				
	R	ANGE		AVERAG
Demolition	\$446.25	to	\$589.67	\$528.4
FF&E Installation	\$175.00	to	\$292.42	\$227.5
Artwork, Mirrors, and Accessories (Installed Package)	\$886.36	to	\$1,304.24	\$1,096.0
Full-height Framed Dressing Mirror	\$211.43	to	\$278.08	\$244.6
Bed Skirt or Box Spring Cover	\$171.50	to	\$203.94	\$187.4
Decorative Pillow	\$106.56	to	\$138.49	\$122.5
Carpet and Pad	\$893.48	to	\$1,051.26	\$960.2
Desk Lamp	\$153.47	to	\$191.58	\$172.7
Floor Lamp	\$278.10	to	\$371.83	\$324.7
End Table Lamp	\$276.04	to	\$352.26	\$314.1
Nightstand or Bracket Lamp (2)	\$392.43	to	\$523.76	\$458.3
Welcome Light (in Existing Location)	\$223.77	to	\$293.94	\$262.9
Desk Chair (including Fabric)	\$331.66	to	\$438.78	\$385.5
Lounge Chair (including Fabric)	\$689.07	to	\$903.31	\$796.1
Ottoman (including Fabric)	\$283.25	to	\$379.04	\$330.9
Sleeper Sofa (including Fabric; Assumes King Rooms Only)	\$520.67	to	\$673.11	\$596.8
Paint Textured or Drywall Ceiling	\$316.98	to	\$443.77	\$405.7
Paint Trim (Base and Crown)	\$445.11	to	\$707.00	\$628.1
Paint Entry Doors, Closet Doors, Frames, and Grilles	\$150.00	to	\$214.78	\$182.5
Vinyl Wallcovering (LY 54")	\$1,550.62	to	\$2,225.01	\$1,896.6
Window Treatments (Sheer, Blackout, Hardware, Installed)	\$559.29	to	\$847.69	\$703.4
Guestroom Softgoods Renovation Cost Per Key	\$9.061.02	to	\$12.423.96	\$10.825.8



Additional Renovation / Full Renovation

The Guide provides an additional level of renovation costs in the event you want to do a full renovation or even additional elements of a full renovation. Armed with your softgoods renovation cost, you decide you also want to replace the beds, add a tile foyer to the entry, and get new televisions. Under the Upper Upscale Guestroom – Add for a Full Renovation category (page 66), you should highlight the three additions to your scope. Add the average costs associated with each line item.

Guestroom - Add for a Full Renovation				
	R		AVERAGE	
Bedsets (Box Spring, Mattress, and Frame)	\$852.95	to	\$1,101.41	\$977.18
Entry Area Hard Surface Flooring	\$831.60	to	\$1,170.68	\$1,005.04
TV and Mount (HD LCD, including Programming Allowance)	\$1,284.67	to	\$1,460.24	\$1,371.60
Guestroom Full Renovation Additional Cost Per Key	\$2,969.22	to	\$3,732.33	\$3,353.8

Take the additional renovation costs and add them to your total softgoods number (before you multiply by the number of keys). Take the combined total of the softgoods and additional renovation item total and multiply that number by the number of keys to get the total construction and FF&E cost for your proposed renovation.

Total Guestroom Renovation Cost				
		AVERAGE		
Guestrooms Softgoods Renovation Cost Per Key	\$9,061.02	to	\$12,423.96	\$10,825.88
Guestroom Full Renovation Additional Cost Per Key	\$2,969.22	to	\$3,732.33	\$3,353.82
Total Construction and FF&E Cost Per Key	\$12,030.23	to	\$16,156.28	\$14,179.70

Adjustments

Once you have the construction and FF&E costs for your project, you also need to account for things not included in the costs above. As stated in the Guide, these costs do not include Professional Fees, Contingency, Operating Supplies + Equipment, Attic Stock, Freight or Sales Tax, the Contractor's General Conditions, Overhead and Profit, etc. Typically, the design cost of a project including the Architecture, Interior Design, Project Management, and Procurement make up about 10% of the overall budget. The freight and tax vary greatly by location and should be adjusted based upon your specific location. For the freight and tax calculation, assume that the FF&E costs are 50% of the costs of the construction and FF&E. For our sample project, we will assume it is a Midwestern location with 6% state and local tax. You also need to apply a contingency to the budget. If you are doing a quick budget, you might apply 15%. If you are doing a detailed version, it might be 10%.

1	AVERAGE		
\$9,061.02	to	\$12,423.96	\$10,825.88
\$815.49	to	\$1,118.16	\$974.33
\$271.83	to	\$496.96	\$378.91
\$1,014.83	to	\$1,403.91	\$1,217.91
\$1,674.48	to	\$2,316.45	\$2,009.55
\$12,837.65	to	\$17,759.43	\$15,406.59
	\$9,061.02 \$815.49 \$271.83 \$1,014.83 \$1,674.48	\$815.49 to \$271.83 to \$1,014.83 to \$1,674.48 to	\$9,061.02 to \$12,423.96 \$815.49 to \$1,118.16 \$271.83 to \$496.96 \$1,014.83 to \$1,403.91 \$1,674.48 to \$2,316.45

Adjustments for Detailed Budget				
		RANGE		AVERAGE
Costs for Guestroom Renovation from the Detail Pages	\$12,030.23	to	\$16,156.28	\$14,179.70
Construction Markups (18% of Construction)	\$1,082.72	to	\$1,454.07	\$1,276.17
Freight and Tax (6%-8%)	\$360.91	to	\$484.69	\$425.39
Professional Fees	\$1,347.39	to	\$1,809.50	\$1,588.13
Contingency (10%)	\$1,482.12	to	\$1,990.45	\$1,746.94
Total Construction and FF&E Cost Per Key	\$16,303.37	to	\$21,895.00	\$19,216.33



About the Author

Mr. Feldman has expertise in all facets of Project Management, Architecture, Interior Design, Design Management, and Construction Administration. His experience includes work as Architect and Owner's Representative in the direction and management of commercial, institutional, educational, residential, and hospitality projects. Complementing his education in Architecture, Mr. Feldman completed his Juris Doctorate from Georgetown University in December 1998 and is a member of the Maryland Bar.

ABOUT THE COST GUIDE

CONTRIBUTORS

2020 COST GUIDE CONTRIBUTORS



JN+A and HVS Design 7361 Calhoun Place, Suite 310 Rockville, MD 20855 ph: 301.670.1635 | ph: 240.683.7123 info@nehmer.com | designinfo@hvs.com nehmer.com | hvsdesign.com



Benjamin West 428 CTC Boulevard Louisville, CO 80027 ph: 303.530.3885 info@benjaminwest.com benjaminwest.com



Freight, Warehouse & Installation Management

Audit Logistics 1172 Century Drive, Suite 245 Louisville, CO 80027 ph: 303.994.7418 dhenke@auditlogistics.com auditlogistics.com



The Allied Group 2109 Heck Avenue Neptune, NJ 07753 ph: 732.751.2522 info@addastar.com addastar.com



Continental Contractors 410 Severn Avenue, Suite 410 Annapolis, MD 21403 ph: 410.263.6514 info@continentalcontractors.com continentalcontractors.com



Reliance Construction Company, LLC 1025 South Dixie Highway Delray Beach, FL 33483 ph: 561.613.5423

rocky@reliancefl.com reliancefl.com Ironstar Construction, Inc. 2600 E.Southlake Blvd. #120-234 Southlake, TX 76092 ph: 760.585.5399 winklerd@ironstarconstructioninc.com

The JN+A and HVS Design Team would like to thank the above firms for the large amount of time they volunteered to provide us with unit cost data for each of the categories and sub-categories included in the Guide. JN+A and HVS Design have successfully worked with each of these firms on past projects. All of them are well-known, regionally- or nationally-based contractors that specialize in the hospitality industry. These organizations are acutely aware of the crucial need for efficient operation in hotels with regard to noise and guest satisfaction, as well as the primary need to produce complete, guest-ready hotel rooms, broad areas of costs that will likely apply to most types of hotel renovations, and can provide preliminary insight when planning for such work.



HOTEL MARKET TIERS | MODEL HOTEL CRITERIA

Line item costs included in this Guide have been estimated using the following models in each hotel tier:

Economy | 90 guestrooms, 3 stories (all with guestrooms), 30 rooms/floor

Extended Stay | 150 guestrooms, 4 stories (all with guestrooms), 38 rooms/floor


Midscale | 135 guestrooms, 5 stories (all with guestrooms), 27 rooms/floor

Upscale | 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor

Upper Upscale | 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor

Luxury | 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor

COST CATEGORIES



When using this Guide, please note that since project-specific conditions will affect the final cost of every renovation project, this Estimating Guide will not include all costs for each hotel renovation. Costs such as Professional Fees, Contingency, Operating Supplies + Equipment, Attic Stock, Freight, Sales Tax, etc. have not been included. However, this Guide does identify broad areas of costs that will likely apply to most types of hotel renovations and can provide preliminary insight when planning for such work.

HOTEL COST ESTIMATING GUIDE 2020 SUMMARY

Cost Per Guestroom | Per Seat | Per Square Foot

		Economy	Extended Stay	Midscale
Guestrooms & Corridors				
Guestroom	Softgoods Renovation Add for Full Renovation	\$2,214 to \$3,190 Per Guestroom \$2,130 to \$2,744 Per Guestroom	\$6,232 to \$8,566 Per Guestroom \$9,909 to \$14,087 Per Guestroom	\$4,886 to \$6,767 Per Guestroom \$4,742 to \$6,199 Per Guestroom
	Softgoods Renovation (1)			
Bathroom	Add for Full Renovation (2)	\$703 to \$1,076 Per Guestroom \$3,589 to \$4,801 Per Guestroom	\$1,025 to \$1,625 Per Guestroom \$7,605 to \$9,849 Per Guestroom	\$1,212 to \$1,975 Per Guestroom \$7,166 to \$9,306 Per Guestroom
Guestroom Corridors (3,4)		\$422 to \$638 Per Guestroom	\$867 to \$1,214 Per Guestroom	\$948 to \$1,269 Per Guestroom
Public Spaces				
Reception Area	Softgoods Renovation (5)	\$32 to \$44 Per SF (180)	\$12 to \$16 Per SF (1400)	\$13 to \$17 Per SF (2500)
	Add for Full Renovation	\$141 to \$189 Per SF (180)	\$69 to \$93 Per SF (1400)	\$60 to \$84 Per SF (2500)
Marketplace / Sundries	Full Renovation	N/A	\$457 to \$672 Per SF (85)	\$457 to \$672 Per SF (85)
Public Restrooms	Softgoods Renovation Add for Full Renovation	\$7 to \$10 Per SF (80) \$73 to \$99 Per SF (80)	\$8 to \$12 Per SF (480) \$75 to \$102 Per SF (480)	\$11 to \$17 Per SF (480) \$76 to \$105 Per SF (480)
ood & Beverage Facilities			······································	
	Coffeende Deservation	600 to 600 Dec 05 (400)	620 to 640 Dec 05 (4400)	\$20 to \$40 Dec 05 (4000)
Restaurant Economy: Breakfast Bar Only)	Softgoods Renovation	\$20 to \$28 Per SF (400) \$667 to \$936 Per Seat (12)	\$30 to \$42 Per SF (1400) \$560 to \$773 Per Seat (76)	\$30 to \$43 Per SF (1296) \$581 to \$813 Per Seat (68)
	Add for Full Renovation	\$42 to \$61 Per SF (400) \$1,396 to \$2,037 Per Seat (12)	\$66 to \$96 Per SF (1400) \$1,219 to \$1,767 Per Seat (76)	\$92 to \$135 Per SF (1296) \$1,763 to \$2,564 Per Seat (68)
Bar & Lounge	Softgoods Renovation	N/A	N/A	\$51 to \$72 Per SF (720)
	Add for Full Renovation	N/A N/A	N/A N/A	\$683 to \$953 Per Seat (54) \$156 to \$216 Per SF (720)
		N/A	N/A	\$2,075 to \$2,881 Per Seat (54)
Kitchen (6) Economy: Storage Pantry Only)	Excl. Equipment Select Kitchen Equipment	N/A N/A	\$55 to \$94 Per SF (80) \$32 to \$43 Per SF (80)	\$17 to \$25 Per SF (400) \$15 to \$19 Per SF (400)
	Select Ritchen Equipment	N/A	φ32 10 φ43 Fer 31 (00)	
unction Spaces				
Prefunction	Softgoods Renovation Add for Full Renovation	N/A N/A	N/A N/A	\$25 to \$34 Per SF (750) \$76 to \$119 Per SF (750)
Ballroom	Softgoods Renovation	N/A	N/A	N/A
	Add for Full Renovation	N/A	N/A	N/A
leeting Rooms	Softgoods Renovation Add for Full Renovation	N/A N/A	\$15 to \$21 Per SF (552) \$60 to \$85 Per SF (552)	\$13 to \$18 Per SF (2964) \$74 to \$103 Per SF (2964)
Board Rooms	Softgoods Renovation	N/A	N/A	N/A
Joard Rooms	Add for Full Renovation	N/A	N/A	N/A
• • • • • • • • • • • • • •				
Guest Amenities				
Exercise Facility	Softgoods Renovation Add for Full Renovation (7)	N/A N/A	\$18 to \$31 Per SF (728) \$104 to \$136 Per SF (728)	\$24 to \$34 Per SF (728) \$109 to \$142 Per SF (728)
Outdoor Swimming Pool (8)		N/A	\$17 to \$30 Per SF (1656)	\$19 to \$34 Per SF (1656)
ndoor Swimming Pool (8,9)		N/A	\$55 to \$77 Per SF (1656)	\$57 to \$82 Per SF (1656)
Dutdoor Amenities		N/A	\$44,639 to \$70,206 Allowance	\$48,248 to \$76,740 Allowance
nfrastructure				
Outdoor Parking (Seal Lot & Strip Structured Parking	e Spaces)	\$394 to \$997 Per Space (100)	\$394 to \$997 Per Space (175)	\$394 to \$997 Per Space (15
andscaping (10)		N/A \$11,740 to \$19,723 Allowance	N/A \$23,480 to \$32,050 Allowance	N/A \$23,480 to \$32,050 Allowance
Common Additives (11)				
New Electronic Key System		\$226 to \$326 Per Key	N/A	N/A
New RFID Key System (Nested V	ViFi)	N/A	\$339 to \$475 Per Key	\$339 to \$475 Per Key
lew RFID Key System (Nested V levator Cab Finishes levator Modernization	ViFi)	N/A \$7,044 to \$9,862 Per Cab	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab
lew RFID Key System (Nested V levator Cab Finishes levator Modernization Hydraulic, per Cab Traction, per Cab	ViFi)	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Sto N/A
lew RFID Key System (Nested V levator Cab Finishes levator Modernization Hydraulic, per Cab Traction, per Cab scalator Modernization lectronic Signage Boards		N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Sto N/A N/A
lew RFID Key System (Nested V Elevator Cab Finishes Elevator Modernization Hydraulic, per Cab Traction, per Cab Escalator Modernization Electronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction	reen (42" diag.) Screens	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Sto N/A \$11,740 to \$16,025 Per Screen N/A N/A N/A
lew RFID Key System (Nested V levator Cab Finishes levator Modernization Hydraulic, per Cab Traction, per Cab Scalator Modernization lectronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo	reen (42″ diag.) Screens r Screen (18″ diag.)	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Sto N/A N/A N/A \$11,740 to \$16,025 Per Screen
lew RFID Key System (Nested V levator Cab Finishes levator Cab Finishes Traction, per Cab Traction, per Cab detertonic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo TAC Unit Direct Replacement, N wo-Pipe Horizontal Fan Coil Uni	reen (42″ diag.) Screens r Screen (18″ diag.)	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A N/A	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Sto N/A N/A N/A \$11,740 to \$16,025 Per Screen N/A N/A N/A
leve RFID Key System (Nested V ilevator Cab Finishes levator Modernization Hydraulic, per Cab iscalator Modernization lectronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeter Replacement, N wo-Pipe Horizontal Fan Coil Uni jour-Pipe Vertical Fan Coil Uni our-Pipe Vertical Fan Coil Uni	reen (42" diag.) Screens r Screen (18" diag.) VIC Finishes I Direct Replacement , NIC Finishes Jirect Replacement with Drywall Repair	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A N/A	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A	\$333 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Std N/A \$11,740 to \$16,025 Per Screen N/A N/A N/A \$11,070 to \$12,33 Each N/A N/A N/A
leve RFID Key System (Nested V levator Cab Finishes levator Modernization Hydraulic, per Cab scalator Modernization lectronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo TAC Unit Direct Replacement, N wo-Pipe Horizontal Fan Coil Unit Dur-Pipe Vertical Fan Coil Unit aundry Equipment (Direct Equip 75# Washer 125# Dryer	reen (42" diag.) Screens r Screen (18" diag.) VIC Finishes I Direct Replacement , NIC Finishes Jirect Replacement with Drywall Repair	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A \$1,070 to \$1,233 A N/A \$1,070 to \$1,233 A N/A \$1,070 to \$1,233 A N/A \$1,070 to \$1,233 Each N/A \$23,480 to \$32,050 \$35,220 to \$44,377	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A \$1,070 to \$1,233 \$1,070 to \$1,233 \$1,070 to \$1,233 \$1,070 to \$1,233 \$1,070 \$1,233 Each N/A N/A \$23,480 to \$32,050 \$35,220 \$44,377 Each	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Sto N/A \$11,740 to \$16,025 Per Screen N/A N/A N/A \$11,740 to \$16,025 Per Screen N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A N/A \$23,480 to \$32,050 Each \$35,220 to \$44,377 Each
ew RFID Key System (Nested V levator Cab Finishes levator Modernization Hydraulic, per Cab Traction, per Cab Scalator Modernization lectronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo TAC Unit Direct Replacement, N wo-Pipe Horizontal Fan Coil Unit Dur-Pipe Vertical Fan Coil Unit aundry Equipment (Direct Equip 75# Washer 125# Dryer Ironer / Folder orte Cochere - Re-image: Demo	reen (42" diag.) Screens r Screen (18" diag.) IIC Finishes Direct Replacement , NIC Finishes Direct Replacement with Drywall Repair ment Replacement with Access)	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A \$1,070 to \$12,33 Each N/A \$1,070 to \$12,33 Each N/A \$23,480 to \$32,050	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$1,070 to \$1,233 N/A N/A \$1,070 to \$1,233 N/A N/A \$1,070 \$1,233 Each N/A \$1,070 \$1,233 S23,480 to \$32,050	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Str N/A N/A N/A \$111,740 to \$16,025 Per Screen N/A \$1,233 Each N/A \$1,070 to \$1,233 Each N/A \$N/A \$N/A \$1,233 Each N/A \$1,233 Each \$N/A \$23,480 to \$32,050 Each
leve RFID Key System (Nested V levator Cab Finishes levator Cab Finishes levator Modernization Hydraulic, per Cab Traction, per Cab Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo TAC Unit Direct Replacement, No-Pipe Horizontal Fan Coil Uni our-Pipe Vertical Fan Coil Unit D aundry Equipment (Direct Equip 75# Waber 125# Dryer Ironer / Folder forte Cochere - Re-image: Demo fuestroom ADA Modifications Bathtub Room	reen (42" diag.) Screens r Screen (18" diag.) IIC Finishes Direct Replacement , NIC Finishes Direct Replacement with Drywall Repair ment Replacement with Access)	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A S1,070 to \$1,233 Each N/A N/A N/A \$10,700 to \$12,33 Each N/A N/A N/A \$10,700 to \$12,050 Each \$17,399 to \$33,130 Each \$117,399 to<\$133,130	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$86,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$14,377 Each \$147,399 to<\$133,130	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab N/A N/A N/A \$110,572 Per Cab Stac N/A N/A N/A \$110,572 Per Screen N/A N/A \$16,025 Per Screen N/A N/A N/A \$1,070 \$1,233 Each N/A N/A N/A \$10,700 \$1,233 Each N/A N/A N/A \$10,700 \$1,233 Each \$14,309 to<\$44,377
ew RFID Key System (Nested V levator Cab Finishes levator Cab Finishes levator Cab Finishes Traction, per Cab Scalator Modernization lectronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo TAC Unit Direct Replacement, No- Pipe Horizontal Fan Coil Unit Die Vertical Fan Coil Unit Di aundry Equipment (Direct Equip 75# Washer 125# Dryer Ironer / Folder orte Cochere - Re-Image: Demo uestroom ADA Modifications Bathub Room Roll-in Shower Room Xerior Signage - Monument	reen (42" diag.) Screens r Screen (18" diag.) IIC Finishes Direct Replacement , NIC Finishes Direct Replacement with Drywall Repair ment Replacement with Access)	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each \$1,070 to \$1,233 Each \$23,480 to \$32,050 Each \$35,220 to \$44,377 Each \$117,399 to \$133,130 Each \$14,500 to \$23,100 Per Key \$16,000 to \$22,808 Per Key \$16,000 to \$22,808 Per Key \$5,870 to \$8,629 Each	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A \$1,070 to \$1,233 Each N/A \$10,700 to \$1,233 Each N/A \$10,700 \$1,233 Each \$11,740 \$44,377 Each \$11,740 \$49,308 Allowance \$11,740 \$25,808 Allowance \$11,740 to \$27,808 \$11,740 to \$27,808	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab N/A N/A N/A \$110,572 Per Cab State N/A N/A N/A \$110,572 Per Screen N/A N/A N/A N/A \$10,070 to \$12,33 Each N/A N/A N/A \$10,700 to \$12,33 Each N/A N/A N/A N/A \$10,700 to \$12,33 Each \$117,309 to \$33,130 Each \$117,409 to \$49,308 Allowance \$11,740 to \$49,308 Allowance \$11,740 to \$25,808 Per Key \$19,602 to \$25,808 Per Key \$11,740 to \$17,258 Each
lew RFID Key System (Nested V ilevator Cab Finishes ilevator Modernization Hydraulic, per Cab Traction, per Cab Scalator Modernization disctoronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo TAC Unit Direct Replacement, N wo-Pipe Horizontal Fan Coll Unit Jour-Pipe Vertical Fan Coll Unit aundry Equipment (Direct Equip 75# Washer 125# Dryer Ironer / Folder Forte Cochere - Re-image: Demo Suestroom ADA Modifications Bathtub Room Roll-in Shower Room Xterior Signage - Monument Xterior Signage - Highway	reen (42" diag.) Screens r Screen (18" diag.) (UC Finishes t Direct Replacement , NIC Finishes Direct Replacement with Drywall Repair ment Replacement with Access)	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A N/A \$10,070 to \$1,233 Each N/A N/A N/A N/A \$117,399 to \$133,130 Each \$14,500 to \$23,100 Per Key \$14,500 to \$23,100 Per Key \$14,500 to \$22,608 Per Key \$5,870 to \$8,629 Each \$23,480 to \$32,050 Each	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$1,070 to \$1,233 S23,480 to \$32,050 S44,377 Each \$35,220 to<\$44,377	\$333 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 St) N/A N/A \$111,740 to \$16,025 Per Screen N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$1,700 to \$1,233 Each \$35,220 to \$44,377 Each \$11,740 to \$49,308 Allowance \$11,740 to \$49,308 Allowance \$17,371 to \$23,100 Per Key \$19,602 to \$25,808 Per Key \$11,740 to \$17,258 Each \$29,350 to \$312,132 Each
lew RFID Key System (Nested V ilevator Cab Finishes ilevator Modernization Hydraulic, per Cab Traction, per Cab Traction, per Cab discretation Modernization ilectronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Lobby / Prefunction Additional Meeting Room Doo TAC Unit Direct Replacement, N wo-Pipe Horizontal Fan Coil Unit our-Pipe Vertical Fan Coil Unit D aundry Equipment (Direct Equip 75# Waher 125# Dryer Ironer / Folder Yote Cochere - Re-image: Demo Suestroom ADA Modifications Bathtub Room Roll-in Shower Room Xeterior Signage - Monument Exterior Signage - Monument Exterior Signage - Mighway Xeterior Signage - New Exterior E	reen (42" diag.) Screens r Screen (18" diag.) (UC Finishes I Direct Replacement , NIC Finishes Direct Replacement with Drywall Repair ment Replacement with Access) blish and Replace	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$23,480 to \$32,050 Each \$35,220 to \$44,377 Each \$117,399 to \$133,130 Each \$147,500 to \$23,100 Per Key \$5,870 to \$8,629 Each \$23,480 to \$32,050 Each \$23,480 to \$32,050 Each \$23,480 to \$32,2050 Each	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$86,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$1,070 to \$1,233 N/A N/A \$10,70 to \$1,233 N/A N/A \$11,740 \$44,377 \$11,740 \$49,308 \$11,740 \$25,808 \$11,740 \$25,808 \$11,740 \$25,808 \$11,740 \$10 \$21,300 \$11,740 \$11,740 \$25,808 \$11,740 \$10 \$11,740 \$10 \$31,00 \$10 \$31,00 \$11,740 \$11,740 \$15,740 \$11,740 \$10 \$11,740 \$10 \$12,550	\$333 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab N/A N/A N/A \$110,572 Per Cab Stat N/A N/A N/A \$110,700 \$16,025 Per Screen N/A N/A N/A \$10,070 to \$1,233 Each N/A N/A \$10,070 to \$1,233 N/A N/A N/A \$117,309 to \$13,130 \$117,409 to \$44,377 \$117,409 to \$23,000 \$117,400 to \$24,9308 <allowance< td=""> \$117,400 to \$25,808 Per Key \$119,602 to \$25,808 Per Key \$11,740 to \$38,213 Each \$29,350 to \$38,213 Each \$35,220 to \$44,377 Each </allowance<>
lew RFID Key System (Nested V ilevator Cab Finishes ilevator Addenization Hydraulic, per Cab Traction, per Cab Scalator Modernization ilectronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction ilectronic Signage Boards Meeting Room Doo PTAC Unit Direct Replacement, No- Pioe Portoratal Fan Coil Unit iour-Pipe Vertical Fan Coil Unit Substrom ADA Modifications Bathtub Room Roll-in Shower Room Xeterior Signage - Monument Xeterior Signage - New Exterior E tumpster Enclosure (CMU Walls Yower-operated Bi-parting Entrain preplace - Natural Gas with Ston	reen (42" diag.) Screens r Screen (18" diag.) VIC Finishes I Direct Replacement , NIC Finishes Direct Replacement with Drywall Repair ment Replacement with Access) wish and Replace Strand Sign in Existing Location Wood Gate, Bollards, Concrete Pad) ice Doors (Inner and Outer at a Vestibule) e Hearth and Surrounding Wall (Public Area)	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A N/A N/A N/A S1,070 to \$1,233 Each N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$10,700 to \$12,33 Each \$14,500 to \$32,050 Each \$117,399 to \$133,130 Each \$14,500 to \$23,100 Per Key \$16,000 to \$25,808 Per Key \$5,870 to \$8,629 Each \$23,480 to<<\$28,352	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A \$1,070 to \$1,233 Each N/A \$10,700 to \$1,233 Each N/A \$10,700 \$1,233 Each N/A N/A N/A \$11,740 \$10 \$32,050 \$11,740 \$38,213 Each \$11,740 \$38,213 Each \$23,350 to \$38,213 Each \$35,220 to \$47,377 Each \$11,740 to \$49,308 Allowance \$11,740 to \$37,258 Each \$23,350 to \$38,213 Each \$35,260 to \$34,77 Each	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab N/A N/A \$110,572 Per Cab \$117,40 \$16,025 \$117,30 \$12,33 \$10,070 \$1,233 \$10,070 \$1,233 \$10,070 \$1,233 \$10,700 \$1,233 \$10,700 \$1,233 \$10,700 \$1,233 \$10,804 \$10,804 \$10,804 \$11,740 \$11,740 \$11,740 \$11,740 \$10,803 \$11,740 \$10,804 \$11,740 \$10,804 \$11,740 \$10,804 \$11,740 \$11,740 \$11,740 \$11,740 \$11,740 \$11,740 \$11,740 \$11,7820
lew RFID Key System (Nested V levator Cab Finishes levator Cab Finishes levator Cab Finishes levator Cab Cab Scalator Modernization lectronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo 07TAC Uni Direct Replacement, N wo-Pipe Horizontal Fan Coil Uni Your-Pipe Vertical Fan Coil Uni Your Folder Yourd Cocher - Re-image: Demo Sustoro Signage - Neomumet Exterior Signage - Highway Exterior Signage - New Exterior E Jumpster Enclosure (CNU Walls Sower-operated Bi-parting Entrar Tireplace - Natural Gas with Ston	reen (42" diag.) Screens r Screen (18" diag.) UC Finishes t Direct Replacement , NIC Finishes incert Replacement with Drywall Repair ment Replacement with Access) blish and Replace	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A \$10,70 to \$1,233 N/A N/A N/A \$117,399 to \$133,130 S117,399 to \$23,100 \$14,500 to \$22,650 \$24,800 to<	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$\$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A N/A \$\$1,070 to \$1,233 Each N/A N/A N/A \$\$1,070 to \$1,233 N/A N/A \$\$1,070 to \$1,233 N/A N/A \$\$11,740 \$44,377 \$\$11,740 \$49,308 \$\$11,740 \$17,258 \$25,808 Per Key \$11,740 \$17,258 \$24,310 Per Key \$11,740 \$17,258 \$25,500 \$38,213 \$22,500 \$44,377 \$35,220 to<\$44,377	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab (5 Str N/A N/A \$110,572 Per Cab (5 Str N/A N/A \$110,572 Per Cab (5 Str N/A N/A \$110,572 Per Screen N/A N/A \$10,070 \$1,233 Each N/A \$10,70 \$1,233 Each N/A \$117,309 \$133,130 \$11,740 \$133,130 \$11,740 \$133,000 \$11,740 \$133,430 \$11,740 \$17,256 \$11,740 \$17,258 \$29,350 \$333,100 \$12,500 \$35,220 \$12,500 \$35,640 \$22,500 \$34,377 \$22,500 \$35,640 \$12,500 \$15,900 \$11,865 \$19,500
lew RFID Key System (Nested V Elevator Cab Finishes Elevator Modernization Hydraulic, per Cab Traction, per Cab Scalator Modernization Electronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Lobby / Prefunction Additional Lobby / Prefunction Additional Meeting Room Doo YTAC Unit Direct Replacement, N wo-Pipe Horizontal Fan Coil Unit Direr-Pipe Vertical Fan Coil Unit Cour-Pipe Vertical Fan Coil Unit Steff Vasher 125# Dryer Torder / Folder Profer Cochere - Re-image: Demo Suestroom ADA Modifications Bathtub Room Roll-in Shower Room Sterior Signage - Moument Sterior Signage - Moument Sterior Signage - Moument Sterior Signage - Moument Sterior Signage - New Exterior E Signage - Moutural Gas with Ston dd Screening for Buffet in Resta Replace Guestroom Connecting [reen (42" diag.) Screens r Screen (18" diag.) (UC Finishes t Direct Replacement , NIC Finishes Direct Replacement with Drywall Repair ment Replacement with Access) blish and Replace Strand Sign in Existing Location (Wood Gate, Bollards, Concrete Pad) ice Doors (Inner and Outer at a Vestibule) e Hearth and Surrounding Wall (Public Area) jurant nd Hardware Doors and Hardware	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A \$10,070 to \$1,233 Each N/A N/A N/A N/A \$23,480 to \$32,050 Each \$35,220 to \$44,377 Each \$117,399 to \$133,130 Each \$147,500 to \$23,100 Per Key \$5,870 to \$8,629 Each \$23,480 to<	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$\$6,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A N/A \$\$1,070 to \$1,233 Each N/A N/A N/A \$\$1,070 to \$1,233 N/A N/A \$\$1,070 to \$1,233 N/A N/A \$\$14,740 to \$44,377 \$\$11,740 to \$44,377 \$\$11,740 to \$44,308 \$\$11,740 to \$49,308 \$\$11,740 to \$23,100 \$\$11,740 to<\$23,100	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab N/A N/A \$110,572 Per Cab \$110,572 Per Cab \$10,572 Per Cab \$10,572 Per Cab N/A N/A \$11,740 to \$16,025 N/A N/A \$1,070 \$1,233 Each N/A N/A \$23,480 to \$32,050 N/A N/A \$11,740 to \$44,377 \$11,740 to \$44,306 \$11,740 to \$49,308 \$11,740 to \$41,740 \$11,740 to \$47,258 \$11,740 to \$43,213 \$11,740 to \$41,220 \$11,740 to \$42,308 \$11,740 to \$41,220 \$11,740 to
Traction, per Cab Escalator Modernization Electronic Signage Boards Basic System - One Lobby Sc Additional Lobby / Prefunction Additional Meeting Room Doo PTAC Unit Direct Replacement, N two-Pipe Horizontal Fan Coll Unit our-Pipe Vertical Fan Coll Unit our-Pipe Vertical Fan Coll Unit 25# Dryer Troner / Folder Orte Cochere - Re-image: Demo Suestroom ADA Modifications Bathtub Room Roll-in Shower Room Exterior Signage - How Exterior E Jumpster Enclosure (CMU Walls Cweroperate Bi-parting Entrar Trieplace - Natural Gas with Ston dd Screening for Buffet in Resta Replace Guestroom Entry Door a Replace Guestroom Connecting [Replace Contor Service Doors a	reen (42° diag.) Screens r Screen (18° diag.) (UC Finishes I Direct Replacement , NIC Finishes Direct Replacement with Drywall Repair ment Replacement with Access) wish and Replace Brand Sign in Existing Location , Wood Gate, Bollards, Concrete Pad) (oce Doors (Inner and Outer at a Vestibule) e Hearth and Surrounding Wall (Public Area) nurant ind Hardware Doors and Hardware and Hardware	N/A \$7,044 to \$9,862 Per Cab \$49,549 to \$66,343 Per Cab (3 Stops) N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A \$1,070 to \$12,33 Each N/A \$10,070 to \$32,050 \$10,070 to \$32,050 Each \$35,220 to \$44,377 Each \$117,399 to<\$133,130	\$339 to \$475 Per Key \$9,979 to \$15,162 Per Cab \$66,065 to \$88,458 Per Cab (4 Stops) N/A N/A N/A N/A N/A N/A N/A \$1,070 to \$1,233 Each N/A N/A N/A \$10,70 to \$1,233 Each N/A N/A N/A \$11,70 to \$22,605 \$11,740 \$44,377 Each \$11,740 to \$49,308 \$11,740 to \$49,308 \$11,740 to \$22,600 \$11,740 to \$34,77 \$2,500 Per Key \$11,740 \$11,740 to \$34,77 \$35,220 to \$44,377 \$11,740 to \$47,286 \$11,740 to \$34,277 \$35,220 to \$34,377	\$339 to \$475 Per Key \$3,356 to \$12,209 Per Cab \$82,581 to \$110,572 Per Cab N/A N/A \$110,572 Per Cab N/A N/A N/A \$11,740 to \$16,025 N/A N/A \$10,070 to \$12,33 RAA N/A \$10,070 to \$1,233 RAA N/A N/A N/A \$10,070 to \$1,233 Rach N/A \$10,070 to \$1,233 Rach N/A \$10,070 to \$1,233 Rach \$11,330 Each \$35,240 to \$44,377 Still,740 to \$49,308 \$11,740 to \$49,308 \$11,740 to \$49,313 \$11,740 to \$49,320 \$25,608 Per Key

HOTEL COST ESTIMATING GUIDE 2020 SUMMARY

Cost Per Guestroom | Per Seat | Per Square Foot

		Upsca	le			U	pper Ups	cale				Luxu	ry	
\$7,022 \$8,929	to to	\$9,757 \$11,624	Per Guestroom Per Guestroom		\$9,061 \$14,072	to to	\$12,424 \$18,454	Per Guestroom Per Guestroom		\$15,049 \$23,644	to to	\$20,832 \$31,830	Per Guestroom Per Guestroom	
\$1,528 \$8,208	to	\$2,379 \$11,623	Per Guestroom Per Guestroom		\$1,812 \$11,192	to to	\$2,842 \$16,300	Per Guestroom Per Guestroom		\$3,307 \$19,394	to	\$4,913 \$28,627	Per Guestroom Per Guestroom	
\$1,259	to to	\$1,718	Per Guestroom		\$1,719	to	\$2,236	Per Guestroom		\$19,394	to to	\$2,649	Per Guestroom	
ψ1,200	10	ψ1,1 TO	1 of Oddouroom	1	ψ1,110		QL,200			\$1,010		¢2,010		
\$14 \$104	to to	\$20 \$146	Per SF (3500) Per SF (3500)		\$20 \$107	to to	\$27 \$150	Per SF (4800) Per SF (4800)		\$33 \$164	to to	\$45 \$234	Per SF (4000) Per SF (4000)	
\$296	to	\$437	Per SF (205)		\$307	to	\$442	Per SF (205)				N/A		
\$17 \$101	to to	\$25 \$158	Per SF (1440) Per SF (1440)		\$20 \$118	to to	\$30 \$184	Per SF (1440) Per SF (1440)		\$18 \$142	to to	\$26 \$203	Per SF (1920) Per SF (1920)	
\$39	to	\$52	Per SF (3000)		\$38	to	\$51	Per SF (4560)	7	\$47	to	\$63	Per SF (3200)	
\$827 \$101	to to	\$1,121 \$142	Per Seat (140) Per SF (3000)		\$883 \$102	to to	\$1,194 \$142	Per Seat (195) Per SF (4560)		\$1,240 \$100	to to	\$1,684 \$138	Per Seat (120) Per SF (3200)	
\$2,167	to	\$3,039	Per Seat (140)		\$2,395	to	\$3,330	Per Seat (195)		\$2,676	to	\$3,687	Per Seat (120)	
\$50 \$893	to to	\$69 \$1,225	Per SF (1600) Per Seat (90)		\$72 \$1,232	to to	\$99 \$1,691	Per SF (1200) Per Seat (70)		\$81 \$1,865	to to	\$110 \$2,536	Per SF (1200) Per Seat (52)	
\$142 \$2,529	to to	\$205 \$3,652	Per SF (1600) Per Seat (90)		\$209 \$3,576	to to	\$298 \$5,111	Per SF (1200) Per Seat (70)		\$275 \$6,357	to to	\$421 \$9,726	Per SF (1200) Per Seat (52)	
\$26 \$19	to to	\$39 \$28	Per SF (3500) Per SF (3500)	-	\$19 \$21	to to	\$28 \$27	Per SF (4200) Per SF (4200)		\$19 \$23	to to	\$29 \$30	Per SF (4200) Per SF (4200)	7
			(***** /											
\$19 \$64	to to	\$25 \$92	Per SF (7250) Per SF (7250)	7	\$23 \$74	to to	\$30 \$110	Per SF (6250) Per SF (6250)		\$38 \$131	to to	\$49 \$191	Per SF (3100) Per SF (3100)	
\$11	to	\$14	Per SF (8550)		\$13	to	\$18	Per SF (4500)		\$15	to	\$19	Per SF (4800)	
\$109 \$14	to to	\$157 \$19	Per SF (8550) Per SF (11900)		\$204 \$21	to to	\$305 \$28	Per SF (4500) Per SF (8400)		\$250 \$38	to to	\$370 \$53	Per SF (4800) Per SF (3000)	
\$72	to	\$97	Per SF (11900)		\$108	to	\$151	Per SF (8400)		\$174	to	\$247	Per SF (3000)	
\$24 \$99	to to	\$33 \$140	Per SF (728) Per SF (728)		\$28 \$107	to to	\$38 \$156	Per SF (1456) Per SF (1456)		\$37 \$142	to to	\$48 \$197	Per SF (1456) Per SF (1456)	
\$25 \$130	to to	\$37 \$169	Per SF (1092) Per SF (1092)		\$26 \$127	to to	\$36 \$167	Per SF (1456) Per SF (1456)		\$28 \$129	to to	\$38 \$167	Per SF (1820) Per SF (1820)	
\$28 \$70	to to	\$46 \$96	Per SF (2700) Per SF (2016)		\$24 \$81	to to	\$40 \$113	Per SF (3300) Per SF (2496)		\$17 \$90	to to	\$28 \$127	Per SF (6600) Per SF (3576)	
\$125,146	to	\$204,956	Allowance		\$228,824	to	\$335,464	Allowance		\$292,284	to	\$445,714	Allowance	
\$394	to	\$997	Per Space (486)				N/A		_	[N/A		
\$46,960	to	N/A \$73,961	Allowance		\$1,265 \$70,439	to to	\$1,859	Per Space (347) Allowance		\$1,359 \$105,659	to to	\$1,998	Per Space (352) Allowance	
¢40,500	10	\$70,001	Allowance	1	¢10,400	10	\$30,010	Allowance]	φ100,000	10	φ1 4 1,520	Allowance	
¢220	4-	N/A	Des Kau		6000	4-	N/A \$475	Des Kau		6000	4-	N/A	Des Kerr	
\$339 \$14,675	to to	\$475 \$20,832	Per Key Per Cab		\$339 \$20,545	to to	\$29,954	Per Key Per Cab		\$339 \$29,350	to to	\$475 \$38,213	Per Key Per Cab	
\$233,506	to	N/A \$294,218	Per Cab (9 Stops)	7	\$192,299	to	N/A \$240,054	Per Cab (7 Stops)		\$173,985	to	N/A \$215,375	Per Cab (6 Stops)	
		N/A			\$352,197	to	\$517,729	Per Flight		\$352,197	to	\$517,729		
\$17,610 \$5,870	to to	\$25,393 \$8,464	Per Screen Per Screen	7	\$17,610 \$5,870	to to	\$25,393 \$8,464	Per Screen Per Screen		\$29,350 \$9,783	to to	\$48,075 \$16,025	Per Screen Per Screen	
\$5,700	to	\$8,286 N/A	Per Screen		\$8,805	to	\$10,971 N/A	Per Screen		\$8,805	to	\$10,971 N/A	Per Screen	
\$1,800 \$2,599	to to	\$3,874 \$5,800	Each Each		\$2,599	to	N/A \$5,800	Each		\$2,599	to	N/A \$5,800	Each	
\$23,480	to	\$32,050	Each		\$23,480	to	\$32,050	Each		\$23,480	to	\$32,050	Each	
\$35,220 \$117,399	to to	\$44,377 \$133,130			\$35,220 \$117,399	to to	\$44,377 \$133,130	Each Each		\$35,220 \$117,399	to to	\$44,377 \$133,130		
\$29,350	to	\$67,798	Allowance		\$41,090	to	\$80,125	Allowance		\$58,699	to	\$130,665		
\$18,460 \$21,375	to to	\$27,120 \$29,380	Per Key Per Key		\$22,035 \$23,730	to to	\$39,387 \$45,200	Per Key Per Key		\$36,276 \$42,375	to to	\$48,486 \$54,240	Per Key Per Key	
\$17,610	to	\$23,421 N/A	Each		\$17,610	to	\$23,421 N/A	Each		\$17,610	to	\$23,421 N/A	Each	
\$46,960	to	\$56,704 N/A	Each		\$46,960	to	\$56,704 N/A	Each		\$46,960	to	\$56,704 N/A	Each	
\$27,500 \$11,865	to to	\$35,640 \$19,500	Allowance		\$27,500 \$16,950	to to	\$35,640 \$28,250	Per Pair Allowance		\$27,500 \$19,775	to to	\$35,640 \$29,663	Per Pair Allowance	
\$11,865 \$748	to to	\$56,500 \$950	Allowance Each	7	\$11,865 \$883	to to	\$56,500 \$1,243	Allowance Each		\$1,130	to	N/A \$1,720	Each	
\$1,630 \$1,356	to to	\$2,240 \$1,780	Each Each]	\$1,630 \$1,469	to to	\$2,486 \$1,898	Each Each		\$1,900 \$1,582	to to	\$3,277 \$2,195	Each Each	
\$790	to	\$891	Per Pair Each		\$790	to	\$891	Per Pair Each		\$790 \$1 105	to	\$891	Per Pair Each	

eneral Notes

- This estimating information is a guideline only. Before utilizing this information for any renovation, a full budget estimate should be prepared by JN+A and HVS Design.
- Sources: JN+A historical data, misc. purchasing organization unit price information, input from U.S. General Contractors, geographically diverse.
- Costs indicated in this Estimating Guide do NOT include Professional Fees, Contingency, Operating Supplies, and Equipment, Attic Stock, Freight or Sales Tax, etc.
- Costs indicated in this Estimating Guide do NOT include the Contractor's General Conditions, Overhead and Profit. Cost for Performance Bonds and Building Permits are NOT included.

ootnotes

- Includes vanity light, vinyl wallcovering, framed mirror, paint ceiling.
- Adds vanity (base), vanity top, faucet, stone / tile tub surround, shower valve, tub diverter, tub drain, tub refinish, porcelain tile floor with tile base.
- B. Includes carpet and double stick pad, vinyl wallcovering, sconce lighting, artwork, window treatments, paint ceiling, painted millwork running trim, furniture, signage, and ice machines.
- The guestroom component of a guest corridor occupies an area equal to the width of the guestroom, full height, and one half of the corridor width.
- Includes finishes and lighting upgrades, no electrical, HVAC or life safety upgrades, nor any reconfiguration.
 Allowance only; varies with site.
- . Assumes treadmills, elliptical, small free weights, small universal, towel display, dirty towel hamper, art, vinyl wallcovering, lighting, and flooring.
- Resurface pool bottom, resurface pool deck, new pool furniture; includes ADA lift.
- Includes interior finishes, lighting, pool pak HVAC.
- 10. Allowance only; varies geographically.
- Costs listed in common additives section are for items not typically included in the renovation scopes for the major categories. These costs assume that a full renovation is also occurring at the time of construction.



Prototype Hotel: 90 guestrooms, 3 stories, 30 rooms/floor Other assumptions and allowances are listed in each section below.

Guestroom Softgoods Renovation

Assume guestroom area of approximately 12' x 19' and 7' x 5' entry area with closet rack (303 SF). Ceilings 8' AFF, textured finish.

	RANGE					
Demolition	\$124.30	to	\$290.69	\$219.87		
FF&E Installation	\$167.81	to	\$292.42	\$223.65		
Artwork, Mirrors, and Accessories (Installed Package)	\$119.03	to	\$169.06	\$132.07		
Carpet and Pad	\$477.78	to	\$561.57	\$523.07		
Carpet Base	\$96.49	to	\$131.52	\$115.93		
Desk Lamp	\$57.77	to	\$74.11	\$66.11		
Nightstand or Bracket Lamp (2)	\$127.65	to	\$163.19	\$145.80		
Welcome Light (in Existing Location)	\$121.18	to	\$168.46	\$149.23		
Desk Chair (including Fabric)	\$101.85	to	\$139.15	\$120.85		
Paint Existing Knockdown-finish Walls	\$307.09	to	\$474.00	\$387.68		
Paint Textured or Drywall Ceiling	\$126.24	to	\$163.45	\$146.62		
Paint Entry Doors, Closet Doors, Frames, and Grilles	\$75.00	to	\$107.39	\$91.28		
Window Treatments (Sheer, Blackout, Hardware, Installed)	\$312.09	to	\$454.52	\$385.32		
Guestroom Softgoods Renovation Cost Per Key	\$2,214.26	to	\$3,189.54	\$2,707.45		

Guestroom - Add for a Full Renovation

	R		AVERAGE			
Casegoods Installation	\$203.40	to	\$326.29	\$273.18		
Bedsets (Box Spring, Mattress, and Frame)	\$580.25	to	\$736.07	\$659.46		
Headboard	\$220.94	to	\$315.95	\$269.60		
Nightstands	\$162.23	to	\$190.33	\$176.23		
Desk	\$271.92	to	\$351.38	\$312.48		
Closet Rack	\$101.00	to	\$148.31	\$126.98		
TV and Mount (HD LCD, including Programming Allowance)	\$589.81	to	\$675.47	\$631.68		
Guestroom Full Renovation Additional Cost Per Key	\$2,129.54	to	\$2,743.79	\$2,449.61		

Guestroom Full Renovation Additional Cost Per Key \$2,129.54

Guest Bathroom Softgoods Renovation

Assume guest bathroom area of 5' x 8'. Ceilings 8' AFF, textured finish.

	RANGE				
Demolition	\$87.79	to	\$169.50	\$113.35	
Artwork (Installed)	\$42.91	to	\$70.31	\$56.87	
Framed Mirror	\$62.61	to	\$76.84	\$69.51	
Vanity Lighting	\$162.20	to	\$195.25	\$179.42	
Paint Ceiling	\$21.20	to	\$30.00	\$26.38	
Paint Walls	\$76.32	to	\$108.00	\$90.49	
Shower Curtain and Hooks	\$32.66	to	\$35.85	\$34.27	
Curved Shower Rod	\$54.00	to	\$70.44	\$62.80	
Paint Door and Trim	\$75.00	to	\$100.00	\$87.00	
Regrout Floor Tile	\$88.00	to	\$220.00	\$142.22	
Guest Bathroom Softgoods Renovation Cost P	er Key \$702.69	to	\$1,076.18	\$862.33	

Prototype Hotel: 90 guestrooms, 3 stories, 30 rooms/floor Other assumptions and allowances are listed in each section below.

Guest Bathroom - Add for a Full Renovation					
	R		AVERAGE		
Additional Demolition	\$308.17	to	\$369.81	\$329.74	
Architectural Lighting	\$117.40	to	\$176.10	\$160.34	
Replace Bathroom Door and Hardware	\$410.90	to	\$576.90	\$512.18	
Electrical Upgrades (Add One GFI Outlet)	\$54.50	to	\$100.00	\$78.02	
Shower Valve and Head, Tub Diverter, Tub Drain	\$250.00	to	\$352.20	\$312.21	
Tub Surround (Solid Panel)	\$840.00	to	\$1,101.75	\$966.71	
Lavatory	\$134.47	to	\$149.00	\$143.10	
Faucet (and Connections)	\$146.90	to	\$201.71	\$169.80	
Vanity Top	\$278.94	to	\$418.60	\$352.36	
Vanity Base	\$210.41	to	\$297.14	\$252.90	
Toilet Accessories	\$176.10	to	\$234.80	\$207.50	
Tile Flooring	\$309.38	to	\$412.39	\$365.46	
Toilet and Seat	\$352.20	to	\$410.90	\$373.33	
Guest Bathroom Full Renovation Additional Cost Per Key	\$3,589.36	to	\$4,801.28	\$4,223.65	

Corridors

Per room with each unit 12' long by half of a 5'-wide corridor; 30 rooms per floor.

		ANGE		AVERAGE	
Demolition	\$39.60	to	\$48.84	\$42.82	
Artwork (Installed)	\$2.42	to	\$3.33	\$2.90	
Carpet and Pad	\$146.39	to	\$228.01	\$193.15	
Carpet Base	\$20.33	to	\$27.56	\$24.34	
Ceiling-mounted Lighting	\$4.24	to	\$5.87	\$5.20	
Paint Ceiling	\$17.28	to	\$27.00	\$22.88	
Signage Package (Room Numbers, Wayfinding, Complete)	\$56.50	to	\$73.56	\$64.88	
Vinyl Wallcovering (LY 54")	\$131.57	to	\$218.65	\$176.38	
Window Treatments (with Hardware and Installation)	\$3.47	to	\$5.04	\$4.28	
Corridors Renovation Cost Per Key	\$421.80	to	\$637.86	\$536.83	

Lobby Softgoods Renovation

Assume a 180 SF area. Ceiling 8' AFF.					
	RANGE			AVERAGE	
Demolition	\$253.58	to	\$310.64	\$283.88	
Artwork and Artifacts (Installed)	\$460.19	to	\$694.64	\$581.20	
Carpet and Pad	\$656.69	to	\$779.73	\$722.47	
Millwork (Refinish)	\$352.20	to	\$616.34	\$487.21	
Paint Drywall Ceiling	\$86.40	to	\$135.00	\$114.41	
Paint Doors and Trim	\$150.00	to	\$214.78	\$182.56	
Vinyl Wallcovering (LY 54", 40% Openings)	\$384.31	to	\$651.53	\$521.83	
Window Treatments (with Hardware and Installation)	\$463.50	to	\$683.20	\$576.90	
Seating Groups	\$2,933.44	to	\$3,797.32	\$3,374.53	
Lobby Softgoods Renovation Cost Subtotal	\$5,740.31	to	\$7,883.19	\$6,844.98	
Lobby Softgoods Renovation Cost Per SF	\$31.89	to	\$43.80	\$38.03	

Prototype Hotel: 90 guestrooms, 3 stories, 30 rooms/floor Other assumptions and allowances are listed in each section below.

Lobby - Add for a Full Renovation

•	RANGE			AVERAGE
Additional Demolition	\$845.27	to	\$1,065.04	\$948.39
Decorative Lighting	\$2,003.24	to	\$2,801.16	\$2,407.38
Electrical	\$1,090.22	to	\$1,535.67	\$1,325.46
Hard Surface Flooring	\$405.00	to	\$539.85	\$478.42
HVAC	\$422.64	to	\$532.52	\$474.20
Life Safety	\$534.60	to	\$630.00	\$569.81
Architectural Lighting	\$1,584.88	to	\$2,329.78	\$1,804.83
Front Desk (New Pods, in Existing Location)	\$11,300.00	to	\$15,500.00	\$13,064.34
Front Desk Equipment	\$3,521.97	to	\$4,191.14	\$3,820.16
Acoustical Ceiling Tile and Grid (New)	\$733.87	to	\$982.80	\$813.56
Drywall Partitions	\$2,916.00	to	\$3,849.12	\$3,462.74
Lobby Full Renovation Additional Cost Subtotal	\$25,357.69	to	\$33,957.08	\$29,169.29
Lobby Full Renovation Additional Cost Per SF	\$140.88	to	\$188.65	\$162.05

Marketplace / Sundries Shop

Typically, hotels in this market segment do not have marketplaces.

Public Restrooms Softgoods Renovation

Assume one, 80 SF unisex restroom. Ceiling 8' AFF.				
	RANGE			AVERAGE
Demolition	\$49.31	to	\$73.96	\$56.70
Artwork and Artifacts (Installed)	\$108.36	to	\$169.60	\$142.12
Framed Mirrors	\$92.09	to	\$121.04	\$107.04
Paint Drywall Ceiling	\$42.40	to	\$60.00	\$53.56
Paint Doors and Trim	\$72.50	to	\$110.11	\$91.32
Decorative Vanity Lighting	\$176.39	to	\$268.10	\$227.53
Public Restrooms Softgoods Renovation Cost Subtotal	\$541.05	to	\$802.82	\$678.27
Public Restrooms Softgoods Renovation Cost Per SF	\$6.76	to	\$10.04	\$8.48

Public Restrooms - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$939.19	to	\$1,232.69	\$1,080.07
Toilet Accessories	\$264.15	to	\$423.58	\$356.54
Replace Doors	\$821.25	to	\$891.00	\$854.04
Toilets / Urinals	\$482.50	to	\$900.00	\$699.50
Architectural Lighting	\$788.92	to	\$986.15	\$855.98
Tile Flooring	\$900.00	to	\$1,199.67	\$1,063.16
Motion-sensing Flush Valves	\$610.00	to	\$796.00	\$672.52
Motion-sensing Faucets	\$600.00	to	\$945.40	\$791.29
Vanity Top, Sinks	\$440.25	to	\$562.47	\$511.06
Public Restrooms Full Renovation Additional Cost Subtotal	\$5,846.25	to	\$7,936.96	\$6,884.16
Public Restrooms Full Renovation Additional Cost Per SF	\$73.08	to	\$99.21	\$86.05

Prototype Hotel: 90 guestrooms, 3 stories, 30 rooms/floor Other assumptions and allowances are listed in each section below.

Restaurant Softgoods Renovation

Assume a 12-seat breakfast bar area of approximately 20' x 20' (400 SF). Ceiling 8' AFF.

	RANGE			AVERAGE
Demolition	\$469.60	to	\$690.31	\$579.48
Artwork (Installed)	\$1,400.35	to	\$2,049.86	\$1,737.20
Carpet and Pad (80% of Floor Area)	\$1,273.25	to	\$1,513.07	\$1,401.48
Millwork Buffet, Host Station (Refinish)	\$469.60	to	\$887.54	\$684.67
Acoustical Tile Ceiling (New)	\$1,643.58	to	\$2,340.00	\$1,991.76
Paint Doors and Trim	\$65.54	to	\$89.00	\$79.61
Vinyl Wallcovering (LY 54", 40% Openings)	\$449.56	to	\$765.63	\$612.23
Window Treatments (with Hardware and Installation)	\$508.82	to	\$746.46	\$631.29
Dining Chairs (No Arms)	\$1,718.04	to	\$2,152.61	\$1,941.18
Restaurant Softgoods Renovation Cost Subtotal	\$7,998.34	to	\$11,234.47	\$9,658.90
Restaurant Softgoods Renovation Cost Per SF	\$20.00	to	\$28.09	\$24.15
Restaurant Softgoods Renovation Cost Per Seat	\$666.53	to	\$936.21	\$804.91

Restaurant - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$469.60	to	\$690.31	\$579.48
Buffet Equipment	\$1,173.99	to	\$1,725.76	\$1,448.70
Architectural Lighting	\$1,479.23	to	\$2,465.38	\$1,992.02
Electrical	\$2,465.38	to	\$3,451.53	\$2,785.87
Hard Surface Flooring (20% of Floor Area)	\$900.00	to	\$1,199.67	\$1,063.16
HVAC	\$986.15	to	\$1,972.30	\$1,494.02
Life Safety	\$1,479.23	to	\$2,465.38	\$1,992.02
Millwork Buffet, Host Station (New, in Existing Location)	\$3,164.00	to	\$4,500.00	\$3,831.22
Tables	\$395.52	to	\$500.66	\$449.11
Drywall Partitions	\$3,456.00	to	\$4,561.92	\$4,103.99
TV and Mount (55", including Programming Allowance)	\$786.41	to	\$910.87	\$844.40
Restaurant Full Renovation Additional Cost Subtotal	\$16,755.49	to	\$24,443.76	\$20,584.00
Restaurant Full Renovation Additional Cost Per SF	\$41.89	to	\$61.11	\$51.46
Restaurant Full Renovation Additional Cost Per Seat	\$1,396.29	to	\$2,036.98	\$1,715.33

Bar / Lounge

Typically, hotels in this market segment do not have bar / lounge areas.

Kitchen

Typically, hotels in this market segment do not have kitchens; a small pantry area is included in the breakfast bar costs above.

Prototype Hotel: 90 guestrooms, 3 stories, 30 rooms/floor Other assumptions and allowances are listed in each section below.

Function Spaces

Typically, hotels in this market segment do not have function spaces.

Exercise Facility

Typically, hotels in this market segment do not have exercise facilities.

Outdoor Amenities

Typically, hotels in this market segment do not have outdoor amenities or pools

Outdoor Parking

Assume 100 parking spaces, 9' x 19', and 25'-wide aisles.

		RANGE			AVERAGE	
Clean and Seal Asphalt		\$7,695.00	to	\$15,958.43	\$10,927.19	
Stripe Spaces		\$1,500.00	to	\$3,800.00	\$2,330.26	
Pavement Resurfacing		\$30,172.50	to	\$79,987.50	\$54,843.39	
	Outdoor Parking Renovation Cost Subtotal	\$39,367.50	to	\$99,745.93	\$68,100.84	
	Outdoor Parking Renovation Cost Per Space	\$393.68	to	\$997.46	\$681.01	

Structured Parking

Typically, hotels in this market segment do not have structured parking.

Landscaping					
		R	ANGE		AVERAGE
Landscaping Allowance		\$11,739.88	to	\$19,723.01	\$15,801.88
	Landscaping Renovation Cost Subtotal	\$11,739.88	to	\$19,723.01	\$15,801.88

Prototype Hotel: 90 guestrooms, 3 stories, 30 rooms/floor Other assumptions and allowances are listed in each section below.

Common Additives				
	R	ANGE		AVERAGE
New Electronic Key System	\$226.00	to	\$326.29	\$279.96
Elevator Cab Finishes	\$7,043.93	to	\$9,861.50	\$8,429.24
Elevator Modernization				
Hydraulic, per Cab	\$49,548.77	to	\$66,343.26	\$58,616.42
PTAC Unit Direct Replacement, NIC Finishes	\$1,070.00	to	\$1,233.00	\$1,159.20
Laundry Equipment (Direct Equipment Replacement with Access)				
75# Washer	\$23,479.77	to	\$32,049.88	\$27,659.17
125# Dryer	\$35,219.65	to	\$44,376.76	\$39,516.45
Ironer / Folder	\$117,398.85	to	\$133,130.29	\$123,832.30
Guestroom ADA Modifications				
Bathtub Room	\$14,500.00	to	\$23,100.00	\$18,250.11
Roll-in Shower Room	\$16,000.00	to	\$25,808.00	\$20,128.41
Exterior Signage - Monument - New Graphics on Existing Sign	\$5,869.94	to	\$8,628.82	\$7,243.51
Exterior Signage - Highway - New Graphics on Existing Sign	\$23,479.77	to	\$32,049.88	\$27,659.17
Exterior Signage - New Exterior Brand Sign in Existing Location	\$23,479.77	to	\$28,351.82	\$25,686.87
Dumpster Enclosure (CMU Walls, Wood Gate, Bollards, Concrete Pad)	\$12,500.00	to	\$17,820.00	\$16,368.33
Power-operated, Bi-parting Entrance Doors (Inner and Outer at a Vestibule)	\$27,500.00	to	\$35,640.00	\$32,804.82
Replace Guestroom Entry Door and Hardware	\$748.00	to	\$950.00	\$877.36
Replace Guestroom Connecting Doors and Hardware	\$1,630.00	to	\$1,960.95	\$1,814.99
Replace Corridor Service Doors and Hardware	\$776.88	to	\$1,334.81	\$1,100.34



Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Guestroom Softgoods Renovation

Assume guestroom area of approximately 25' x 16' and 8' x 6' kitchen area (548 SF). Ceilings 8' AFF, textured finish. (Studio)

		RANGE		AVERAGE
Demolition	\$535.50	to	\$707.60	\$634.12
FF&E Installation	\$227.50	to	\$380.15	\$302.20
Artwork, Mirrors, and Accessories (Installed Package)	\$187.74	to	\$271.56	\$231.35
Full-height Framed Dressing Mirror	\$94.89	to	\$124.25	\$110.12
Bed Skirt or Box Spring Cover	\$67.63	to	\$74.24	\$70.97
Decorative Pillow	\$32.46	to	\$41.64	\$37.15
Carpet and Pad	\$747.85	to	\$881.01	\$820.05
Rigid Vinyl Base	\$332.22	to	\$631.81	\$511.78
Desk Lamp	\$66.39	to	\$85.03	\$75.92
Floor Lamp	\$99.81	to	\$133.43	\$116.89
End Table Lamp	\$88.25	to	\$113.79	\$101.32
Nightstand or Bracket Lamp (2)	\$154.44	to	\$202.13	\$178.60
Welcome Light (in Existing Location)	\$141.30	to	\$194.60	\$172.37
Desk Chair (including Fabric)	\$187.46	to	\$247.26	\$218.04
Lounge Chair (including Fabric)	\$146.40	to	\$186.01	\$166.60
Dining Chair (including Fabric)	\$531.48	to	\$673.79	\$604.3
Ottoman (including Fabric)	\$209.09	to	\$263.65	\$236.89
Sleeper Sofa (including Fabric)	\$669.19	to	\$837.19	\$752.76
Paint Existing Knockdown-finish Walls	\$380.95	to	\$588.00	\$480.9 [°]
Paint Textured or Drywall Ceiling	\$192.00	to	\$300.00	\$254.2
Paint Entry Doors, Closet Doors, Frames, and Grilles	\$225.00	to	\$322.18	\$273.84
Luxury Vinyl Kitchen Flooring	\$264.00	to	\$342.24	\$314.0
Window Treatments (Sheer, Blackout, Hardware, Installed)	\$650.96	to	\$964.18	\$813.0
Guestroom Softgoods Renovation Cost Per Key	\$6,232.50	to	\$8,565.74	\$7,477.5

Guestroom - Add for a Full Renovation

Guestroom - Add for a Full Renovation	_			
	R	ANGE		AVERAGE
Additional Demolition	\$90.00	to	\$150.00	\$125.30
Casegoods Installation	\$293.80	to	\$584.84	\$442.38
Bedsets (Box Spring, Mattress, and Frame)	\$628.73	to	\$809.68	\$720.86
Headboard	\$344.54	to	\$508.42	\$429.03
Nightstands	\$279.65	to	\$359.49	\$320.16
Dresser	\$964.08	to	\$1,241.66	\$1,106.05
Desk	\$408.91	to	\$526.38	\$469.01
Side Table	\$420.24	to	\$538.90	\$481.08
Coffee Table	\$233.81	to	\$294.24	\$264.60
Dining Table	\$271.92	to	\$351.38	\$312.48
Closet Rack	\$101.00	to	\$186.66	\$134.65
Drapery Valance - Painted Wood	\$336.54	to	\$443.29	\$396.09
Kitchen Cabinetry	\$2,437.50	to	\$4,125.00	\$3,534.60
Kitchen Appliances	\$1,711.32	to	\$2,338.07	\$2,060.59
TV and Mount (HD LCD, including Programming Allowance)	\$1,387.33	to	\$1,629.11	\$1,507.42
Guestroom Full Renovation Additional Cost Per Key	\$9,909.35	to	\$14,087.13	\$12,304.31

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Guest Bathroom Softgoods Renovation

Assume guest bathroom area of 12' x 8'. Ceilings 8' AFF, textured finish.

	RANGE			AVERAGE	
Demolition	\$101.00	to	\$175.00	\$148.30	
Artwork (Installed)	\$49.63	to	\$69.71	\$59.99	
Framed Mirror	\$62.61	to	\$76.84	\$69.51	
Vanity Lighting	\$164.30	to	\$212.17	\$189.25	
Night Light	\$35.00	to	\$75.49	\$58.10	
Paint Ceiling	\$50.88	to	\$72.00	\$63.32	
Vinyl Wallcovering (LY 54")	\$265.17	to	\$385.77	\$328.61	
Shower Curtain and Hooks	\$32.58	to	\$35.92	\$34.26	
Curved Shower Rod	\$54.00	to	\$76.84	\$66.43	
Paint Door and Trim	\$75.00	to	\$107.39	\$91.28	
Regrout Floor Tile	\$35.00	to	\$87.50	\$56.57	
Regrout Wall Tile	\$100.00	to	\$250.00	\$161.62	
Guest Bathroom Softgoods Renovation Cost Per K	ey \$1,025.17	to	\$1,624.63	\$1,327.23	

Guest Bathroom - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$431.44	to	\$493.08	\$454.25
Architectural Lighting	\$182.00	to	\$248.56	\$204.92
Replace Bathroom Door and Hardware	\$547.50	to	\$594.00	\$568.42
Electrical Upgrades (Add One GFI Outlet)	\$54.50	to	\$100.00	\$78.02
Tub-to-Shower Conversion (New Pan, Solid Panel Surround, Valve and Shower Head)	\$2,825.00	to	\$3,522.00	\$3,214.78
Shower Valve and Head, Tub Diverter, Tub Drain	\$250.00	to	\$462.26	\$372.08
Tub Surround (Solid Panel)	\$840.00	to	\$1,101.75	\$966.71
Lavatory	\$176.10	to	\$194.76	\$183.79
Faucet (and Connections)	\$225.00	to	\$297.02	\$259.01
Vanity Top	\$323.23	to	\$483.64	\$407.34
Vanity Base	\$244.50	to	\$375.48	\$312.21
Toilet Accessories	\$268.94	to	\$375.00	\$308.70
Tile Flooring	\$855.00	to	\$1,139.69	\$1,010.00
Toilet and Seat	\$381.55	to	\$462.26	\$439.42
Guest Bathroom Full Renovation Additional Cost Per Key	\$7,604.76	to	\$9,849.49	\$8,779.62

Corridors

Per room with each unit 25' long by half of a 5'-wide corridor; 38 rooms per floor.

	R	ANGE		AVERAGE	
Demolition	\$50.16	to	\$61.87	\$54.24	
Artwork (Installed)	\$3.11	to	\$4.48	\$3.82	
Carpet and Pad	\$157.31	to	\$235.36	\$201.42	
Rigid Vinyl Base	\$56.95	to	\$108.31	\$87.73	
Ceiling-mounted Lighting	\$36.63	to	\$50.44	\$44.73	
Sconces	\$89.58	to	\$123.52	\$108.83	
Vending Area Floor Tile	\$7.40	to	\$9.87	\$8.74	
Ice Machine	\$196.53	to	\$216.86	\$206.66	
Paint Ceiling	\$17.28	to	\$27.00	\$22.88	
Signage Package (Room Numbers, Wayfinding, Complete)	\$96.05	to	\$118.65	\$107.35	
Vinyl Wallcovering (LY 54")	\$146.48	to	\$243.42	\$196.36	
Window Treatments (with Hardware and Installation)	\$9.73	to	\$14.32	\$12.10	
Corridors Renovation Cost Per Key	\$867.22	to	\$1,214.09	\$1,054.88	

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Lobby Softgoods Renovation

Assume a 1,400 SF area. Ceiling 10' AFF.

	R	ANGE		AVERAGE
Demolition	\$1,972.30	to	\$2,416.07	\$2,207.98
Artwork and Artifacts (Installed)	\$655.83	to	\$978.31	\$820.93
Carpet and Pad	\$5,432.62	to	\$6,478.10	\$5,982.81
Millwork (Refinish)	\$528.29	to	\$801.25	\$665.06
Paint Drywall Ceiling	\$672.00	to	\$1,050.00	\$889.87
Paint Doors and Trim	\$150.00	to	\$214.78	\$182.56
Vinyl Wallcovering (LY 54", 40% Openings)	\$1,305.59	to	\$2,071.18	\$1,699.22
Window Treatments (with Hardware and Installation)	\$519.12	to	\$745.33	\$635.38
Seating Groups	\$5,897.78	to	\$7,549.45	\$6,741.20
Lobby Softgoods Renovation Cost Subtotal	\$17,133.54	to	\$22,304.47	\$19,825.00
Lobby Softgoods Renovation Cost Per SF	\$12.24	to	\$15.93	\$14.16

Lobby - Add for a Full Renovation

Lobby - Add for a run Renovation				
	R	ANGE		AVERAGE
Additional Demolition	\$8,217.92	to	\$10,009.43	\$9,036.42
Decorative Lighting	\$2,970.31	to	\$4,230.28	\$3,607.84
Electrical	\$10,852.52	to	\$14,317.10	\$12,712.32
Hard Surface Flooring	\$4,725.00	to	\$6,298.29	\$5,581.58
HVAC	\$4,930.75	to	\$6,903.05	\$5,900.47
Life Safety	\$6,985.23	to	\$9,060.26	\$7,975.49
Architectural Lighting	\$8,628.82	to	\$13,090.49	\$11,732.35
Front Desk (New Pods, in Existing Location)	\$15,500.00	to	\$20,645.10	\$17,575.30
Front Desk Equipment	\$4,108.96	to	\$5,054.02	\$4,544.51
Acoustical Ceiling Tile and Grid (New)	\$3,822.00	to	\$5,325.01	\$4,590.87
Articulated Drywall Ceiling (New)	\$7,098.00	to	\$9,541.35	\$8,662.84
Sound System	\$1,760.98	to	\$2,218.84	\$1,975.82
Drywall Partitions	\$8,100.00	to	\$10,692.00	\$9,618.73
Business Center (Millwork / Finishes / Seating)	\$8,524.25	to	\$12,902.12	\$10,694.28
Lobby Full Renovation Additional Cost Subtotal	\$96,224.74	to	\$130,287.34	\$114,208.83
Lobby Full Renovation Additional Cost Per SF	\$68.73	to	\$93.06	\$81.58

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Marketplace / Sundries Shop

Assume an 85 SF space with display millwork, refrigeration, and coffee offering.

	R	ANGE		AVERAGE
Demolition	\$759.28	to	\$1,134.59	\$964.68
Drywall Partitions	\$1,800.00	to	\$2,376.00	\$2,137.50
Acoustical Tile Ceiling (New)	\$245.70	to	\$342.32	\$295.13
Articulated Drywall Ceiling (New)	\$405.60	to	\$545.22	\$495.02
Millwork - Base Cabinets and Hard Surface Top	\$771.23	to	\$1,328.88	\$1,060.73
Millwork - Display Millwork and Hard Surface Top - 8' Tall	\$2,966.25	to	\$4,235.81	\$3,639.39
Millwork - Island Cabinets and Hard Surface Top	\$813.60	to	\$1,370.41	\$1,101.24
Hard Surface Flooring and Base	\$956.25	to	\$1,274.65	\$1,129.61
Paint	\$120.00	to	\$187.50	\$158.90
Architectural Lighting	\$1,008.53	to	\$1,437.15	\$1,252.73
Electrical	\$1,464.76	to	\$1,916.20	\$1,704.89
Plumbing	\$864.45	to	\$1,195.10	\$1,047.76
Life Safety	\$424.10	to	\$550.09	\$484.23
Nesting Tables	\$750.00	to	\$1,250.00	\$1,000.00
Undercounter Refrigerator / Undercounter Freezer	\$2,000.00	to	\$3,000.00	\$2,466.67
Refrigerated Merchandiser	\$10,000.00	to	\$15,000.00	\$12,666.67
Espresso Machine / Coffee	\$12,000.00	to	\$17,000.00	\$14,500.00
Signage	\$1,500.00	to	\$3,000.00	\$2,266.67
Marketplace / Sundries Renovation Cost Subtotal	\$38,849.74	to	\$57,143.91	\$48,371.80
Marketplace / Sundries Renovation Cost Per SF	\$457.06	to	\$672.28	\$569.08

Public Restrooms Softgoods Renovation

Assume two, 12' x 20' (480 SF total) restrooms. Each with 2 lavs, 3 fixtures. Ceiling 10' AFF.

	R	ANGE		AVERAGE
Demolition	\$295.85	to	\$443.77	\$340.22
Artwork and Artifacts (Installed)	\$287.50	to	\$441.71	\$371.53
Framed Mirrors	\$368.37	to	\$484.17	\$428.17
Paint Drywall Ceiling	\$254.40	to	\$360.00	\$321.35
Paint Doors and Trim	\$145.00	to	\$220.21	\$182.64
Vinyl Wallcovering (LY 54")	\$1,631.71	to	\$2,606.91	\$2,133.31
Decorative Vanity Lighting	\$965.12	to	\$1,403.25	\$1,205.78
Public Restrooms Softgoods Renovation Cost Subtotal	\$3,947.94	to	\$5,960.02	\$4,983.01
Public Restrooms Softgoods Renovation Cost Per SF	\$8.22	to	\$12.42	\$10.38

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Public Restrooms - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$4,508.12	to	\$5,916.90	\$5,184.33
Toilet Partitions	\$3,164.00	to	\$4,139.19	\$3,480.64
Toilet Accessories	\$1,056.59	to	\$1,410.00	\$1,243.55
Replace Doors	\$1,642.50	to	\$1,782.00	\$1,708.09
Toilets / Urinals	\$2,895.00	to	\$5,400.00	\$4,196.99
Architectural Lighting	\$4,733.52	to	\$5,916.90	\$5,135.87
Tile Flooring	\$5,400.00	to	\$7,198.05	\$6,378.95
Tile Walls	\$4,050.00	to	\$5,398.54	\$4,784.22
Motion-sensing Flush Valves	\$3,660.00	to	\$4,776.00	\$4,035.10
Motion-sensing Faucets	\$2,400.00	to	\$3,781.60	\$3,165.17
Vanity Top, Sinks	\$2,582.77	to	\$3,204.99	\$2,940.11
Public Restrooms Full Renovation Additional Cost Subtotal	\$36,092.50	to	\$48,924.17	\$42,253.02
Public Restrooms Full Renovation Additional Cost Per SF	\$75.19	to	\$101.93	\$88.03

Restaurant Softgoods Renovation

Assume a 76-seat restaurant area of approximately 35' x 40' (1,400 SF). Ceiling 10' AFF.

	R	ANGE		AVERAGE
Demolition	\$1,643.58	to	\$2,416.07	\$2,028.18
Artwork (Installed)	\$3,364.82	to	\$4,947.48	\$4,196.35
Carpet and Pad (80% of Floor Area)	\$4,918.34	to	\$5,803.39	\$5,389.92
Millwork Buffet, Host Station (Refinish)	\$1,467.49	to	\$2,773.55	\$2,139.59
Millwork Running Trim (Refinish - Hardwood Crown, Chair, and Base)	\$160.60	to	\$259.20	\$220.78
Reupholster Banquettes	\$3,862.50	to	\$5,725.72	\$4,823.47
Acoustical Tile Ceiling (New)	\$7,644.00	to	\$10,650.02	\$9,181.74
Paint Doors and Trim	\$131.08	to	\$178.00	\$159.22
Vinyl Wallcovering (LY 54", 40% Openings)	\$1,285.56	to	\$2,048.93	\$1,678.19
Window Treatments (with Hardware and Installation)	\$1,188.62	to	\$1,727.91	\$1,466.23
Dining Chairs (No Arms)	\$16,908.48	to	\$22,192.38	\$19,609.14
Restaurant Softgoods Renovation Cost Subtotal	\$42,575.08	to	\$58,722.65	\$50,892.83
Restaurant Softgoods Renovation Cost Per SF	\$30.41	to	\$41.94	\$36.35
Restaurant Softgoods Renovation Cost Per Seat	\$560.20	to	\$772.67	\$669.64

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Restaurant - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$4,930.75	to	\$6,903.05	\$5,900.47
Banquettes	\$2,261.80	to	\$3,790.96	\$3,018.95
Buffet Equipment	\$9,605.00	to	\$17,797.50	\$13,955.50
Decorative Lighting	\$5,667.00	to	\$8,244.54	\$6,991.38
Architectural Lighting	\$9,450.61	to	\$15,963.31	\$12,610.40
Electrical	\$13,806.10	to	\$17,257.63	\$14,979.62
Hard Surface Flooring (20% of Floor Area)	\$3,150.00	to	\$4,198.86	\$3,721.06
HVAC	\$3,451.53	to	\$6,903.05	\$5,229.06
Life Safety	\$6,985.23	to	\$9,060.26	\$7,975.49
Millwork Buffet, Host Station (New, in Existing Location)	\$14,062.50	to	\$19,260.75	\$16,063.89
Sound System	\$1,760.98	to	\$2,218.84	\$1,975.82
Tables	\$7,730.15	to	\$10,031.73	\$8,908.31
Drywall Partitions	\$8,100.00	to	\$10,692.00	\$9,618.73
TV and Mount (55", including Programming Allowance)	\$1,702.60	to	\$1,989.30	\$1,838.05
Restaurant Full Renovation Additional Cost Subtotal	\$92,664.25	to	\$134,311.78	\$112,786.74
Restaurant Full Renovation Additional Cost Per SF	\$66.19	to	\$95.94	\$80.56
Restaurant Full Renovation Additional Cost Per Seat	\$1,219.27	to	\$1,767.26	\$1,484.04

Bar / Lounge

Typically, hotels in this market segment do not have bar / lounge areas.

Kitchen

Assume a kitchen	area of	approximately 80 SF.
------------------	---------	----------------------

		R	ANGE		AVERAGE
Selective Demolition		\$791.00	to	\$972.93	\$888.86
Vinyl-coated Tile Ceiling (2' x 4' Tiles and New Grid)		\$380.00	to	\$712.80	\$507.22
Fluorescent Lighting (2' x 4')		\$295.85	to	\$493.08	\$357.97
Paint Door Frames and Trim		\$145.00	to	\$220.21	\$182.64
Paint Walls		\$30.53	to	\$43.20	\$37.99
Quarry Tile Flooring		\$932.80	to	\$1,224.21	\$1,107.71
Replace Doors		\$1,526.18	to	\$3,446.50	\$2,648.86
Kydex-paneled Walls		\$316.80	to	\$413.25	\$354.52
Kita	chen Renovation Cost Subtotal	\$4,418.16	to	\$7,526.18	\$6,085.77
к	itchen Renovation Cost Per SF	\$55.23	to	\$94.08	\$76.07

Kitchen Equipment					
		RANGE			AVERAGE
Select Kitchen Equipment		\$2,582.77	to	\$3,406.16	\$2,978.87
	Kitchen Equipment Cost Subtotal	\$2,582.77	to	\$3,406.16	\$2,978.87
	Kitchen Equipment Cost Per SF	\$32.28	to	\$42.58	\$37.24

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Ballroom and Prefunction

Typically, hotels in this market segment do not have ballrooms.

Meeting Rooms Softgoods Renovation

Assume a meeting room area of approximately 24' x 23' (552 SF). Ceiling 12' AFF.

	RANGE			AVERAGE
Demolition	\$648.04	to	\$952.62	\$799.68
Carpet and Pad	\$2,061.11	to	\$2,462.65	\$2,276.18
Paint Articulated Drywall Ceiling	\$292.56	to	\$441.60	\$373.28
Paint Doors and Trim	\$300.00	to	\$355.01	\$321.40
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$314.51	to	\$507.60	\$432.36
Protect / Remove / Reinstall All Light Fixtures	\$452.00	to	\$711.90	\$588.73
Vinyl Wallcovering (LY 54")	\$1,597.72	to	\$2,552.60	\$2,088.87
Window Treatments (with Hardware and Installation)	\$2,517.32	to	\$3,674.64	\$3,113.56
Meeting Rooms Softgoods Renovation Cost Subtotal	\$8,183.26	to	\$11,658.62	\$9,994.06
Meeting Rooms Softgoods Renovation Cost Per SF	\$14.82	to	\$21.12	\$18.11

Meeting Rooms - Add for a Full Renovation					
	RANGE			AVERAGE	
Additional Demolition	\$3,240.21	to	\$3,946.57	\$3,562.93	
Banquet Chairs	\$7,042.02	to	\$9,633.97	\$8,374.39	
Artwork, Accessories, and Mirrors (Installed)	\$1,133.58	to	\$1,656.83	\$1,405.33	
Acoustical Tile Ceiling (New)	\$2,250.53	to	\$3,229.20	\$2,658.61	
Decorative Lighting	\$1,084.87	to	\$1,652.25	\$1,384.51	
Electrical	\$5,443.55	to	\$6,804.44	\$5,906.25	
HVAC	\$1,360.89	to	\$2,721.77	\$2,061.74	
Life Safety	\$2,754.18	to	\$3,572.33	\$3,144.62	
Architectural Lighting	\$4,082.66	to	\$5,443.55	\$4,810.74	
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$1,655.32	to	\$2,979.58	\$2,468.59	
Millwork Serving Stations	\$3,164.00	to	\$5,423.83	\$4,725.32	
Meeting Rooms Full Renovation Additional Cost Subtotal	\$33,211.81	to	\$47,064.33	\$40,503.04	
Meeting Rooms Full Renovation Additional Cost Per SF	\$60.17	to	\$85.26	\$73.38	

Board Room

Typically, hotels in this market segment do not have board rooms.

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Exercise Facility Softgoods Renovation

Assume a two-bay facility of approximately 26' x 28' (728 SF). Ceiling 10' AFF.

	R	ANGE		AVERAGE
Demolition	\$854.66	to	\$1,256.36	\$1,054.65
Artwork (Installed)	\$223.06	to	\$333.25	\$281.94
Clock	\$42.19	to	\$64.87	\$56.09
Hamper	\$99.81	to	\$133.43	\$116.89
Towel Caddy	\$327.54	to	\$416.98	\$373.15
Sport Flooring	\$7,403.76	to	\$12,993.41	\$10,640.17
Mirrors	\$1,952.64	to	\$2,965.90	\$2,502.91
Paint Doors and Trim	\$600.00	to	\$710.03	\$638.01
Remove and Reinstall Exercise Equipment	\$586.99	to	\$1,849.03	\$1,250.30
Paint Walls	\$686.88	to	\$972.00	\$854.75
Window Treatments (with Hardware and Installation)	\$356.38	to	\$516.34	\$438.88
Exercise Facility Softgoods Renovation Cost Subtotal	\$13,133.91	to	\$22,211.60	\$18,207.74
Exercise Facility Softgoods Renovation Cost Per SF	\$18.04	to	\$30.51	\$25.01

Exercise Facility - Add for a Full Renovation					
	RANG			AVERAGE	
Additional Demolition	\$4,273.32	to	\$5,204.90	\$4,698.94	
Acoustical Tile Ceiling (New)	\$3,974.88	to	\$5,347.16	\$4,736.33	
Exercise Equipment (Installed)	\$46,985.51	to	\$60,263.24	\$53,759.82	
Electrical	\$7,179.17	to	\$8,973.97	\$7,789.40	
HVAC	\$1,794.79	to	\$3,589.59	\$2,719.11	
Life Safety	\$3,632.32	to	\$4,711.33	\$4,147.26	
Architectural Lighting	\$5,384.38	to	\$7,179.17	\$6,344.60	
TVs and Mounts (42", including Programming Allowance)	\$893.53	to	\$1,038.01	\$961.97	
Water Fountain	\$939.19	to	\$1,331.30	\$1,132.66	
Sound System	\$880.49	to	\$1,109.42	\$987.91	
Exercise Facility Full Renovation Additional Cost Subtotal	\$75,937.59	to	\$98,748.09	\$87,278.01	
Exercise Facility Full Renovation Additional Cost Per SF	\$104.31	to	\$135.64	\$119.89	

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Outdoor Pool

Assume a 15' x 30' (450 SF) pool and a 12'-wide deck, approximately 1,656 SF surface.

		RANGE			AVERAGE	
ADA Lift		\$3,955.00	to	\$8,305.50	\$6,068.10	
Pool Furniture		\$8,248.00	to	\$12,031.78	\$10,197.26	
Pool Equipment		\$5,869.94	to	\$13,559.57	\$9,873.24	
Resurface Pool Bottom		\$4,050.00	to	\$9,900.00	\$6,348.97	
Resurface Pool Deck (Kool Deck)		\$12,163.32	to	\$15,732.00	\$13,747.24	
Signage (Life Safety, Pool Rules)		\$1,130.00	to	\$2,966.25	\$2,118.75	
	Outdoor Pool Renovation Cost Subtotal	\$35,416.26	to	\$62,495.09	\$48,353.55	
	Outdoor Pool Renovation Cost Per SF	\$16.82	to	\$29.67	\$22.96	

Indoor Pool

Assume a 15' x 30' (450 SF) pool and a 12'-wide deck, approximately 1,656 SF surface.

	RANGE			AVERAGE	
ADA Lift	\$3,955.00	to	\$8,305.50	\$6,068.10	
Architectural Lighting	\$18,457.04	to	\$23,730.47	\$21,304.69	
Acoustical Tile Ceiling with Aluminum Grid (New)	\$7,785.96	to	\$10,473.97	\$9,277.49	
Paint Doors and Trim	\$300.00	to	\$355.01	\$319.00	
Pool Deck Tile	\$14,895.57	to	\$19,249.65	\$16,791.98	
Pool Equipment	\$5,869.94	to	\$13,559.57	\$9,873.24	
Pool Furniture	\$4,640.15	to	\$6,767.16	\$5,735.75	
Pool Pak HVAC	\$53,175.54	to	\$64,294.06	\$58,460.87	
Replace Doors (Storefront)	\$1,760.98	to	\$2,588.64	\$2,173.05	
Resurface Pool Bottom	\$4,050.00	to	\$9,900.00	\$6,348.97	
Paint Walls (Assume Two Walls are Storefront, Two are Drywall)	\$408.10	to	\$577.50	\$507.84	
Signage (Life Safety, Pool Rules)	\$1,130.00	to	\$2,966.25	\$2,118.75	
Indoor Pool Renovation Cost Subtotal	\$116,428.28	to	\$162,767.79	\$138,979.73	
Indoor Pool Renovation Cost Per SF	\$55.28	to	\$77.29	\$65.99	

Indoor Pool Renovation Cost Per SF

Outdoor Amenities					
		R	ANGE		AVERAGE
Stamped Concrete at Arrivals		\$7,500.00	to	\$13,125.00	\$9,749.61
Outdoor Furniture		\$8,749.85	to	\$12,764.19	\$10,817.89
Fire Pit		\$9,605.00	to	\$13,500.00	\$11,416.57
Permanent Grill		\$5,869.94	to	\$9,861.50	\$7,900.94
Outdoor Lighting		\$7,630.92	to	\$11,710.53	\$9,679.53
Patio Landscaping		\$5,282.95	to	\$9,245.16	\$7,308.08
	Outdoor Amenities Renovation Cost Subtotal	\$44,638.67	to	\$70,206.39	\$56,872.62

Prototype Hotel: 150 guestrooms, 4 stories, 38 rooms/floor Other assumptions and allowances are listed in each section below.

Outdoor Parking

Assume 175 spaces, 9' x 18', and 25'-wide aisles.

		RANGE			AVERAGE	
Clean and Seal Asphalt		\$13,466.25	to	\$27,927.26	\$19,122.58	
Stripe Spaces		\$2,625.00	to	\$6,650.00	\$4,077.95	
Pavement Resurfacing		\$52,801.88	to	\$139,978.13	\$95,975.93	
	Outdoor Parking Renovation Cost Subtotal	\$68,893.13	to	\$174,555.38	\$119,176.46	
	Outdoor Parking Renovation Cost Per Space	\$393.68	to	\$997.46	\$681.01	

Structured Parking

Typically, hotels in this market segment do not have structured parking.

Landscaping					
		RANGE			AVERAGE
Landscaping Allowance		\$23,479.77	to	\$32,049.88	\$27,659.17
	Landscaping Renovation Cost Subtotal	\$23,479.77	to	\$32,049.88	\$27,659.17

Common Additives				
	R		AVERAGE	
New RFID Key System	\$339.00	to	\$474.60	\$416.97
Elevator Cab Finishes	\$9,978.90	to	\$15,162.06	\$12,576.94
Elevator Modernization				
Hydraulic, per Cab	\$66,065.03	to	\$88,457.68	\$78,155.23
PTAC Unit Direct Replacement, NIC Finishes	\$1,070.00	to	\$1,233.00	\$1,159.20
Laundry Equipment (Direct Equipment Replacement with Access)				
75# Washer	\$23,479.77	to	\$32,049.88	\$27,659.17
125# Dryer	\$35,219.65	to	\$44,376.76	\$39,516.45
Ironer / Folder	\$117,398.85	to	\$133,130.29	\$123,832.30
Porte Cochere - Re-image: Demolish and Replace	\$11,739.88	to	\$49,307.52	\$31,580.29
Guestroom ADA Modifications				
Bathtub Room	\$17,370.57	to	\$23,100.00	\$18,943.51
Roll-in Shower Room	\$17,857.07	to	\$25,808.00	\$21,538.81
Exterior Signage - Monument - New Graphics on Existing Sign	\$11,739.88	to	\$17,257.63	\$14,487.02
Exterior Signage - Highway - New Graphics on Existing Sign	\$29,349.71	to	\$38,213.32	\$33,587.81
Exterior Signage - New Exterior Brand Sign in Existing Location	\$35,219.65	to	\$44,376.76	\$39,516.45
Dumpster Enclosure (CMU Walls, Wood Gate, Bollards, Concrete Pad)	\$12,500.00	to	\$17,820.00	\$16,368.33
Power-operated, Bi-parting Entrance Doors (Inner and Outer at a Vestibule)	\$27,500.00	to	\$35,640.00	\$32,804.82
Fireplace - Natural Gas with Stone Hearth and Surrounding Wall (Public Area)	\$11,865.00	to	\$19,500.00	\$14,359.95
Replace Guestroom Entry Door and Hardware	\$748.00	to	\$950.00	\$877.36
Replace Guestroom Connecting Doors and Hardware	\$1,630.00	to	\$2,240.00	\$1,878.79
Replace Corridor Service Doors and Hardware	\$776.88	to	\$1,334.81	\$1,100.34
Replace Guestroom Closet Door with Pair of Swing Doors and Hardware	\$790.00	to	\$891.00	\$831.86
Replace Guestroom Bath Door with Barn Door and Hardware	\$1,105.00	to	\$1,310.00	\$1,208.37
Incremental Add for LVT in Guestroom Instead of Carpet	\$1,331.15	to	\$2,091.35	\$1,797.22



MIDSCALE

H.A.

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Guestroom Softgoods Renovation

Assume guestroom area of approximately 13' x 21'-6" and 6' x 7' entry / closet area (370 SF). Ceilings 8' AFF, painted drywall.

	R	ANGE		AVERAGE
Demolition	\$357.00	to	\$471.73	\$422.75
FF&E Installation	\$175.00	to	\$292.42	\$227.54
Artwork, Mirrors, and Accessories (Installed Package)	\$177.44	to	\$268.44	\$223.44
Full-height Framed Dressing Mirror	\$104.92	to	\$139.03	\$122.06
Bed Skirt or Box Spring Cover	\$127.31	to	\$140.04	\$133.67
Decorative Pillow	\$36.35	to	\$47.25	\$41.80
Carpet and Pad	\$637.54	to	\$748.76	\$697.87
Carpet Base	\$113.88	to	\$155.87	\$137.24
Desk Lamp	\$76.79	to	\$99.81	\$88.28
Floor Lamp	\$152.44	to	\$190.55	\$171.32
End Table Lamp	\$99.81	to	\$135.96	\$117.73
Nightstand or Bracket Lamp (2)	\$190.04	to	\$225.57	\$208.06
Welcome Light (in Existing Location)	\$143.87	to	\$199.18	\$175.80
Desk Chair (including Fabric)	\$280.16	to	\$366.68	\$323.42
Lounge Chair (including Fabric)	\$180.47	to	\$234.62	\$207.55
Ottoman (including Fabric)	\$106.61	to	\$135.96	\$121.20
Sleeper Sofa (including Fabric - Assumes King Rooms Only)	\$396.93	to	\$495.05	\$445.99
Paint Textured or Drywall Ceiling	\$154.32	to	\$241.13	\$204.35
Paint Entry Doors, Closet Doors, Frames, and Grilles	\$150.00	to	\$214.78	\$182.56
Vinyl Wallcovering (LY 54")	\$751.12	to	\$1,248.01	\$1,006.64
Window Treatments (Sheer, Blackout, Hardware, Installed)	\$473.80	to	\$715.85	\$595.00
Guestroom Softgoods Renovation Cost Per Key	\$4,885.78	to	\$6,766.68	\$5,854.28

Guestroom - Add for a Full Renovation

	RANGE			AVERAGE
Casegoods Installation	\$308.49	to	\$416.00	\$365.47
Bedsets (Box Spring, Mattress, and Frame)	\$628.73	to	\$821.13	\$724.68
Headboard	\$514.49	to	\$772.50	\$643.24
Nightstands	\$393.98	to	\$505.22	\$450.11
Dresser	\$506.76	to	\$653.02	\$579.89
Desk	\$459.38	to	\$604.61	\$531.82
Coffee Table	\$198.28	to	\$261.11	\$229.69
Closet Rack	\$101.00	to	\$186.66	\$134.65
Refrigerator Cabinet / Welcome Center	\$515.00	to	\$664.35	\$589.50
Mini Refrigerator	\$247.20	to	\$267.80	\$257.50
Drapery Valance - Painted Wood	\$175.00	to	\$230.51	\$205.97
TV and Mount (HD LCD, including Programming Allowance)	\$693.66	to	\$816.28	\$754.29
Guestroom Full Renovation Additional Cost Per Key	\$4,741.95	to	\$6,199.18	\$5,466.80

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Guest Bathroom Softgoods Renovation

Assume guest bathroom area of 6' x 8'. Ceilings 8' AFF, painted drywall.

	RANGE			AVERAGE
Demolition	\$101.00	to	\$175.00	\$148.30
Artwork (Installed)	\$68.67	to	\$99.72	\$84.27
Lighted Mirror	\$426.79	to	\$591.40	\$503.77
Night Light	\$35.00	to	\$75.49	\$58.10
Paint Ceiling	\$25.44	to	\$36.00	\$31.66
Vinyl Wallcovering (LY 54")	\$185.15	to	\$261.49	\$225.22
Shower Curtain and Hooks	\$36.64	to	\$40.51	\$38.58
Curved Shower Rod	\$54.00	to	\$77.84	\$70.82
Paint Door and Trim	\$75.00	to	\$107.39	\$91.28
Regrout Floor Tile	\$104.00	to	\$260.00	\$168.08
Regrout Wall Tile	\$100.00	to	\$250.00	\$161.62
Guest Bathroom Softgoods Renovation Cost Per Key	\$1,211.70	to	\$1,974.84	\$1,581.69

Guest Bathroom - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$431.44	to	\$493.08	\$454.25
Architectural Lighting	\$182.00	to	\$248.56	\$204.92
Replace Bathroom Door and Hardware	\$547.50	to	\$594.00	\$568.42
Electrical Upgrades (Add One GFI Outlet)	\$54.50	to	\$100.00	\$78.02
Tub-to-Shower Conversion (New Pan, Solid Panel Surround, Valve and Shower Head)	\$2,825.00	to	\$3,522.00	\$3,214.78
Shower Valve and Head, Tub Diverter, Tub Drain	\$250.00	to	\$458.58	\$370.64
Tub Surround (Solid Panel)	\$840.00	to	\$1,180.00	\$1,017.48
Lavatory	\$176.10	to	\$194.76	\$183.79
Faucet (and Connections)	\$225.00	to	\$297.02	\$259.01
Vanity Top	\$323.23	to	\$495.07	\$411.15
Vanity Base	\$244.50	to	\$381.75	\$314.30
Toilet Accessories	\$268.94	to	\$375.00	\$308.70
Tile Flooring	\$415.85	to	\$503.64	\$465.03
Toilet and Seat	\$381.55	to	\$462.26	\$439.42
Guest Bathroom Full Renovation Additional Cost Per Key	\$7,165.60	to	\$9,305.72	\$8,289.90

Corridors

Per room with each unit 13' long and half of a 6'-wide corridor; 27 rooms per floor.

	R	ANGE		AVERAGE
Demolition	\$39.60	to	\$48.84	\$42.82
Artwork (Installed)	\$9.13	to	\$13.76	\$11.45
Carpet and Pad	\$182.69	to	\$261.55	\$225.51
Carpet Base	\$23.66	to	\$31.68	\$28.12
Ceiling-mounted Lighting	\$36.09	to	\$50.03	\$44.18
Sconces	\$82.86	to	\$117.16	\$102.13
Vending Area Floor Tile	\$16.67	to	\$22.22	\$19.69
Ice Machine	\$277.58	to	\$307.65	\$292.66
Paint Ceiling	\$21.60	to	\$33.75	\$28.60
Signage Package (Room Numbers, Wayfinding, Complete)	\$96.05	to	\$118.65	\$107.35
Vinyl Wallcovering (LY 54")	\$147.39	to	\$242.37	\$196.24
Window Treatments (with Hardware and Installation)	\$14.50	to	\$21.55	\$18.03
Corridors Renovation Cost Per Key	\$947.82	to	\$1,269.20	\$1,116.80

Hadal .

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Lobby Softgoods Renovation

Assume a 2,500 SF area. Ceiling 10' AFF.

	R	ANGE		AVERAGE		
Demolition	\$3,521.97	to	\$4,314.41	\$3,942.82		
Artwork and Artifacts (Installed)	\$864.86	to	\$1,321.64	\$1,090.95		
Carpet and Pad	\$10,348.89	to	\$12,453.34	\$11,394.72		
Millwork (Refinish)	\$586.99	to	\$862.88	\$724.35		
Millwork Screen Walls (Refinish)	\$410.90	to	\$677.98	\$546.49		
Paint Drywall Ceiling	\$1,200.00	to	\$1,875.00	\$1,589.05		
Paint Doors and Trim	\$375.00	to	\$536.96	\$456.39		
Vinyl Wallcovering (LY 54", 40% Openings)	\$1,464.30	to	\$2,246.97	\$1,866.45		
Window Treatments (with Hardware and Installation)	\$634.48	to	\$952.75	\$793.44		
Seating Groups	\$13,045.44	to	\$17,039.49	\$15,041.44		
Lobby Softgoods Renovation Cost Subtotal	\$32,452.83	to	\$42,281.41	\$37,446.09		
Lobby Softgoods Renovation Cost Per SF	\$12.98	to	\$16.91	\$14.98		

Lobby - Add for a Full Renovation

	_			
	R	ANGE		AVERAGE
Additional Demolition	\$14,674.86	to	\$17,873.97	\$16,136.47
Decorative Lighting	\$5,200.26	to	\$7,649.62	\$6,419.66
Electrical	\$19,379.50	to	\$25,566.25	\$22,700.57
Hard Surface Flooring	\$8,437.50	to	\$11,246.95	\$9,967.12
HVAC	\$8,804.91	to	\$12,326.88	\$10,536.55
Life Safety	\$12,473.63	to	\$16,179.03	\$14,241.95
Architectural Lighting	\$15,408.60	to	\$23,375.88	\$20,950.63
Front Desk (New Pods, in Existing Location)	\$15,500.00	to	\$25,000.00	\$18,868.90
Front Desk Equipment	\$4,108.96	to	\$5,054.02	\$4,544.51
Millwork Screen Walls (New)	\$6,163.44	to	\$9,676.60	\$7,934.40
Acoustic Ceiling and Grid (New)	\$6,825.00	to	\$9,508.95	\$8,197.98
Articulated Drywall Ceiling (New)	\$12,675.00	to	\$17,038.13	\$15,469.36
Sound System	\$1,760.98	to	\$2,218.84	\$1,975.82
Drywall Partitions	\$8,100.00	to	\$10,692.00	\$9,618.73
Business Center (Millwork / Finishes / Seating)	\$10,283.49	to	\$15,647.82	\$12,928.26
Lobby Full Renovation Additional Cost Subtotal	\$149,796.13	to	\$209,054.94	\$180,490.90
Lobby Full Renovation Additional Cost Per SF	\$59.92	to	\$83.62	\$72.20

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Marketplace / Sundries Shop

Assume an 85 SF space with display millwork, refrigeration, and coffee offering.

Illin_ti

	R	RANGE		
Demolition	\$759.28	to	\$1,134.59	\$964.68
Drywall Partitions	\$1,800.00	to	\$2,376.00	\$2,137.50
Acoustical Tile Ceiling (New)	\$245.70	to	\$342.32	\$295.13
Articulated Drywall Ceiling (New)	\$405.60	to	\$545.22	\$495.02
Millwork - Base Cabinets and Hard Surface Top	\$771.23	to	\$1,328.88	\$1,060.73
Millwork - Display Millwork and Hard Surface Top - 8' Tall	\$2,966.25	to	\$4,235.81	\$3,639.39
Millwork - Island Cabinets and Hard Surface Top	\$813.60	to	\$1,370.41	\$1,101.24
Hard Surface Flooring and Base	\$956.25	to	\$1,274.65	\$1,129.61
Paint	\$120.00	to	\$187.50	\$158.90
Architectural Lighting	\$1,008.53	to	\$1,437.15	\$1,252.73
Electrical	\$1,464.76	to	\$1,916.20	\$1,704.89
Plumbing	\$864.45	to	\$1,195.10	\$1,047.76
Life Safety	\$424.10	to	\$550.09	\$484.23
Nesting Tables	\$750.00	to	\$1,250.00	\$1,000.00
Undercounter Refrigerator / Undercounter Freezer	\$2,000.00	to	\$3,000.00	\$2,466.67
Refrigerated Merchandiser	\$10,000.00	to	\$15,000.00	\$12,666.67
Espresso Machine / Coffee	\$12,000.00	to	\$17,000.00	\$14,500.00
Signage	\$1,500.00	to	\$3,000.00	\$2,266.67
Marketplace / Sundries Renovation Cost Subtotal	\$38,849.74	to	\$57,143.91	\$48,371.80
Marketplace / Sundries Renovation Cost Per SF	\$457.06	to	\$672.28	\$569.08

Public Restrooms Softgoods Renovation

Assume two, 12' x 20' (480 SF total) restrooms. Each with 2 lavs, 3 fixtures. Ceiling 10' AFF.

	R	ANGE		AVERAGE
Demolition	\$295.85	to	\$443.77	\$340.22
Artwork and Artifacts (Installed)	\$542.94	to	\$844.86	\$698.87
Framed Mirrors	\$1,200.04	to	\$1,610.84	\$1,406.56
Paint Drywall Ceiling	\$254.40	to	\$360.00	\$321.35
Paint Doors and Trim	\$145.00	to	\$220.21	\$182.64
Vinyl Wallcovering (LY 54")	\$1,915.73	to	\$2,921.48	\$2,432.11
Decorative Vanity Lighting	\$1,022.80	to	\$1,550.68	\$1,304.37
Public Restrooms Softgoods Renovation Cost Subtotal	\$5,376.75	to	\$7,951.84	\$6,686.12
Public Restrooms Softgoods Renovation Cost Per SF	\$11.20	to	\$16.57	\$13.93

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Public Restrooms - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$3,099.33	to	\$4,437.68	\$3,761.46
Toilet Partitions	\$4,746.00	to	\$6,208.79	\$5,220.96
Toilet Accessories	\$1,242.55	to	\$2,250.00	\$1,721.09
Replace Doors	\$1,642.50	to	\$1,782.00	\$1,708.09
Toilets / Urinals	\$2,895.00	to	\$5,400.00	\$4,196.99
Architectural Lighting	\$4,733.52	to	\$5,916.90	\$5,135.87
Tile Flooring	\$5,400.00	to	\$7,198.05	\$6,378.95
Tile Walls	\$4,050.00	to	\$5,398.54	\$4,784.22
Motion-sensing Flush Valves	\$3,660.00	to	\$4,776.00	\$4,035.10
Motion-sensing Faucets	\$2,400.00	to	\$3,781.60	\$3,165.17
Vanity Top, Sinks	\$2,582.77	to	\$3,204.99	\$2,940.11
Public Restrooms Full Renovation Additional Cost Subtotal	\$36,451.67	to	\$50,354.54	\$43,048.01
Public Restrooms Full Renovation Additional Cost Per SF	\$75.94	to	\$104.91	\$89.68

Restaurant Softgoods Renovation

Assume a 68-seat restaurant area of approximately 36' x 36' (1,296 SF). Ceiling 10' AFF.

	R	ANGE		AVERAGE
Demolition	\$1,521.49	to	\$2,236.59	\$1,877.52
Artwork (Installed)	\$3,710.90	to	\$5,603.85	\$4,675.05
Carpet and Pad (80% of Floor Area)	\$5,326.02	to	\$6,230.95	\$5,803.81
Millwork Buffet, Host Station (Refinish)	\$2,347.98	to	\$4,437.68	\$3,423.35
Millwork Screen Walls (Refinish)	\$880.49	to	\$1,294.32	\$1,086.53
Millwork Running Trim (Refinish - Hardwood Crown, Chair, and Base)	\$160.60	to	\$259.20	\$220.78
Reupholster Banquettes	\$4,317.75	to	\$6,489.25	\$5,403.50
Paint Drywall Ceiling	\$622.08	to	\$972.00	\$823.76
Paint Doors and Trim	\$290.00	to	\$440.42	\$365.28
Vinyl Wallcovering (LY 54", 40% Openings)	\$1,382.06	to	\$2,131.20	\$1,766.89
Window Treatments (with Hardware and Installation)	\$2,333.98	to	\$3,509.21	\$2,921.77
Dining Chairs (No Arms)	\$16,620.56	to	\$21,702.88	\$19,138.83
Restaurant Softgoods Renovation Cost Subtotal	\$39,513.91	to	\$55,307.55	\$47,507.06
Restaurant Softgoods Renovation Cost Per SF	\$30.49	to	\$42.68	\$36.66
Restaurant Softgoods Renovation Cost Per Seat	\$581.09	to	\$813.35	\$698.63

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Restaurant - Add for a Full Renovation

I Shade

	R	ANGE		AVERAGE
Additional Demolition	\$4,564.47	to	\$6,390.25	\$5,462.15
Banquettes	\$2,441.79	to	\$4,230.47	\$3,305.11
Buffet Equipment	\$5,869.94	to	\$13,559.57	\$9,873.24
Decorative Lighting	\$7,346.24	to	\$11,161.64	\$9,189.25
Architectural Lighting	\$8,748.56	to	\$14,777.46	\$12,312.65
Electrical	\$12,780.51	to	\$15,975.63	\$13,866.85
Hard Surface Flooring (20% of Floor Area)	\$2,916.00	to	\$3,886.95	\$3,444.63
HVAC	\$3,195.13	to	\$6,390.25	\$4,840.62
Life Safety	\$6,466.33	to	\$8,387.21	\$7,383.03
Millwork Buffet, Host Station (New, in Existing Location)	\$22,500.00	to	\$30,817.20	\$25,702.23
Millwork Screen Walls (New)	\$4,108.96	to	\$6,533.25	\$5,333.43
Millwork Running Trim (Hardwood Crown, Chair, and Base)	\$845.27	to	\$1,521.49	\$1,260.56
Articulated Drywall Ceiling (New)	\$13,141.44	to	\$17,665.13	\$16,038.63
Sound System	\$1,760.98	to	\$2,218.84	\$1,975.82
Tables	\$7,286.22	to	\$9,307.08	\$8,299.74
Communal Dining Tables, Chef's Table (6 Seats)	\$2,694.45	to	\$4,219.65	\$3,467.22
Communal Table Stools	\$2,014.68	to	\$3,028.20	\$2,521.44
Drywall Partitions	\$7,776.00	to	\$10,264.32	\$9,233.98
TV and Mount (55", including Programming Allowance)	\$3,405.20	to	\$3,986.56	\$3,678.75
Restaurant Full Renovation Additional Cost Subtotal	\$119,862.17	to	\$174,321.14	\$147,189.32
Restaurant Full Renovation Additional Cost Per SF	\$92.49	to	\$134.51	\$113.57
Restaurant Full Renovation Additional Cost Per Seat	\$1,762.68	to	\$2,563.55	\$2,164.55

Bar / Lounge Softgoods Renovation

Assume a 54-seat bar / lounge area of approximately 24' x 30' (720 SF).

	R	ANGE		AVERAGE
Demolition	\$845.27	to	\$1,242.55	\$1,043.07
Artwork, Accessories, and Mirrors (Installed)	\$5,382.33	to	\$8,081.51	\$6,734.40
Bar / Back Bar (Refinish)	\$733.74	to	\$1,386.77	\$1,069.80
Carpet and Pad (60%)	\$2,069.65	to	\$2,431.63	\$2,261.20
Millwork Running Trim (Refinish)	\$107.77	to	\$166.41	\$137.25
Paint Drywall Ceiling	\$345.60	to	\$540.00	\$457.65
Paint Doors and Trim	\$145.00	to	\$220.21	\$182.64
Vinyl Wallcovering (LY 54")	\$1,796.00	to	\$2,738.89	\$2,280.11
Reupholster Banquettes	\$3,108.78	to	\$4,672.26	\$3,890.52
Dining Chairs (No Arms)	\$10,265.64	to	\$13,404.72	\$11,821.04
Bar Stools	\$4,035.96	to	\$6,096.36	\$5,066.16
Seating Group	\$8,042.76	to	\$10,506.81	\$9,275.64
Bar / Lounge Softgoods Renovation Cost Subtotal	\$36,878.50	to	\$51,488.13	\$44,219.47
Bar / Lounge Softgoods Renovation Cost Per SF	\$51.22	to	\$71.51	\$61.42
Bar / Lounge Softgoods Renovation Cost Per Seat	\$682.94	to	\$953.48	\$818.88

H.A.

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Bar / Lounge - Add for a Full Renovation

	RANGE			
Additional Demolition	\$4,881.60	to	\$6,834.24	\$5,882.33
Bar Die and Top (New in Existing Location)	\$9,630.37	to	\$14,103.79	\$11,391.86
Back Bar (New in Existing Location)	\$9,630.37	to	\$12,037.97	\$10,927.11
Bar Equipment	\$29,349.71	to	\$40,062.36	\$34,573.96
Articulated Drywall Ceiling (New)	\$7,300.80	to	\$9,813.96	\$8,910.35
Banquettes	\$2,800.00	to	\$7,910.00	\$4,734.61
Communal Table Chairs	\$2,014.68	to	\$3,028.20	\$2,521.44
Communal Table	\$2,121.00	to	\$3,181.50	\$2,651.25
Decorative Lighting	\$3,472.41	to	\$5,348.32	\$4,345.50
Electrical	\$7,100.28	to	\$8,875.35	\$7,703.81
Hard Surface Flooring (40%)	\$3,240.00	to	\$4,318.83	\$3,827.37
HVAC	\$1,775.07	to	\$3,550.14	\$2,689.23
Life Safety	\$3,592.40	to	\$4,659.56	\$4,101.68
Architectural Lighting	\$6,212.75	to	\$7,987.82	\$7,171.28
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$633.95	to	\$1,141.12	\$945.42
Sound System	\$2,641.47	to	\$3,328.26	\$2,963.73
TVs - 50" LCD HD	\$2,044.56	to	\$2,339.36	\$2,183.39
Tables	\$3,865.59	to	\$4,236.39	\$4,050.99
Drywall Partitions	\$9,720.00	to	\$12,830.40	\$11,542.48
Bar / Lounge Full Renovation Additional Cost Subtotal	\$112,027.03	to	\$155,587.56	\$133,117.79
Bar / Lounge Full Renovation Additional Cost Per SF	\$155.59	to	\$216.09	\$184.89
Bar / Lounge Full Renovation Additional Cost Per Seat	\$2,074.57	to	\$2,881.25	\$2,465.14

Kitchen

Assume a kitchen area of approximately 20' x 20' (400 SF).

	R	ANGE		AVERAGE
Selective Demolition	\$7,910.00	to	\$9,729.30	\$8,888.58
Vinyl-coated Tile Ceiling (2' x 4' Tiles and New Grid)	\$3,800.00	to	\$7,128.00	\$5,072.20
Fluorescent Lighting (2' x 4')	\$2,958.45	to	\$4,930.75	\$3,579.73
Paint Door Frames and Trim	\$145.00	to	\$220.21	\$182.64
Paint Walls	\$127.20	to	\$180.00	\$158.29
Quarry Tile Flooring	\$9,328.00	to	\$12,242.11	\$11,077.13
Replace Doors	\$1,526.18	to	\$3,446.50	\$2,648.86
Kydex-paneled Walls	\$1,408.00	to	\$1,836.67	\$1,575.65
Kitchen Renovation Cost Subtotal	\$27,202.84	to	\$39,713.55	\$33,183.08
Kitchen Renovation Cost Per SF	\$17.00	to	\$24.82	\$20.74

Kitchen Equipment					
		RANGE			AVERAGE
Select Kitchen Equipment		\$23,479.77	to	\$30,965.12	\$27,080.63
	Kitchen Equipment Cost Subtotal	\$23,479.77	to	\$30,965.12	\$27,080.63
	Kitchen Equipment Cost Per SF	\$14.67	to	\$19.35	\$16.93

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Prefunction Softgoods Renovation

Assume a prefunction area of approximately 10' x 75' (750 SF). Ceiling 12' AFF.

	R	RANGE		
Demolition	\$880.49	to	\$1,294.32	\$1,086.53
Paint Articulated Drywall Ceiling	\$397.50	to	\$562.50	\$494.65
Carpet and Pad	\$3,600.48	to	\$4,278.74	\$3,961.64
Paint Doors and Trim (Service Doors and Exits)	\$145.00	to	\$220.21	\$182.64
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$628.67	to	\$867.00	\$782.64
Protect / Remove / Reinstall All Light Fixtures	\$293.50	to	\$801.25	\$559.41
Vinyl Wallcovering (LY 54")	\$2,827.03	to	\$4,311.22	\$3,589.06
Window Treatments (with Hardware and Installation)	\$2,298.96	to	\$3,457.71	\$2,878.16
Seating Groups	\$7,621.59	to	\$10,044.34	\$8,818.82
Prefunction Softgoods Renovation Cost Subtotal	\$18,693.21	to	\$25,837.29	\$22,353.54
Prefunction Softgoods Renovation Cost Per SF	\$24.92	to	\$34.45	\$29.80

Prefunction - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$3,390.00	to	\$4,449.38	\$3,983.25
Artwork, Accessories, and Mirrors (Allowance, Installed)	\$4,585.56	to	\$6,885.55	\$5,735.38
Articulated Drywall Ceiling (New)	\$4,661.25	to	\$8,765.25	\$6,558.11
Decorative Lighting	\$20,730.24	to	\$32,376.91	\$25,971.17
Electrical	\$3,698.06	to	\$5,547.10	\$4,668.81
HVAC	\$2,641.47	to	\$3,698.06	\$3,160.96
Life Safety	\$3,742.09	to	\$4,853.71	\$4,272.58
Architectural Lighting	\$3,962.21	to	\$6,933.87	\$5,481.06
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$2,289.28	to	\$4,120.70	\$3,634.27
Portable Bars	\$7,618.00	to	\$11,436.00	\$9,526.67
Prefunction Full Renovation Additional Cost Subtotal	\$57,318.16	to	\$89,066.52	\$72,992.26
Prefunction Full Renovation Additional Cost Per SF	\$76.42	to	\$118.76	\$97.32

Ballroom

Typically, hotels in this market segment do not have ballrooms.

H.A.

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Meeting Rooms Softgoods Renovation

Assume 3 meeting rooms with areas approximately 26' x 38' each (988 SF each; 2,964 SF total). Ceiling 12' AFF, coffered.

	RANGE			AVERAGE
Demolition	\$3,479.70	to	\$5,115.16	\$4,293.95
Carpet and Pad	\$12,321.76	to	\$14,256.22	\$13,384.38
Paint Articulated Drywall Ceiling	\$1,570.92	to	\$2,371.20	\$2,004.35
Paint Doors and Trim	\$900.00	to	\$1,065.04	\$964.21
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$1,284.81	to	\$2,073.60	\$1,766.25
Protect / Remove / Reinstall All Light Fixtures	\$1,356.00	to	\$2,135.70	\$1,766.19
Vinyl Wallcovering (LY 54")	\$7,662.91	to	\$11,685.93	\$9,728.45
Window Treatments (with Hardware and Installation)	\$9,662.43	to	\$14,492.10	\$12,076.75
Meeting Rooms Softgoods Renovation Cost Subtotal	\$38,238.54	to	\$53,194.96	\$45,984.53
Meeting Rooms Softgoods Renovation Cost Per SF	\$12.90	to	\$17.95	\$15.51

Meeting Rooms - Add for a Full Renovation

meeting Rooms - Add for a run Renovation				
	R	ANGE		AVERAGE
Additional Demolition	\$17,398.51	to	\$21,191.38	\$19,131.40
Banquet Chairs	\$37,812.59	to	\$52,771.90	\$45,314.06
Artwork, Accessories, and Mirrors (Installed)	\$4,201.05	to	\$6,322.53	\$5,269.24
Articulated Drywall Ceiling (New)	\$30,054.96	to	\$40,400.80	\$36,680.94
Decorative Lighting	\$7,676.40	to	\$11,694.96	\$9,716.19
Electrical	\$29,229.49	to	\$36,536.87	\$31,714.00
HVAC	\$7,307.37	to	\$14,614.75	\$11,070.67
Life Safety	\$14,788.73	to	\$19,181.86	\$16,885.25
Architectural Lighting	\$25,575.81	to	\$32,883.18	\$29,521.79
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$11,172.86	to	\$13,685.76	\$12,412.51
Millwork Serving Stations	\$11,865.00	to	\$20,306.10	\$17,713.31
AV Infrastructure: Ceiling speakers and cabling; input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; CAT 6 AVnet cabling; retractable projection screens built into ceiling; ceiling attachments for portable projectors. Portable equipment by others.	\$20,806.00	to	\$36,565.00	\$31,209.00
Meeting Rooms Full Renovation Additional Cost Subtotal	\$217,888.79	to	\$306,155.09	\$266,638.37
Meeting Rooms Full Renovation Additional Cost Per SF	\$73.51	to	\$103.29	\$89.96

Board Room

Typically, hotels in this market segment do not have board rooms.

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Exercise Facility Softgoods Renovation

Assume a two-bay facility of approximately 26' x 28' (728 SF). Ceiling 10' AFF.

ALL DA

	R	ANGE		AVERAGE
Demolition	\$854.66	to	\$1,256.36	\$1,054.65
Artwork (Installed)	\$337.39	to	\$508.95	\$425.31
Clock	\$49.60	to	\$74.98	\$64.77
Hamper	\$207.03	to	\$263.68	\$235.18
Towel Caddy	\$341.96	to	\$452.17	\$396.89
Sport Flooring	\$10,920.00	to	\$14,560.00	\$12,754.28
Mirrors	\$1,952.64	to	\$2,965.90	\$2,502.91
Paint Doors and Trim	\$600.00	to	\$710.03	\$638.01
Remove and Reinstall Exercise Equipment	\$880.49	to	\$2,157.20	\$1,546.73
Paint Walls	\$686.88	to	\$972.00	\$854.75
Window Treatments (with Hardware and Installation)	\$429.51	to	\$651.99	\$540.75
Exercise Facility Softgoods Renovation Cost Subtotal	\$17,260.16	to	\$24,573.25	\$21,014.24
Exercise Facility Softgoods Renovation Cost Per SF	\$23.71	to	\$33.75	\$28.87

Exercise Facility - Add for a Full Renovation					
	RANGE			AVERAGE	
Additional Demolition	\$4,273.32	to	\$5,204.90	\$4,698.94	
Acoustical Tile Ceiling (New)	\$3,974.88	to	\$5,347.16	\$4,736.33	
Exercise Equipment (Installed)	\$49,431.76	to	\$64,265.82	\$56,848.79	
Electrical	\$7,179.17	to	\$8,973.97	\$7,789.40	
HVAC	\$1,794.79	to	\$3,589.59	\$2,719.11	
Life Safety	\$3,632.32	to	\$4,711.33	\$4,147.26	
Architectural Lighting	\$6,281.78	to	\$8,076.57	\$7,250.97	
TVs and Mounts (42", including Programming Allowance)	\$957.39	to	\$1,104.79	\$1,026.81	
Water Fountain	\$939.19	to	\$1,331.30	\$1,132.66	
Sound System	\$880.49	to	\$1,109.42	\$987.91	
Exercise Facility Full Renovation Additional Cost Subtotal	\$79,345.10	to	\$103,714.85	\$91,338.18	
Exercise Facility Full Renovation Additional Cost Per SF	\$108.99	to	\$142.47	\$125.46	

H.A.

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Outdoor Pool

Assume a 15' x 30' (450 SF) pool and a 12'-wide deck, approximately 1,656 SF surface.

		R	ANGE		AVERAGE
ADA Lift		\$7,910.00	to	\$16,611.00	\$12,136.20
Pool Furniture		\$8,826.00	to	\$13,247.00	\$11,036.33
Pool Equipment		\$5,869.94	to	\$13,559.57	\$9,873.24
Resurface Pool Bottom		\$4,050.00	to	\$9,900.00	\$6,348.97
Resurface Pool Deck (Kool Deck)		\$12,163.32	to	\$15,732.00	\$13,747.24
Signage (Life Safety, Pool Rules)		\$1,130.00	to	\$2,966.25	\$2,118.75
	Outdoor Pool Renovation Cost Subtotal	\$39,949.26	to	\$72,015.82	\$55,260.73
	Outdoor Pool Renovation Cost Per SF	\$18.97	to	\$34.20	\$26.24

Indoor Pool

Assume a 15' x 30' (450 SF) pool and a 12'-wide deck, approximately 1,656 SF surface.

	R	ANGE		AVERAGE
ADA Lift	\$7,910.00	to	\$16,611.00	\$12,136.20
Architectural Lighting	\$18,457.04	to	\$23,730.47	\$21,304.69
Acoustical Tile Ceiling with Aluminum Grid (New)	\$7,785.96	to	\$10,473.97	\$9,277.49
Paint Doors and Trim	\$300.00	to	\$355.01	\$319.00
Pool Deck Tile	\$14,895.57	to	\$19,249.65	\$16,791.98
Pool Equipment	\$5,869.94	to	\$13,559.57	\$9,873.24
Pool Furniture	\$5,147.97	to	\$7,724.48	\$6,436.06
Pool Pak HVAC	\$53,175.54	to	\$64,294.06	\$58,460.87
Replace Doors (Storefront)	\$1,760.98	to	\$2,588.64	\$2,173.05
Resurface Pool Bottom	\$4,050.00	to	\$9,900.00	\$6,348.97
Paint Walls (Assume Two Walls are Storefront, Two are Drywall)	\$408.10	to	\$577.50	\$507.84
Signage (Life Safety, Pool Rules)	\$1,130.00	to	\$2,966.25	\$2,118.75
Indoor Pool Renovation Cost Subtotal	\$120,891.10	to	\$172,030.62	\$145,748.14
Indoor Pool Renovation Cost Per SF	\$57.40	to	\$81.69	\$69.21

ndoor Po	ool Renovatio	າ Cost Per	SF

Outdoor Amenities					
		R	ANGE	AVERAG	
Stamped Concrete at Arrivals		\$10,500.00	to	\$18,375.00	\$13,649.45
Outdoor Furniture		\$9,359.67	to	\$14,048.09	\$11,703.88
Fire Pit		\$9,605.00	to	\$13,500.00	\$11,416.57
Permanent Grill		\$5,869.94	to	\$9,861.50	\$7,900.94
Outdoor Lighting		\$7,630.92	to	\$11,710.53	\$9,679.53
Patio Landscaping		\$5,282.95	to	\$9,245.16	\$7,308.08
	Outdoor Amenities Renovation Cost Subtotal	\$48,248.49	to	\$76,740.29	\$61,658.46

Prototype Hotel: 135 guestrooms, 5 stories, 27 rooms/floor Other assumptions and allowances are listed in each section below.

Outdoor Parking

Assume 150 spaces, 9' x 18', and 25'-wide aisles.

		R	ANGE		AVERAGE
Clean and Seal Asphalt		\$11,542.50	to	\$23,937.65	\$16,390.78
Stripe Spaces		\$2,250.00	to	\$5,700.00	\$3,495.39
Pavement Resurfacing		\$45,258.75	to	\$119,981.25	\$82,265.09
	Outdoor Parking Renovation Cost Subtotal	\$59,051.25	to	\$149,618.90	\$102,151.25
	Outdoor Parking Renovation Cost Per Space	\$393.68	to	\$997.46	\$681.01

Structured Parking

Typically, hotels in this market segment do not have structured parking.

A LE DA

Landscaping					
		R	ANGE		AVERAGE
Landscaping Allowance		\$23,479.77	to	\$32,049.88	\$27,659.17
	Landscaping Renovation Cost Subtotal	\$23,479.77	to	\$32,049.88	\$27,659.17

Common Additives				
	R	ANGE		AVERAGE
New RFID Key System	\$339.00	to	\$474.60	\$416.97
Elevator Cab Finishes	\$3,356.10	to	\$12,209.48	\$8,032.52
Elevator Modernization				
Hydraulic, per Cab	\$82,581.28	to	\$110,572.10	\$97,694.04
Electronic Signage Boards				
Basic System - One Lobby Screen (42" diag.)	\$11,739.88	to	\$16,024.94	\$13,829.58
PTAC Unit Direct Replacement, NIC Finishes	\$1,070.00	to	\$1,233.00	\$1,159.20
Laundry Equipment (Direct Equipment Replacement with Access)				
75# Washer	\$23,479.77	to	\$32,049.88	\$27,659.17
125# Dryer	\$35,219.65	to	\$44,376.76	\$39,516.45
Ironer / Folder	\$117,398.85	to	\$133,130.29	\$123,832.30
Porte Cochere - Re-image: Demolish and Replace	\$11,739.88	to	\$49,307.52	\$31,580.29
Guestroom ADA Modifications				
Bathtub Room	\$17,370.57	to	\$23,100.00	\$19,757.11
Roll-in Shower Room	\$19,602.00	to	\$25,808.00	\$23,255.64
Exterior Signage - Monument - New Graphics on Existing Sign	\$11,739.88	to	\$17,257.63	\$14,487.02
Exterior Signage - Highway - New Graphics on Existing Sign	\$29,349.71	to	\$38,213.32	\$33,587.81
Exterior Signage - New Exterior Brand Sign in Existing Location	\$35,219.65	to	\$44,376.76	\$39,516.45
Dumpster Enclosure (CMU Walls, Wood Gate, Bollards, Concrete Pad)	\$12,500.00	to	\$17,820.00	\$16,368.33
Power-operated, Bi-parting Entrance Doors (Inner and Outer at a Vestibule)	\$27,500.00	to	\$35,640.00	\$32,804.82
Fireplace - Natural Gas with Stone Hearth and Surrounding Wall (Public Area)	\$11,865.00	to	\$19,500.00	\$14,359.95
Replace Guestroom Entry Door and Hardware	\$748.00	to	\$950.00	\$877.36
Replace Guestroom Connecting Doors and Hardware	\$1,630.00	to	\$2,240.00	\$1,878.79
Replace Corridor Service Doors and Hardware	\$988.75	to	\$1,557.28	\$1,328.46
Replace Guestroom Closet Door with Pair of Swing Doors and Hardware	\$790.00	to	\$891.00	\$831.86
Replace Guestroom Bath Door with Barn Door and Hardware	\$1,105.00	to	\$1,310.00	\$1,208.37





Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Guestroom Softgoods Renovation

Assume guestroom area of approximately 13' x 24' and 5' x 7' entry / closet area (389 SF). Ceilings 8'-6" AFF. Painted drywall.

	R	ANGE		AVERAGE
Demolition	\$357.00	to	\$471.73	\$422.75
FF&E Installation	\$167.81	to	\$292.42	\$223.65
Artwork, Mirrors, and Accessories (Installed Package)	\$663.88	to	\$992.14	\$828.67
Full-height Framed Dressing Mirror	\$179.50	to	\$244.09	\$211.90
Bed Skirt or Box Spring Cover	\$166.86	to	\$197.76	\$182.31
Decorative Pillow	\$74.82	to	\$97.27	\$86.04
Carpet and Pad	\$677.56	to	\$784.02	\$731.98
Rigid Vinyl Base	\$284.76	to	\$541.55	\$438.67
Desk Lamp	\$132.87	to	\$170.98	\$151.75
Floor Lamp	\$276.04	to	\$352.26	\$314.15
End Table Lamp	\$209.09	to	\$266.77	\$237.93
Nightstand or Bracket Lamp (2)	\$369.26	to	\$471.23	\$420.24
Welcome Light (in Existing Location)	\$211.41	to	\$281.58	\$250.90
Desk Chair (including Fabric)	\$280.16	to	\$366.68	\$323.42
Lounge Chair (including Fabric)	\$484.10	to	\$634.48	\$559.63
Ottoman (including Fabric)	\$135.45	to	\$173.56	\$154.50
Sleeper Sofa (including Fabric; Assumes King Rooms Only)	\$451.14	to	\$581.44	\$516.37
Paint Textured or Drywall Ceiling	\$202.80	to	\$274.71	\$232.61
Paint Entry Doors, Closet Doors, Frames, and Grilles	\$150.00	to	\$214.78	\$182.56
Vinyl Wallcovering (LY 54")	\$1,042.50	to	\$1,594.20	\$1,325.86
Window Treatments (Sheer, Blackout, Hardware, Installed)	\$504.70	to	\$752.93	\$628.64
Guestroom Softgoods Renovation Cost Per Key	\$7,021.69	to	\$9,756.58	\$8,424.53

Guestroom - Add for a Full Renovation

	R	ANGE		AVERAGE
Casegoods Installation	\$713.00	to	\$869.10	\$791.62
Bedsets (Box Spring, Mattress, and Frame)	\$822.65	to	\$1,069.59	\$945.87
Headboard	\$987.26	to	\$1,480.11	\$1,233.43
Nightstands	\$448.05	to	\$590.19	\$519.12
Dresser	\$636.54	to	\$827.09	\$731.99
Desk	\$774.56	to	\$1,006.31	\$890.61
Side Table	\$275.01	to	\$359.47	\$317.24
Coffee Table	\$261.62	to	\$336.30	\$299.04
Closet Shelf Unit	\$1,216.42	to	\$1,661.82	\$1,423.37
Refrigerator Cabinet / Welcome Center	\$894.30	to	\$1,182.58	\$1,036.06
Mini Refrigerator	\$247.20	to	\$267.80	\$257.50
Drapery Valance - Painted Wood	\$175.00	to	\$264.15	\$227.27
Entry Area Hard Surface Flooring	\$192.50	to	\$249.55	\$229.01
TV and Mount (HD LCD, including Programming Allowance)	\$1,284.67	to	\$1,460.24	\$1,371.60
Guestroom Full Renovation Additional Cost Per Key	\$8,928.77	to	\$11,624.29	\$10,273.71

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Guest Bathroom Softgoods Renovation

Assume guest bathroom area of 6' x 8'. Ceilings 8'-6" AFF. Painted drywall.

	RANGE			AVERAGE	
Demolition	\$101.00	to	\$175.00	\$148.30	
Artwork (Installed)	\$89.17	to	\$126.33	\$107.89	
Lighted Mirror	\$473.14	to	\$651.14	\$556.64	
Makeup Mirror	\$169.55	to	\$202.00	\$186.29	
Night Light	\$75.00	to	\$100.57	\$85.43	
Paint Ceiling	\$25.44	to	\$36.00	\$31.66	
Vinyl Wallcovering (LY 54")	\$198.28	to	\$279.62	\$240.97	
Shower Curtain and Hooks	\$53.07	to	\$58.38	\$55.72	
Curved Shower Rod	\$54.00	to	\$108.00	\$81.97	
Paint Door and Trim	\$75.00	to	\$107.39	\$91.28	
Regrout Floor Tile	\$104.00	to	\$260.00	\$168.08	
Regrout Wall Tile	\$110.00	to	\$275.00	\$177.78	
Guest Bathroom Softgoods Renovation Cost Per Key	\$1,527.65	to	\$2,379.44	\$1,932.02	

Guest Bathroom - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$550.00	to	\$956.25	\$733.74
Architectural Lighting	\$182.00	to	\$250.00	\$226.17
Replace Bathroom Door and Hardware	\$547.50	to	\$594.00	\$575.94
Electrical Upgrades (Add One GFI Outlet)	\$54.50	to	\$100.00	\$78.02
Tub-to-Shower Conversion (New Pan, Solid Panel Surround, Valve and Shower Head)	\$2,825.00	to	\$3,750.00	\$3,331.98
Shower Valve and Head, Tub Diverter, Tub Drain	\$433.00	to	\$586.99	\$499.24
Tub Surround (Solid Panel)	\$840.00	to	\$1,180.00	\$1,017.48
Lavatory	\$216.85	to	\$308.00	\$260.23
Faucet (and Connections)	\$682.80	to	\$1,021.29	\$829.21
Vanity Top	\$374.73	to	\$571.29	\$475.35
Vanity Base	\$324.84	to	\$501.23	\$413.86
Toilet Accessories	\$326.15	to	\$440.29	\$388.77
Tile Flooring	\$415.85	to	\$647.35	\$493.77
Toilet and Seat	\$435.00	to	\$716.60	\$565.61
Guest Bathroom Full Renovation Additional Cost Per Key	\$8,208.22	to	\$11,623.30	\$9,889.38

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor. Other assumptions and allowances are listed in each section below.

Corridors

Per room with each unit 13' long and half of a 6'-wide corridor; 34 rooms per floor.

	R	ANGE		AVERAGE
Demolition	\$47.52	to	\$58.61	\$51.39
Artwork (Installed)	\$13.40	to	\$19.38	\$16.41
Carpet and Pad	\$186.74	to	\$275.12	\$231.16
Rigid Vinyl Base	\$54.24	to	\$103.15	\$83.56
Ceiling-mounted Lighting	\$56.78	to	\$79.17	\$69.05
Sconces	\$124.46	to	\$169.79	\$149.55
Elevator Lobby Furniture (Allowance)	\$54.41	to	\$81.89	\$68.14
Vending Area Floor Tile	\$17.79	to	\$27.69	\$21.12
Ice Machine	\$220.07	to	\$243.46	\$231.77
Millwork (Allowance for Elevator Lobby)	\$69.58	to	\$88.05	\$75.61
Paint Ceiling	\$21.60	to	\$33.75	\$28.60
Signage Package (Room Numbers, Wayfinding, Complete)	\$186.45	to	\$219.50	\$201.65
Vinyl Wallcovering (LY 54")	\$182.65	to	\$283.25	\$234.31
Window Treatments (with Hardware and Installation)	\$23.27	to	\$35.14	\$29.20
Corridors Renovation Cost Per Key	\$1,258.95	to	\$1,717.95	\$1,491.52

Lobby Softgoods Renovation

Assume a 3,500 SF area. Ceiling 12' AFF.				
	R	ANGE		AVERAGE
Demolition	\$4,930.75	to	\$6,040.17	\$5,519.94
Artwork and Artifacts (Installed)	\$9,819.62	to	\$14,858.92	\$12,363.49
Millwork (Refinish)	\$1,760.98	to	\$2,095.57	\$1,910.08
Millwork Screen Walls (Refinish)	\$1,173.99	to	\$1,479.23	\$1,317.22
Paint Drywall Ceiling	\$3,360.00	to	\$5,250.00	\$4,449.33
Paint Doors and Trim	\$750.00	to	\$1,073.92	\$912.78
Vinyl Wallcovering (LY 54", 40% Openings)	\$2,850.76	to	\$4,154.80	\$3,519.66
Window Treatments (with Hardware and Installation)	\$2,664.61	to	\$3,997.43	\$3,331.02
Seating Groups	\$23,137.56	to	\$30,913.84	\$27,151.68
Lobby Softgoods Renovation Cost Subtotal	\$50,448.27	to	\$69,863.87	\$60,475.21
Lobby Softgoods Renovation Cost Per SF	\$14.41	to	\$19.96	\$17.28

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Lobby - Add for a Full Renovation

-	RANGE			AVERAGE
Additional Demolition	\$24,653.76	to	\$29,337.97	\$26,741.11
Decorative Lighting	\$22,817.88	to	\$32,870.86	\$27,799.17
Electrical	\$40,696.95	to	\$51,369.52	\$45,845.17
Hard Surface Flooring	\$59,325.00	to	\$70,596.75	\$65,819.11
HVAC	\$18,490.32	to	\$32,358.06	\$25,578.27
Life Safety	\$17,463.08	to	\$22,650.64	\$19,938.73
Architectural Lighting	\$30,817.20	to	\$49,615.69	\$36,162.30
Front Desk (New Pods, in Existing Location)	\$37,500.00	to	\$61,020.00	\$47,396.76
Front Desk Equipment	\$9,391.91	to	\$11,340.73	\$10,274.75
Concierge Desk	\$7,546.67	to	\$11,273.43	\$9,255.86
Bell Stand	\$5,282.95	to	\$6,286.71	\$5,730.24
Millwork Running Trim (Stained Hardwood Crown and Base)	\$5,223.00	to	\$8,065.00	\$6,433.37
Millwork Screen Walls (New)	\$19,370.81	to	\$27,735.48	\$23,509.12
Articulated Drywall Ceiling (New)	\$35,490.00	to	\$47,706.75	\$43,314.20
Sound System	\$3,698.06	to	\$8,413.09	\$6,243.56
Drywall Partitions	\$12,960.00	to	\$18,428.40	\$16,378.56
Business Center (Millwork / Finishes / Seating)	\$14,520.38	to	\$22,108.53	\$18,258.35
Lobby Full Renovation Additional Cost Subtotal	\$365,247.96	to	\$511,177.60	\$434,678.64
Lobby Full Renovation Additional Cost Per SF	\$104.36	to	\$146.05	\$124.19

Marketplace / Sundries Shop

Assume a 205 SF space with display millwork, refrigeration, and coffee offering.

	R	ANGE		AVERAGE
Demolition	\$1,831.19	to	\$2,736.37	\$2,326.58
Drywall Partitions	\$3,060.00	to	\$4,351.15	\$3,867.16
Articulated Drywall Ceiling (New)	\$2,078.70	to	\$2,794.25	\$2,536.97
Millwork - Display Millwork and Hard Surface Top - 8' Tall	\$6,390.15	to	\$9,892.44	\$8,090.09
Millwork - Island Cabinets and Hard Surface Top	\$2,395.60	to	\$3,701.88	\$3,054.62
Hard Surface Flooring and Base	\$2,583.31	to	\$3,938.05	\$3,050.70
Paint	\$192.00	to	\$300.00	\$254.25
Architectural Lighting	\$2,432.33	to	\$3,466.06	\$3,021.30
Electrical	\$3,532.66	to	\$4,621.42	\$4,111.79
Plumbing	\$2,084.85	to	\$2,882.31	\$2,526.95
Life Safety	\$1,022.84	to	\$1,326.68	\$1,167.84
HVAC	\$508.50	to	\$1,067.85	\$830.55
Nesting Tables	\$1,100.00	to	\$1,800.00	\$1,466.67
Undercounter Refrigerator / Undercounter Freezer	\$2,400.00	to	\$3,500.00	\$2,900.00
Refrigerated Merchandiser	\$10,000.00	to	\$15,000.00	\$12,666.67
Undercounter Ice Maker	\$3,800.00	to	\$5,000.00	\$4,433.33
Microwave Oven	\$175.00	to	\$300.00	\$241.67
Espresso Machine / Coffee	\$13,000.00	to	\$19,000.00	\$16,000.00
Signage	\$2,000.00	to	\$4,000.00	\$3,000.00
Marketplace / Sundries Renovation Cost Subtotal	\$60,587.13	to	\$89,678.46	\$75,547.13
Marketplace / Sundries Renovation Cost Per SF	\$295.55	to	\$437.46	\$368.52

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Public Restrooms Softgoods Renovation

Assume four restrooms totaling 1,440 SF. Each with 5 lavs; 7 fixtures. Ceiling 12' AFF.

	R	ANGE		AVERAGE
Demolition	\$887.54	to	\$1,331.30	\$1,020.67
Artwork and Artifacts (Installed)	\$8,590.72	to	\$12,946.08	\$10,788.26
Framed Mirrors	\$3,875.60	to	\$5,088.00	\$4,484.60
Paint Drywall Ceiling	\$1,526.40	to	\$2,160.00	\$1,928.09
Paint Doors and Trim	\$580.00	to	\$880.84	\$730.57
Vinyl Wallcovering (LY 54")	\$4,478.38	to	\$6,554.98	\$5,544.02
Decorative Vanity Lighting	\$4,266.80	to	\$6,492.90	\$5,420.48
Public Restrooms Softgoods Renovation Cost Subtotal	\$24,205.44	to	\$35,454.10	\$29,916.70
Public Restrooms Softgoods Renovation Cost Per SF	\$16.81	to	\$24.62	\$20.78

Public Restrooms - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$13,524.35	to	\$17,750.71	\$15,553.00
Toilet Partitions	\$24,653.76	to	\$56,382.48	\$35,667.66
Toilet Accessories	\$4,500.00	to	\$7,100.28	\$5,925.67
Replace Doors	\$6,570.00	to	\$7,800.00	\$7,062.47
Toilets / Urinals	\$13,510.00	to	\$25,200.00	\$19,585.94
Architectural Lighting	\$14,200.56	to	\$17,750.71	\$15,407.61
Tile Flooring	\$16,200.00	to	\$21,594.14	\$19,136.86
Tile Walls	\$8,100.00	to	\$10,797.07	\$9,568.43
Motion-sensing Flush Valves	\$17,080.00	to	\$22,288.00	\$18,830.47
Motion-sensing Faucets	\$12,000.00	to	\$18,908.00	\$15,825.84
Vanity Top, Sinks	\$15,280.00	to	\$22,034.30	\$18,373.02
Public Restrooms Full Renovation Additional Cost Subtotal	\$145,618.67	to	\$227,605.68	\$180,936.97
Public Restrooms Full Renovation Additional Cost Per SF	\$101.12	to	\$158.06	\$125.65

Restaurant Softgoods Renovation

Assume a 140-seat restaurant area of approximately 50' x 60' (3,000 SF). Ceiling 12' AFF.

	R	ANGE		AVERAGE
Demolition	\$3,521.97	to	\$5,177.29	\$4,346.11
Artwork (Installed)	\$4,781.07	to	\$7,203.44	\$6,009.93
Carpet and Pad (80% of Floor Area)	\$13,832.05	to	\$16,595.68	\$15,118.14
Millwork Buffet, Host Station (Refinish)	\$5,282.95	to	\$8,505.55	\$6,913.62
Millwork Screen Walls (Refinish)	\$1,173.99	to	\$1,972.30	\$1,580.19
Millwork Running Trim (Refinish - Hardwood Crown, Chair, and Base)	\$736.09	to	\$1,188.00	\$1,011.92
Reupholster Banquettes	\$11,211.00	to	\$17,331.60	\$14,261.20
Paint Drywall Ceiling	\$2,880.00	to	\$4,500.00	\$3,813.71
Paint Doors and Trim	\$435.00	to	\$660.63	\$547.93
Vinyl Wallcovering (LY 54", 40% Openings)	\$3,076.17	to	\$4,503.83	\$3,808.80
Window Treatments (with Hardware and Installation)	\$2,824.26	to	\$4,236.39	\$3,530.15
Dining Chairs (With Arms)	\$10,350.48	to	\$13,525.92	\$11,934.16
Dining Chairs (No Arms)	\$55,711.60	to	\$71,548.40	\$63,582.87
Restaurant Softgoods Renovation Cost Subtotal	\$115,816.63	to	\$156,949.04	\$136,458.71
Restaurant Softgoods Renovation Cost Per SF	\$38.61	to	\$52.32	\$45.49
Restaurant Softgoods Renovation Cost Per Seat	\$827.26	to	\$1,121.06	\$974.71

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Restaurant - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$13,966.80	to	\$18,367.02	\$16,013.00
Banquettes	\$2,550.87	to	\$4,441.53	\$3,456.87
Buffet Equipment	\$29,349.71	to	\$55,470.95	\$42,791.88
Decorative Lighting	\$11,664.37	to	\$17,928.03	\$14,844.05
Architectural Lighting	\$33,282.57	to	\$40,678.70	\$37,350.44
Electrical	\$29,584.51	to	\$36,980.64	\$32,099.19
Hard Surface Flooring (20% of Floor Area)	\$6,750.00	to	\$8,997.56	\$7,973.69
HVAC	\$11,094.19	to	\$18,490.32	\$14,940.18
Life Safety	\$14,968.35	to	\$19,414.83	\$17,090.34
Millwork Buffet, Host Station (New, in Existing Location)	\$50,640.00	to	\$66,565.15	\$59,953.67
Millwork Screen Walls (New)	\$14,674.86	to	\$18,613.59	\$16,530.93
Millwork Running Trim (Hardwood Crown, Chair, and Base)	\$4,792.51	to	\$7,085.10	\$6,419.73
Articulated Drywall Ceiling (New)	\$30,420.00	to	\$40,891.50	\$37,126.46
Sound System	\$3,698.06	to	\$8,413.09	\$6,243.56
Tables	\$19,315.59	to	\$25,415.25	\$22,365.42
Communal Dining Tables, Chef's Table (6 Seats)	\$7,127.54	to	\$11,047.26	\$9,107.74
Communal Table Stools	\$5,191.20	to	\$7,786.80	\$6,489.00
Drywall Partitions	\$14,256.00	to	\$18,817.92	\$16,928.96
Restaurant Full Renovation Additional Cost Subtotal	\$303,327.14	to	\$425,405.24	\$367,725.14
Restaurant Full Renovation Additional Cost Per SF	\$101.11	to	\$141.80	\$122.58
Restaurant Full Renovation Additional Cost Per Seat	\$2,166.62	to	\$3,038.61	\$2,626.61

Bar / Lounge Softgoods Renovation

Assume a 90-seat bar / lounge area of approximately 40' x 40' (1,600 SF). Ceiling 12' AFF.

		RANGE		AVERAGE
Demolition	\$1,878.38	to	\$2,761.22	\$2,317.92
Artwork, Accessories, and Mirrors (Installed)	\$7,829.61	to	\$11,761.70	\$9,798.31
Bar / Back Bar (Refinish)	\$1,760.98	to	\$2,835.18	\$2,304.54
Carpet and Pad (60%)	\$5,147.04	to	\$6,253.95	\$5,650.35
Millwork Running Trim (Refinish)	\$478.99	to	\$739.61	\$610.00
Paint Drywall Ceiling	\$768.00	to	\$1,200.00	\$1,016.99
Paint Doors and Trim	\$145.00	to	\$220.21	\$182.64
Vinyl Wallcovering (LY 54")	\$3,731.98	to	\$5,462.48	\$4,620.02
Reupholster Banquettes	\$7,474.00	to	\$11,554.40	\$9,507.47
Dining Chairs (With Arms)	\$2,587.62	to	\$3,381.48	\$2,983.54
Dining Chairs (No Arms)	\$30,243.44	to	\$38,840.56	\$34,516.41
Bar Stools	\$7,282.10	to	\$10,901.94	\$9,092.02
Seating Group	\$11,002.95	to	\$14,334.07	\$12,684.67
Bar / Lounge Softgoods Renovation Cost	Subtotal \$80,330.10	to	\$110,246.81	\$95,284.88
Bar / Lounge Softgoods Renovation Cos	st Per SF \$50.21	to	\$68.90	\$59.55
Bar / Lounge Softgoods Renovation Cost	Per Seat \$892.56	to	\$1,224.96	\$1,058.72

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Bar / Lounge - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$10,848.00	to	\$15,187.20	\$13,071.84
Bar Die and Top (New in Existing Location)	\$22,566.07	to	\$28,006.00	\$25,355.91
Back Bar (New in Existing Location)	\$18,000.00	to	\$35,640.00	\$27,365.04
Bar Equipment	\$41,089.60	to	\$56,087.30	\$48,403.54
Articulated Drywall Ceiling (New)	\$16,224.00	to	\$21,808.80	\$19,800.78
Banquettes	\$4,200.00	to	\$12,712.50	\$7,271.42
Communal Table Chairs	\$5,191.20	to	\$7,786.80	\$6,489.00
Communal Table	\$7,125.30	to	\$11,043.90	\$9,104.94
Decorative Lighting	\$6,369.14	to	\$9,985.70	\$8,225.27
Electrical	\$15,778.40	to	\$19,723.01	\$17,119.57
Hard Surface Flooring (40%)	\$7,200.00	to	\$9,597.40	\$8,505.27
HVAC	\$5,916.90	to	\$9,861.50	\$7,968.09
Life Safety	\$7,983.12	to	\$10,354.58	\$9,114.85
Architectural Lighting	\$17,750.71	to	\$21,695.31	\$19,920.24
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$2,817.57	to	\$5,071.63	\$4,201.85
Other Seating and Tables (Allowance)	\$2,749.22	to	\$4,131.91	\$3,440.40
Sound System	\$5,547.10	to	\$12,619.64	\$9,365.35
TVs - 50" LCD HD	\$4,089.12	to	\$4,678.72	\$4,366.79
Tables	\$8,866.24	to	\$9,838.56	\$9,355.15
Drywall Partitions	\$17,280.00	to	\$22,809.60	\$20,519.96
Bar / Lounge Full Renovation Additional Cost Subtotal	\$227,591.68	to	\$328,640.05	\$278,965.25
Bar / Lounge Full Renovation Additional Cost Per SF	\$142.24	to	\$205.40	\$174.35
Bar / Lounge Full Renovation Additional Cost Per Seat	\$2,528.80	to	\$3,651.56	\$3,099.61

Kitchen

Assume a kitchen area of approximately 50' x 70' (3,500 SF), including banquet prep.

	RANGE				AVERAGE
Selective Demolition		\$28,673.75	to	\$32,806.73	\$30,517.67
Vinyl-coated Tile Ceiling (2' x 4' Tiles and New Grid)		\$16,625.00	to	\$31,185.00	\$22,190.87
Fluorescent Lighting (2' x 4')		\$12,943.22	to	\$21,572.04	\$15,661.30
Paint Door Frames and Trim		\$725.00	to	\$1,101.06	\$913.21
Paint Walls		\$1,102.40	to	\$1,560.00	\$1,371.83
Quarry Tile Flooring		\$40,810.00	to	\$53,559.23	\$48,462.46
Replace Doors		\$7,630.92	to	\$17,232.50	\$13,244.28
Kydex-paneled Walls		\$2,288.00	to	\$2,984.59	\$2,560.44
Kito	chen Renovation Cost Subtotal	\$110,798.30	to	\$162,001.14	\$134,922.06
K	itchen Renovation Cost Per SF	\$26.38	to	\$38.57	\$32.12

Kitchen Equipment					
		RANGE			AVERAGE
Select Kitchen Equipment		\$79,100.00	to	\$118,650.00	\$96,502.00
	Kitchen Equipment Cost Subtotal	\$79,100.00	to	\$118,650.00	\$96,502.00
	Kitchen Equipment Cost Per SF	\$18.83	to	\$28.25	\$22.98

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Prefunction Softgoods Renovation

Assume prefunction areas are approximately 20' to 25'-wide (7,250 SF). Ceiling 12' AFF, coffered.

	RANGE			AVERAGE	
Demolition	\$8,511.42	to	\$12,511.78	\$10,503.09	
Paint Articulated Drywall Ceiling	\$7,685.00	to	\$10,875.00	\$9,563.22	
Carpet and Pad	\$42,209.34	to	\$51,353.21	\$46,441.26	
Paint Doors and Trim (Service Doors and Exits)	\$435.00	to	\$660.63	\$547.93	
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$2,951.05	to	\$4,069.80	\$3,673.80	
Protect / Remove / Reinstall All Light Fixtures	\$1,760.98	to	\$3,081.72	\$2,436.03	
Vinyl Wallcovering (LY 54")	\$18,613.27	to	\$27,244.12	\$23,042.34	
Window Treatments (with Hardware and Installation)	\$2,803.66	to	\$4,213.73	\$3,508.52	
Seating Groups	\$52,752.35	to	\$68,741.35	\$60,825.97	
Prefunction Softgoods Renovation Cost Subtotal	\$137,722.07	to	\$182,751.34	\$160,542.15	
Prefunction Softgoods Renovation Cost Per SF	\$19.00	to	\$25.21	\$22.14	

Prefunction - Add for a Full Renovation

	R	ANGE		AVERAGE
		-	* 40.040.00	_
Additional Demolition	\$32,770.00	to	\$43,010.63	\$38,504.75
Artwork, Accessories, and Mirrors (Allowance, Installed)	\$28,094.28	to	\$42,129.06	\$35,111.67
Articulated Drywall Ceiling (New)	\$73,515.00	to	\$98,821.13	\$89,722.28
Decorative Lighting	\$80,228.90	to	\$120,840.52	\$100,891.35
Electrical	\$63,835.62	to	\$84,901.38	\$74,006.76
HVAC	\$38,301.37	to	\$67,027.40	\$52,983.57
Life Safety	\$36,173.52	to	\$46,919.18	\$41,301.65
Architectural Lighting	\$63,835.62	to	\$102,775.35	\$83,539.55
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$23,218.61	to	\$28,440.72	\$25,794.75
Portable Bars	\$22,854.00	to	\$34,308.00	\$28,580.00
Prefunction Full Renovation Additional Cost Subtotal	\$462,826.92	to	\$669,173.36	\$570,436.33
Prefunction Full Renovation Additional Cost Per SF	\$63.84	to	\$92.30	\$78.68

Ballroom Softgoods Renovation

Assume a ballroom area of approximately 75' x 114' (8,550 SF) with 3 divisions. Ceiling 18' AFF, coffered.

		RANGE		
Demolition	\$10,037.60	to	\$14,755.27	\$12,386.40
Paint Articulated Drywall Ceiling	\$9,063.00	to	\$13,680.00	\$11,563.56
Carpet and Pad	\$42,119.77	to	\$51,244.23	\$46,342.71
Paint Doors and Trim	\$3,000.00	to	\$3,550.14	\$3,214.03
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$1,686.16	to	\$2,494.80	\$1,959.61
Protect / Remove / Reinstall All Light Fixtures	\$9,605.00	to	\$13,051.50	\$11,446.90
Vinyl Wallcovering (LY 54")	\$13,225.22	to	\$19,357.66	\$16,372.19
Operable Wallcovering	\$3,543.91	to	\$4,825.38	\$4,200.67
Ballroom Softgoods Renovation Cost Subtotal	\$92,280.66	to	\$122,958.99	\$107,486.07
Ballroom Softgoods Renovation Cost Per SF	\$10.79	to	\$14.38	\$12.57

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Ballroom - Add for a Full Renovation				
	R	ANGE		AVERAGE
Additional Demolition	\$60,225.61	to	\$71,668.47	\$65,324.71
Artwork, Accessories, and Mirrors (Allowance, Installed)	\$3,741.99	to	\$5,613.50	\$4,677.57
Banquet Chairs	\$76,352.36	to	\$106,558.65	\$91,499.54
Articulated Drywall Ceiling (New)	\$86,697.00	to	\$116,540.78	\$105,810.41
Decorative Lighting	\$201,936.79	to	\$302,235.94	\$252,233.09
Electrical	\$75,282.01	to	\$100,125.07	\$87,276.94
HVAC	\$45,169.21	to	\$79,046.11	\$62,484.07
Life Safety	\$42,659.81	to	\$55,332.28	\$48,707.46
Architectural Lighting	\$75,282.01	to	\$121,204.04	\$98,519.06
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$10,998.29	to	\$13,471.92	\$12,218.57
Operable Walls (New, Manual)	\$90,233.33	to	\$131,152.50	\$104,398.74
Portable Bars	\$22,854.00	to	\$34,308.00	\$28,580.00
Tables (14" x 72", including Meeting Rooms)	\$34,144.50	to	\$37,234.50	\$35,689.50
Tables (72" rounds, including Meeting Rooms)	\$19,528.80	to	\$22,000.80	\$20,764.80
AV Infrastructure: Ceiling speakers and cabling; wall and floor input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; array of ceiling rigging points with CAT 6 AVnet cabling and power (power by others); retractable projection screens. Portable equipment by others.	\$83,275.50	to	\$145,732.64	\$124,913.25
Ballroom Full Renovation Additional Cost Subtotal	\$928,381.19	to	\$1,342,225.19	\$1,143,097.71

Ballroom Full Renovation Additional Cost Subtotal	\$928,381.19	to	\$1,342,225.19	\$1,143,097.71
Ballroom Full Renovation Additional Cost Per SF	\$108.58	to	\$156.99	\$133.70

Meeting Rooms Softgoods Renovation

Assume 7 meeting rooms with areas approximately 34' x 50' each (1,700 each; 11,900 SF total). Ceiling 12' AFF, coffered.

	R	ANGE		AVERAGE
Demolition	\$13,970.46	to	\$20,536.58	\$17,239.55
Carpet and Pad	\$58,622.84	to	\$71,322.38	\$64,500.38
Paint Articulated Drywall Ceiling	\$12,614.00	to	\$19,040.00	\$16,094.31
Paint Doors and Trim	\$3,150.00	to	\$3,727.65	\$3,374.73
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$4,348.92	to	\$7,056.00	\$6,033.41
Protect / Remove / Reinstall All Light Fixtures	\$3,164.00	to	\$4,983.30	\$4,121.11
Vinyl Wallcovering (LY 54")	\$27,430.08	to	\$40,149.23	\$33,957.13
Window Treatments (with Hardware and Installation)	\$39,366.60	to	\$59,013.85	\$49,189.02
Meeting Rooms Softgoods Renovation Cost Subtotal	\$162,666.91	to	\$225,828.99	\$194,509.65
Meeting Rooms Softgoods Renovation Cost Per SF	\$13.67	to	\$18.98	\$16.35

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Meeting Rooms - Add for a Full Renovation				
	F	RANGE		AVERAGE
Additional Demolition	\$83,822.78	to	\$99,749.10	\$90,919.77
Banquet Chairs	\$131,149.90	to	\$175,275.10	\$152,803.93
Artwork, Accessories, and Mirrors (Installed)	\$23,090.48	to	\$34,681.01	\$28,901.92
Articulated Drywall Ceiling (New)	\$120,666.00	to	\$162,202.95	\$147,268.29
Decorative Lighting	\$24,962.98	to	\$37,793.21	\$31,448.08
Electrical	\$117,351.89	to	\$146,689.86	\$127,326.80
HVAC	\$44,006.96	to	\$73,344.93	\$59,262.70
Life Safety	\$59,374.47	to	\$77,012.18	\$67,791.67
Architectural Lighting	\$132,020.87	to	\$161,358.84	\$148,156.76
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$34,216.90	to	\$41,912.64	\$38,013.32
Millwork Serving Stations	\$35,595.00	to	\$58,138.50	\$48,804.70
AV Infrastructure: Ceiling speakers and cabling; input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification with CAT 6 AVnet cabling; retractable projection screens built into ceiling; ceiling attachments for portable projectors. Portable equipment by others.	\$51,654.50	to	\$90,395.89	\$77,481.75
Meeting Rooms Full Renovation Additional Cost Subtotal	\$857,912.71	to	\$1,158,554.21	\$1,018,179.70
Meeting Rooms Full Renovation Additional Cost Per SF	\$72.09	to	\$97.36	\$85.56

Board Room Softgoods Renovation

Assume a single, 2-bay board room, approximately 26' x 28' (728 SF). Ceiling 12' AFF, coffered.

	R	AVERAGE		
Demolition	\$854.66	to	\$1,256.36	\$1,054.65
Carpet and Pad	\$3,586.34	to	\$4,363.25	\$3,945.91
Paint Articulated Drywall Ceiling	\$771.68	to	\$1,092.00	\$909.58
Paint Doors and Trim	\$300.00	to	\$355.01	\$319.00
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$481.76	to	\$712.80	\$559.89
Protect / Remove / Reinstall All Light Fixtures	\$113.00	to	\$237.30	\$183.06
Vinyl Wallcovering (LY 54")	\$2,519.09	to	\$3,687.17	\$3,118.51
Window Treatments (with Hardware and Installation)	\$1,412.13	to	\$2,117.68	\$1,765.08
Executive Chairs	\$7,736.60	to	\$10,019.20	\$8,874.53
Board Room Softgoods Renovation Cost Subtotal	\$17,775.26	to	\$23,840.78	\$20,730.21
Board Room Softgoods Renovation Cost Per SF	\$24.42	to	\$32.75	\$28.48

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Board Room - Add for a Full Renovation					
	R	RANGE		AVERAGE	
Additional Demolition	\$5,127.98	to	\$6,102.30	\$5,562.15	
Artwork, Accessories, and Mirrors (Installed)	\$967.75	to	\$1,459.64	\$1,216.35	
Articulated Drywall Ceiling (New)	\$7,381.92	to	\$9,923.00	\$9,009.35	
Decorative Lighting	\$2,754.15	to	\$4,572.44	\$3,677.85	
Electrical	\$14,807.52	to	\$18,571.10	\$16,711.93	
HVAC	\$2,692.19	to	\$4,486.98	\$3,625.48	
Life Safety	\$3,632.32	to	\$4,711.33	\$4,147.26	
Architectural Lighting	\$10,903.37	to	\$13,326.34	\$12,236.01	
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$3,142.37	to	\$3,849.12	\$3,491.02	
Millwork Serving Stations	\$5,085.00	to	\$8,305.50	\$6,972.10	
Board Room Conference Table	\$3,670.92	to	\$5,506.38	\$4,588.65	
AV Infrastructure: Ceiling speakers and cabling; wall and floor input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; array of ceiling rigging points with CAT 6 AVnet cabling and power (power by others); retractable projection screens. Portable equipment by others.	\$12,045.85	to	\$21,080.50	\$18,068.78	
Board Room Full Renovation Additional Cost Subtotal	\$72,211.34	to	\$101,894.64	\$89,306.92	
Board Room Full Renovation Additional Cost Per SF	\$99.19	to	\$139.97	\$122.67	

Exercise Facility Softgoods Renovation

Assume a three-bay facility of approximately 28' x 39' (1,092 SF). Ceiling 12' AFF.

	R	ANGE		AVERAGE
Demolition	\$1,282.00	to	\$1,884.53	\$1,581.98
Artwork (Installed)	\$579.44	to	\$876.66	\$730.88
Clock	\$62.99	to	\$92.38	\$80.17
Hamper	\$358.44	to	\$461.44	\$409.94
Towel Caddy	\$394.49	to	\$506.76	\$450.45
Sport Flooring	\$16,380.00	to	\$21,840.00	\$19,131.42
Mirrors	\$2,440.80	to	\$3,707.38	\$3,128.64
Paint Drywall Ceiling	\$578.76	to	\$819.00	\$720.21
Paint Doors and Trim	\$600.00	to	\$710.03	\$638.01
Remove and Reinstall Exercise Equipment	\$2,054.48	to	\$4,376.04	\$3,258.40
Vinyl Wallcovering (LY 54")	\$2,486.83	to	\$3,872.80	\$3,198.90
Window Treatments (with Hardware and Installation)	\$472.77	to	\$717.91	\$595.68
Exercise Facility Softgoods Renovation Cost Subtotal	\$27,691.00	to	\$39,864.94	\$33,924.68
Exercise Facility Softgoods Renovation Cost Per SF	\$25.36	to	\$36.51	\$31.07

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Exercise Facility - Add for a Full Renovation					
	R	ANGE		AVERAGE	
Additional Demolition	\$7,691.97	to	\$9,153.45	\$8,343.23	
Articulated Drywall Ceiling (New)	\$11,072.88	to	\$14,215.22	\$13,170.55	
Exercise Equipment (Installed)	\$74,142.49	to	\$96,393.58	\$85,267.86	
Electrical	\$10,768.76	to	\$13,460.95	\$11,684.11	
HVAC	\$4,038.29	to	\$6,730.48	\$5,438.22	
Life Safety	\$5,448.48	to	\$7,067.00	\$6,220.88	
Architectural Lighting	\$12,114.86	to	\$14,807.05	\$13,595.56	
Millwork Lockers	\$8,804.91	to	\$11,217.46	\$9,944.86	
TVs and Mounts (42", including Programming Allowance)	\$4,559.82	to	\$5,136.84	\$4,839.42	
Water Fountain	\$1,408.79	to	\$2,218.84	\$1,817.33	
Sound System	\$1,849.03	to	\$4,206.55	\$3,121.78	
Exercise Facility Full Renovation Additional Cost Subtotal	\$141,900.28	to	\$184,607.41	\$163,443.81	
Exercise Facility Full Renovation Additional Cost Per SF	\$129.95	to	\$169.05	\$149.67	

Outdoor Pool

Assume a 20' x 40' (800 SF) pool and a 15'-wide deck, approximately 2,700 SF surface.

		R	ANGE		AVERAGE
ADA Lift		\$7,910.00	to	\$16,611.00	\$12,136.20
Pool Furniture		\$49,169.00	to	\$73,762.00	\$61,465.33
Pool Equipment		\$11,739.88	to	\$19,723.01	\$15,801.88
Resurface Pool Bottom		\$7,200.00	to	\$17,600.00	\$11,287.05
Resurface Pool Deck (Kool Deck)		\$21,600.00	to	\$29,700.00	\$24,387.67
Signage (Life Safety, Pool Rules)		\$1,130.00	to	\$2,966.25	\$2,118.75
	Outdoor Pool Renovation Cost Subtotal	\$98,748.88	to	\$160,362.26	\$127,196.89
	Outdoor Pool Renovation Cost Per SF	\$28.21	to	\$45.82	\$36.34

Indoor Pool

Assume a 20' x 40' (800 SF) pool and a 12'-wide deck, approximately 2,016 SF surface.

		R	ANGE		AVERAGE
ADA Lift		\$7,910.00	to	\$16,611.00	\$12,136.20
Architectural Lighting		\$33,548.83	to	\$41,004.13	\$37,649.25
Drywall Ceiling (New, from Scaffolding)		\$15,120.00	to	\$17,962.56	\$16,948.76
Paint Doors and Trim		\$450.00	to	\$532.52	\$478.50
Pool Deck Tile		\$21,413.55	to	\$28,480.02	\$24,825.44
Pool Equipment		\$11,739.88	to	\$19,723.01	\$15,801.88
Pool Furniture		\$9,359.67	to	\$14,048.09	\$11,703.88
Pool Pak HVAC		\$75,176.64	to	\$90,895.39	\$82,648.74
Replace Doors (Storefront)		\$1,760.98	to	\$2,588.64	\$2,173.05
Resurface Pool Bottom		\$7,200.00	to	\$17,600.00	\$11,287.05
Wall Tile		\$12,420.00	to	\$16,555.51	\$14,671.59
Signage (Life Safety, Pool Rules)		\$1,130.00	to	\$2,966.25	\$2,118.75
	Indoor Pool Renovation Cost Subtotal	\$197,229.56	to	\$268,967.12	\$232,443.10
	Indoor Pool Renovation Cost Per SF	\$70.04	to	\$95.51	\$82.54

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor. Other assumptions and allowances are listed in each section below.

Outdoor Amenities					
		RANGE			AVERAGE
Stamped Concrete at Arrivals		\$38,743.75	to	\$52,829.48	\$47,339.08
Outdoor Furniture		\$52,143.27	to	\$78,224.50	\$65,183.72
Fire Pit		\$9,605.00	to	\$13,500.00	\$11,416.57
Outdoor Lighting		\$11,152.89	to	\$36,364.29	\$24,413.09
Patio Landscaping		\$13,500.87	to	\$24,037.41	\$18,895.34
	Outdoor Amenities Renovation Cost Subtotal	\$125 145 78	to	\$204 955 69	\$167 247 80

Outdoor Parking

Assume 486 spaces, 9' x 19', and 25'-wide aisles (1.6 spaces per room to accommodate meeting attendance).

		RANGE			AVERAGE	
Clean and Seal Asphalt		\$37,397.70	to	\$77,557.99	\$53,106.13	
Stripe Spaces		\$7,290.00	to	\$18,468.00	\$11,325.06	
Pavement Resurfacing		\$146,638.35	to	\$388,739.25	\$266,538.88	
	Outdoor Parking Renovation Cost Subtotal	\$191,326.05	to	\$484,765.24	\$330,970.06	
	Outdoor Parking Renovation Cost Per Space	\$393.68	to	\$997.46	\$681.01	

Structured Parking

Typically, hotels in this market segment do not have structured parking.

Landscaping					
		RANGE			AVERAGE
Landscaping Allowance		\$46,959.54	to	\$73,961.27	\$60,577.80
	Landscaping Renovation Cost Subtotal	\$46,959.54	to	\$73,961.27	\$60,577.80

Prototype Hotel: 304 guestrooms, 9 stories (8 with guestrooms), 34 rooms/floor Other assumptions and allowances are listed in each section below.

Common Additives

Common Additives				
	R	ANGE		AVERAGE
New RFID Key System	\$339.00	to	\$474.60	\$416.97
Elevator Cab Finishes	\$14,674.86	to	\$20,832.43	\$17,714.31
Elevator Modernization				
Traction, per Cab	\$233,506.30	to	\$294,217.94	\$261,994.07
Electronic Signage Boards				
Basic System - One Lobby Screen (42" diag.)	\$17,609.83	to	\$25,393.37	\$21,467.55
Additional Lobby / Prefunction Screens	\$5,869.94	to	\$8,464.46	\$7,155.85
Additional Meeting Room Door Screen (18" diag.)	\$5,699.71	to	\$8,285.72	\$6,983.92
Two-Pipe Horizontal Fan Coil Unit Direct Replacement, NIC Finishes	\$1,800.00	to	\$3,874.16	\$2,575.75
Four-Pipe Vertical Fan Coil Unit Direct Replacement with Drywall Repair	\$2,598.75	to	\$5,800.00	\$3,873.07
Laundry Equipment (Direct Equipment Replacement with Access)				
75# Washer	\$23,479.77	to	\$32,049.88	\$27,659.17
125# Dryer	\$35,219.65	to	\$44,376.76	\$39,516.45
Ironer / Folder	\$117,398.85	to	\$133,130.29	\$123,832.30
Porte Cochere - Re-image: Demolish and Replace	\$29,349.71	to	\$67,797.83	\$49,366.21
Guestroom ADA Modifications				
Bathtub Room	\$18,460.00	to	\$27,120.00	\$23,012.12
Roll-in Shower Room	\$21,375.00	to	\$29,380.00	\$25,519.41
Exterior Signage - Monument - New Graphics on Existing Sign	\$17,609.83	to	\$23,421.07	\$20,415.66
Exterior Signage - New Exterior Brand Sign in Existing Location	\$46,959.54	to	\$56,703.64	\$51,373.73
Power-operated, Bi-parting Entrance Doors (Inner and Outer at a Vestibule)	\$27,500.00	to	\$35,640.00	\$32,804.82
Fireplace - Natural Gas with Stone Hearth and Surrounding Wall (Public Area)	\$11,865.00	to	\$19,500.00	\$14,359.95
Add Screening for Buffet in Restaurant	\$11,865.00	to	\$56,500.00	\$28,423.00
Replace Guestroom Entry Door and Hardware	\$748.00	to	\$950.00	\$877.36
Replace Guestroom Connecting Doors and Hardware	\$1,630.00	to	\$2,240.00	\$1,878.79
Replace Corridor Service Doors and Hardware	\$1,356.00	to	\$1,779.75	\$1,559.40
Replace Guestroom Closet Door with Pair of Swing Doors and Hardware	\$790.00	to	\$891.00	\$831.86
Replace Guestroom Bath Door with Barn Door and Hardware	\$1,105.00	to	\$1,310.00	\$1,208.37
Incremental Add for LVT in Guestroom Instead of Carpet	\$941.46	to	\$1,537.01	\$1,309.49



UPPER UPSCALE

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Guestroom Softgoods Renovation

Decorative Pillow	\$106.56 \$802.48	to	\$138.49 \$1.051.26	\$122.5
Bed Skirt or Box Spring Cover Decorative Pillow	\$171.50 \$106.56	to to	\$203.94 \$138.49	\$187.40 \$122.5
Carpet and Pad	\$893.48	to	\$1,051.26	\$960.22
Desk Lamp	\$153.47	to	\$191.58	\$172.7
Floor Lamp	\$278.10	to	\$371.83	\$324.7
End Table Lamp	\$276.04	to	\$352.26	\$314.1
Nightstand or Bracket Lamp (2)	\$392.43	to	\$523.76	\$458.3
Welcome Light (in Existing Location)	\$223.77	to	\$293.94	\$262.9
Desk Chair (including Fabric)	\$331.66	to	\$438.78	\$385.5
Lounge Chair (including Fabric)	\$689.07	to	\$903.31	\$796.1
Ottoman (including Fabric)	\$283.25	to	\$379.04	\$330.9
Sleeper Sofa (including Fabric; Assumes King Rooms Only)	\$520.67	to	\$673.11	\$596.8
Paint Textured or Drywall Ceiling	\$316.98	to	\$443.77	\$405.7
Paint Trim (Base and Crown)	\$445.11	to	\$707.00	\$628.1
Paint Entry Doors, Closet Doors, Frames, and Grilles	\$150.00	to	\$214.78	\$182.5
Vinyl Wallcovering (LY 54")	\$1,550.62	to	\$2,225.01	\$1,896.6
Window Treatments (Sheer, Blackout, Hardware, Installed)	\$559.29	to	\$847.69	\$703.4
Guestroom Softgoods Renovation Cost Per Key	\$9,061.02	to	\$12,423.96	\$10,825.8

Guestroom - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$57.50	to	\$150.00	\$107.80
Casegoods Installation	\$713.00	to	\$869.10	\$791.62
Bedsets (Box Spring, Mattress, and Frame)	\$852.95	to	\$1,101.41	\$977.18
Headboard	\$1,134.03	to	\$1,713.41	\$1,423.46
Nightstands	\$709.16	to	\$911.55	\$810.61
Dresser	\$1,514.10	to	\$1,968.33	\$1,741.39
Desk	\$1,185.53	to	\$1,551.18	\$1,368.18
Side Table	\$317.24	to	\$404.79	\$361.19
Coffee Table	\$318.27	to	\$415.09	\$366.85
Closet Shelf Unit	\$1,709.79	to	\$2,312.78	\$1,995.71
Refrigerator Cabinet / Welcome Center	\$1,434.63	to	\$1,879.22	\$1,650.39
Mini Refrigerator	\$247.20	to	\$267.80	\$257.50
Crown Molding	\$808.00	to	\$1,079.69	\$890.54
Drapery Valance - Painted Wood	\$188.46	to	\$328.72	\$272.05
Wall Base	\$765.62	to	\$869.61	\$831.69
Entry Area Hard Surface Flooring	\$831.60	to	\$1,170.68	\$1,005.04
TV and Mount (HD LCD, including Programming Allowance)	\$1,284.67	to	\$1,460.24	\$1,371.60
Guestroom Full Renovation Additional Cost Per Key	\$14,071.74	to	\$18,453.58	\$16,222.79

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Guest Bathroom Softgoods Renovation

Assume guest bathroom area of 8' x 8'. Ceilings 9' AFF. Painted drywall.

	RANGE			AVERAGE
Demolition	\$101.00	to	\$175.00	\$148.30
Artwork (Installed)	\$140.66	to	\$218.00	\$179.23
Lighted Mirror	\$562.75	to	\$769.59	\$660.67
Makeup Mirror	\$208.90	to	\$251.44	\$230.69
Night Light	\$75.00	to	\$100.57	\$85.43
Paint Ceiling	\$33.92	to	\$48.00	\$42.21
Vinyl Wallcovering (LY 54")	\$293.08	to	\$394.16	\$345.98
Curved Shower Rod	\$54.00	to	\$108.00	\$81.97
Paint Door and Trim	\$75.00	to	\$107.39	\$91.28
Regrout Floor Tile	\$128.00	to	\$320.00	\$206.87
Regrout Wall Tile	\$140.00	to	\$350.00	\$226.27
Guest Bathroom Softgoods Renovation Cost Per Key	\$1,812.31	to	\$2,842.15	\$2,298.90

Guest Bathroom - Add for a Full Renovation

	R	ANGE		AVERAGE
		-		
Additional Demolition	\$550.00	to	\$956.25	\$733.74
Architectural Lighting	\$364.00	to	\$500.00	\$452.34
Replace Bathroom Door and Hardware	\$650.00	to	\$880.49	\$750.26
Electrical Upgrades (Add One GFI Outlet)	\$109.00	to	\$200.00	\$156.03
Tub-to-Shower Conversion (New Pan, Tile Surround, Valve, and Shower Head)	\$3,700.00	to	\$4,815.92	\$4,261.58
Shower Valve and Head, Tub Diverter, Tub Drain	\$586.99	to	\$819.74	\$678.15
Tub Surround (Tile)	\$1,237.94	to	\$1,762.80	\$1,421.88
Lavatory	\$433.70	to	\$737.66	\$551.74
Faucet (and Connections)	\$1,082.06	to	\$2,114.02	\$1,467.83
Vanity Top	\$592.06	to	\$891.62	\$743.84
Vanity Base	\$408.27	to	\$627.92	\$518.92
Toilet Accessories	\$375.00	to	\$452.50	\$421.85
Tile Flooring	\$650.88	to	\$784.23	\$735.15
Toilet and Seat	\$452.00	to	\$757.00	\$625.60
Guest Bathroom Full Renovation Additional Cost Per Key	\$11,191.90	to	\$16,300.15	\$13,518.93

www.

-計構し

-

UPPER UPSCAL

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Corridors

Per room with each unit 15' long and half of a 6'-wide corridor; 31 bays per floor.

	R	ANGE		AVERAGE	
Demolition	\$47.52	to	\$58.61	\$51.39	
Artwork (Installed)	\$17.15	to	\$25.67	\$21.42	
Carpet and Pad	\$228.12	to	\$285.95	\$258.07	
Millwork Base	\$136.45	to	\$154.98	\$148.22	
Ceiling-mounted Lighting	\$151.64	to	\$205.40	\$180.71	
Sconces	\$247.46	to	\$335.14	\$295.54	
Elevator Lobby Furniture (Allowance)	\$76.75	to	\$115.39	\$96.08	
Vending Area Floor Tile	\$26.02	to	\$42.83	\$31.36	
Ice Machine	\$241.77	to	\$267.95	\$254.90	
Millwork (Allowance for Elevator Lobby)	\$85.85	to	\$108.64	\$93.29	
Paint Ceiling	\$21.60	to	\$33.75	\$28.60	
Signage Package (Room Numbers, Wayfinding, Complete)	\$186.45	to	\$219.50	\$201.65	
Vinyl Wallcovering (LY 54")	\$224.53	to	\$339.61	\$283.62	
Window Treatments (with Hardware and Installation)	\$28.11	to	\$42.16	\$35.13	
Corridors Renovation Cost Per Key	\$1 719 42	to	\$2 235 59	\$1 979 97	

Lobby Softgoods Renovation

Assume a 4,800 SF area.	Ceiling 12' AFF.

	R	ANGE		AVERAGE
Demolition	\$6,762.17	to	\$8,283.66	\$7,570.21
Artwork and Artifacts (Installed)	\$12,358.07	to	\$18,739.99	\$15,584.06
Area Rugs	\$8,049.70	to	\$12,083.64	\$10,067.01
Millwork (Refinish)	\$2,347.98	to	\$2,958.45	\$2,634.43
Millwork Screen Walls (Refinish)	\$3,521.97	to	\$4,684.21	\$4,083.13
Paint Drywall Ceiling	\$4,608.00	to	\$7,200.00	\$6,101.94
Paint Doors and Trim	\$750.00	to	\$1,073.92	\$912.78
Vinyl Wallcovering (LY 54", 40% Openings)	\$3,739.54	to	\$5,132.33	\$4,452.82
Window Treatments (with Hardware and Installation)	\$5,481.66	to	\$8,222.49	\$6,852.25
Seating Groups	\$47,794.23	to	\$62,095.66	\$54,945.95
Lobby Softgoods Renovation Cost Subtotal	\$95,413.32	to	\$130,474.35	\$113,204.58
Lobby Softgoods Renovation Cost Per SF	\$19.88	to	\$27.18	\$23.58

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Lobby - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$45,081.16	to	\$52,068.74	\$48,056.51
Decorative Lighting	\$27,173.47	to	\$38,971.73	\$33,012.90
Electrical	\$55,812.96	to	\$70,449.62	\$62,873.38
Hard Surface Flooring	\$86,784.00	to	\$104,563.87	\$98,020.36
HVAC	\$25,358.15	to	\$44,376.76	\$35,078.77
Life Safety	\$23,949.36	to	\$31,063.73	\$27,344.54
Architectural Lighting	\$56,351.45	to	\$88,753.53	\$72,693.37
Front Desk (New Pods, in Existing Location)	\$32,076.00	to	\$61,698.00	\$47,276.80
Front Desk Equipment	\$9,391.91	to	\$11,340.73	\$10,274.75
Concierge Desk	\$7,546.67	to	\$11,273.43	\$9,255.86
Bell Stand	\$7,910.00	to	\$10,322.55	\$9,203.85
Millwork Running Trim (Stained Hardwood Crown and Base)	\$7,312.20	to	\$11,291.00	\$9,006.72
Millwork Screen Walls (New)	\$39,328.61	to	\$58,552.67	\$48,925.97
Articulated Drywall Ceiling (New)	\$48,672.00	to	\$65,426.40	\$59,402.34
Sound System	\$7,396.13	to	\$12,943.22	\$10,231.31
Drywall Partitions	\$12,960.00	to	\$18,428.40	\$16,378.56
Business Center (Millwork / Finishes / Seating)	\$19,455.61	to	\$29,620.86	\$24,463.61
Lobby Full Renovation Additional Cost Subtotal	\$512,559.68	to	\$721,145.26	\$621,499.60
Lobby Full Renovation Additional Cost Per SF	\$106.78	to	\$150.24	\$129.48

Marketplace / Sundries Shop

Assume a 205 SF space with display millwork, refrigeration, and coffee offering.

	R	ANGE		AVERAGE
Demolition	\$1,831.19	to	\$2,736.37	\$2,326.58
Drywall Partitions	\$3,060.00	to	\$4,351.15	\$3,867.16
Articulated Drywall Ceiling (New)	\$2,078.70	to	\$2,794.25	\$2,536.97
Millwork - Display Millwork and Hard Surface Top - 8' Tall	\$6,390.15	to	\$9,892.44	\$8,090.09
Millwork - Island Cabinets and Hard Surface Top	\$2,395.60	to	\$3,701.88	\$3,054.62
Hard Surface Flooring and Base	\$4,253.09	to	\$4,465.75	\$4,295.62
Paint	\$192.00	to	\$300.00	\$254.25
Architectural Lighting	\$2,432.33	to	\$3,466.06	\$3,021.30
Electrical	\$3,532.66	to	\$4,621.42	\$4,111.79
Plumbing	\$2,084.85	to	\$2,882.31	\$2,526.95
Life Safety	\$1,022.84	to	\$1,326.68	\$1,167.84
HVAC	\$508.50	to	\$1,067.85	\$830.55
Nesting Tables	\$1,100.00	to	\$1,800.00	\$1,466.67
Undercounter Refrigerator / Undercounter Freezer	\$3,000.00	to	\$4,000.00	\$3,500.00
Refrigerated Merchandiser	\$10,000.00	to	\$15,000.00	\$12,666.67
Undercounter Ice Maker	\$3,800.00	to	\$5,000.00	\$4,433.33
Microwave Oven	\$175.00	to	\$300.00	\$241.67
Espresso Machine / Coffee	\$13,000.00	to	\$19,000.00	\$16,000.00
Signage	\$2,000.00	to	\$4,000.00	\$3,000.00
Marketplace / Sundries Renovation Cost Subtotal	\$62,856.91	to	\$90,706.16	\$77,392.05
Marketplace / Sundries Renovation Cost Per SF	\$306.62	to	\$442.47	\$377.52

annead Labhta

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Public Restrooms Softgoods Renovation

Assume four restrooms, totaling 1,440 SF. Each with 5 lavs and 7 fixtures. Ceiling 12' AFF.

	R	ANGE		AVERAGE
Demolition	\$887.54	to	\$1,331.30	\$1,020.67
Artwork and Artifacts (Installed)	\$10,090.40	to	\$15,228.56	\$12,680.72
Backlit Mirror	\$5,500.00	to	\$7,530.00	\$6,460.00
Paint Drywall Ceiling	\$1,526.40	to	\$2,160.00	\$1,928.09
Paint Doors and Trim	\$580.00	to	\$880.84	\$730.57
Vinyl Wallcovering (LY 54")	\$5,920.15	to	\$8,142.70	\$7,058.77
Decorative Vanity Lighting	\$4,926.00	to	\$7,440.50	\$6,223.88
Public Restrooms Softgoods Renovation Cost Subtotal	\$29,430.49	to	\$42,713.91	\$36,102.70
Public Restrooms Softgoods Renovation Cost Per SF	\$20.44	to	\$29.66	\$25.07

Public Restrooms - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$13,524.35	to	\$17,750.71	\$15,553.00
Toilet Partitions	\$36,158.84	to	\$53,498.65	\$44,882.44
Toilet Accessories	\$4,500.00	to	\$7,810.31	\$6,329.71
Replace Doors	\$6,570.00	to	\$7,800.00	\$7,062.47
Toilets / Urinals	\$13,510.00	to	\$25,200.00	\$19,585.94
Architectural Lighting	\$14,200.56	to	\$17,750.71	\$15,407.61
Tile Flooring	\$18,146.16	to	\$29,875.39	\$21,871.94
Tile Walls	\$9,073.08	to	\$16,060.16	\$11,160.46
Motion-sensing Flush Valves	\$17,080.00	to	\$22,288.00	\$18,830.47
Motion-sensing Faucets	\$12,000.00	to	\$18,908.00	\$15,825.84
Vanity Top, Sinks	\$16,380.00	to	\$26,231.30	\$21,881.95
Millwork Vanity Base	\$8,502.00	to	\$22,305.78	\$14,665.51
Public Restrooms Full Renovation Additional Cost Subtotal	\$169,645.00	to	\$265,479.01	\$213,057.34
Public Restrooms Full Renovation Additional Cost Per SF	\$117.81	to	\$184.36	\$147.96

Restaurant Softgoods Renovation

Assume a 195-seat restaurant area of approximately 60' x 76' (4,560 SF). Ceiling 12' AFF.

	R	ANGE		AVERAGE
Demolition	\$8,030.08	to	\$10,680.01	\$9,309.54
Artwork (Installed)	\$7,707.88	to	\$11,607.85	\$9,679.04
Carpet and Pad (80% of Floor Area)	\$23,639.26	to	\$28,097.47	\$25,722.86
Millwork Buffet, Host Station (Refinish)	\$5,987.34	to	\$9,245.16	\$7,625.06
Millwork Screen Walls (Refinish)	\$2,347.98	to	\$4,930.75	\$3,686.32
Millwork Running Trim (Refinish - Hardwood Crown, Chair, and Base)	\$1,418.25	to	\$2,162.40	\$1,626.79
Reupholster Banquettes	\$12,170.50	to	\$18,432.50	\$15,301.50
Paint Drywall Ceiling	\$4,377.60	to	\$6,840.00	\$5,796.84
Paint Doors and Trim	\$725.00	to	\$1,101.06	\$913.21
Vinyl Wallcovering (LY 54", 40% Openings)	\$4,976.80	to	\$6,859.26	\$5,941.28
Window Treatments (with Hardware and Installation)	\$3,812.03	to	\$5,718.56	\$4,765.47
Dining Chairs (With Arms)	\$87,491.25	to	\$114,887.50	\$101,159.92
Dining Chairs (No Arms)	\$9,494.00	to	\$12,261.40	\$10,881.07
Restaurant Softgoods Renovation Cost Subtotal	\$172,177.98	to	\$232,823.92	\$202,408.88
Restaurant Softgoods Renovation Cost Per SF	\$37.76	to	\$51.06	\$44.39
Restaurant Softgoods Renovation Cost Per Seat	\$882.96	to	\$1,193.97	\$1,037.99

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor. Other assumptions and allowances are listed in each section below.

UPPER UPSCA

Restaurant - Add for a Full Renovation

	RANGE		AVERAGE		
Additional Demolition	\$21,229.54	to	\$27,917.87	\$24,339.77	
Banquettes	\$2,838.72	to	\$4,949.53	\$3,845.99	
Buffet Equipment	\$35,219.65	to	\$66,565.15	\$51,350.25	
Decorative Lighting	\$17,511.21	to	\$27,038.32	\$22,475.34	
Architectural Lighting	\$61,831.62	to	\$70,825.31	\$65,878.78	
Electrical	\$44,968.45	to	\$56,210.57	\$48,790.77	
Hard Surface Flooring (20% of Floor Area)	\$17,138.21	to	\$24,733.44	\$19,776.76	
HVAC	\$33,493.20	to	\$48,180.49	\$43,337.22	
Life Safety	\$22,751.90	to	\$29,510.55	\$25,977.31	
Millwork Buffet, Host Station (New, in Existing Location)	\$62,412.00	to	\$89,862.95	\$71,200.68	
Millwork Screen Walls (New)	\$29,349.71	to	\$35,008.34	\$31,878.48	
Millwork Running Trim (Hardwood Crown, Chair, and Base)	\$7,914.11	to	\$13,561.92	\$9,780.23	
Articulated Drywall Ceiling (New)	\$46,238.40	to	\$62,155.08	\$56,432.22	
Sound System	\$5,547.10	to	\$12,619.64	\$9,365.35	
Tables	\$27,181.70	to	\$35,885.20	\$31,533.45	
Communal Dining Tables, Chef's Table (6 Seats)	\$8,108.10	to	\$12,518.10	\$10,333.44	
Communal Table Stools	\$5,710.32	to	\$8,565.48	\$7,139.96	
Drywall Partitions	\$17,625.60	to	\$23,265.79	\$20,930.36	
Restaurant Full Renovation Additional Cost Subtotal	\$467,069.55	to	\$649,373.72	\$554,366.35	
Restaurant Full Renovation Additional Cost Per SF	\$102.43	to	\$142.41	\$121.57	
Restaurant Full Renovation Additional Cost Per Seat	\$2,395.23	to	\$3,330.12	\$2,842.90	

Bar / Lounge Softgoods Renovation

Assume a 70-seat bar / lounge area of approximately 30' x 40' (1,200 SF). Ceiling 12' AFF.

		R		AVERAGE		
Demolition		\$2,113.18	to	\$2,810.53	\$2,449.88	
Artwork, Accessories, and Mirrors (Installed)		\$9,815.45	to	\$14,729.13	\$12,274.77	
Bar / Back Bar (Refinish)		\$2,494.73	to	\$3,852.15	\$3,177.11	
Carpet and Pad (60%)		\$4,665.64	to	\$5,574.70	\$5,082.71	
Millwork Running Trim (Refinish)		\$729.98	to	\$1,113.00	\$837.32	
Paint Drywall Ceiling		\$576.00	to	\$900.00	\$762.74	
Paint Doors and Trim		\$145.00	to	\$220.21	\$182.64	
Vinyl Wallcovering (LY 54")		\$4,316.78	to	\$5,937.38	\$5,147.02	
Reupholster Banquettes		\$9,249.58	to	\$14,008.70	\$11,629.14	
Dining Chairs (With Arms)		\$2,999.70	to	\$3,939.00	\$3,468.34	
Dining Chairs (No Arms)		\$26,583.20	to	\$34,331.92	\$30,466.99	
Bar Stools		\$7,960.82	to	\$12,019.00	\$9,992.27	
Seating Group		\$14,556.15	to	\$18,922.67	\$16,726.42	
Bar / Lounge Softgo	ods Renovation Cost Subtotal	\$86,206.21	to	\$118,358.39	\$102,197.34	
Bar / Lounge Soft	joods Renovation Cost Per SF	\$71.84	to	\$98.63	\$85.16	
Bar / Lounge Softgo	ods Renovation Cost Per Seat	\$1,231.52	to	\$1,690.83	\$1,459.96	

www.

法法法

JPPER UPSCA F

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Bar / Lounge - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$8,136.00	to	\$11,390.40	\$9,803.88
Bar Die and Top (New in Existing Location)	\$28,207.58	to	\$39,126.25	\$33,843.81
Back Bar (New in Existing Location)	\$33,877.77	to	\$44,550.00	\$38,789.10
Bar Equipment	\$46,959.54	to	\$64,099.77	\$55,318.34
Articulated Drywall Ceiling (New)	\$12,168.00	to	\$16,356.60	\$14,850.58
Banquettes	\$5,600.00	to	\$18,080.00	\$9,921.23
Communal Table Chairs	\$5,710.32	to	\$8,565.48	\$7,139.96
Communal Table	\$8,296.90	to	\$12,801.30	\$10,569.44
Decorative Lighting	\$8,151.60	to	\$12,985.00	\$10,768.70
Electrical	\$11,833.80	to	\$14,792.25	\$12,839.68
Hard Surface Flooring (40%)	\$9,958.46	to	\$13,017.60	\$11,069.30
HVAC	\$5,635.14	to	\$12,425.49	\$10,650.85
Life Safety	\$5,987.34	to	\$7,765.93	\$6,836.13
Architectural Lighting	\$16,271.48	to	\$18,638.24	\$17,336.52
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$4,073.44	to	\$4,989.60	\$4,525.40
Other Seating and Tables (Allowance)	\$3,844.06	to	\$5,766.09	\$4,805.24
Sound System	\$8,320.64	to	\$18,929.46	\$14,048.02
TVs - 50" LCD HD	\$4,089.12	to	\$4,678.72	\$4,366.79
Tables	\$8,095.80	to	\$8,849.76	\$8,474.84
Drywall Partitions	\$15,120.00	to	\$19,958.40	\$17,954.96
Bar / Lounge Full Renovation Additional Cost Subtotal	\$250,337.00	to	\$357,766.36	\$303,912.76
Bar / Lounge Full Renovation Additional Cost Per SF	\$208.61	to	\$298.14	\$253.26
Bar / Lounge Full Renovation Additional Cost Per Seat	\$3,576.24	to	\$5,110.95	\$4,341.61

Kitchen

Assume a kitchen area of approximately 60' x 70' (4,200 SF).

	F	RANGE		AVERAGE
Selective Demolition	\$34,408.50	to	\$39,368.07	\$36,621.20
Vinyl-coated Tile Ceiling (2' x 4' Tiles and New Grid)	\$19,950.00	to	\$37,422.00	\$26,629.04
Fluorescent Lighting (2' x 4')	\$15,531.87	to	\$25,886.45	\$18,793.56
Paint Door Frames and Trim	\$1,015.00	to	\$1,541.48	\$1,278.50
Paint Walls	\$1,187.20	to	\$1,680.00	\$1,477.35
Quarry Tile Flooring	\$48,972.00	to	\$64,271.08	\$58,154.95
Replace Doors	\$10,683.29	to	\$24,125.50	\$18,542.00
Kydex-paneled Walls	\$3,080.00	to	\$4,017.72	\$3,446.74
Kitchen Renovation Cost Subtota	al \$134,827.86	to	\$198,312.29	\$164,943.35
Kitchen Renovation Cost Per S	F \$18.73	to	\$27.54	\$22.91

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Kitchen Equipment					
		RANGE			AVERAGE
Select Kitchen Equipment		\$149,155.23	to	\$196,705.92	\$172,029.68
	Kitchen Equipment Cost Subtotal	\$149,155.23	to	\$196,705.92	\$172,029.68
	Kitchen Equipment Cost Per SF	\$20.72	to	\$27.32	\$23.89

Prefunction Softgoods Renovation

Assume prefunction areas are approximately 20' to 25'-wide (6,250 SF). Ceiling 12' AFF, coffered.

	RANGE			AVERAGE		
Demolition	\$11,006.14	to	\$14,638.17	\$12,759.79		
Paint Articulated Drywall Ceiling	\$6,625.00	to	\$9,375.00	\$8,244.15		
Carpet and Pad	\$38,526.46	to	\$46,623.01	\$42,280.07		
Paint Doors and Trim (Service Doors and Exits)	\$435.00	to	\$660.63	\$547.93		
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$3,379.60	to	\$5,513.81	\$4,150.08		
Protect / Remove / Reinstall All Light Fixtures	\$880.49	to	\$1,664.13	\$1,283.76		
Vinyl Wallcovering (LY 54")	\$21,892.22	to	\$30,111.02	\$26,102.74		
Window Treatments (with Hardware and Installation)	\$4,808.04	to	\$7,219.27	\$6,013.48		
Seating Groups	\$56,269.24	to	\$73,113.16	\$64,639.23		
Prefunction Softgoods Renovation Cost Subtotal	\$143,822.20	to	\$188,918.20	\$166,021.23		
Prefunction Softgoods Renovation Cost Per SF	\$23.01	to	\$30.23	\$26.56		

Prefunction - Add for a Full Renovatio

Freiunction - Aud for a Full Renovation	_			
	RANGE			AVERAGE
Additional Demolition	\$28,250.00	to	\$37,078.13	\$33,193.75
Artwork, Accessories, and Mirrors (Allowance, Installed)	\$44,122.11	to	\$66,197.07	\$55,159.59
Articulated Drywall Ceiling (New)	\$63,375.00	to	\$85,190.63	\$77,346.79
Decorative Lighting	\$98,436.88	to	\$152,758.86	\$123,801.51
Electrical	\$55,030.71	to	\$73,190.84	\$63,798.94
HVAC	\$33,018.43	to	\$57,782.24	\$45,675.49
Life Safety	\$31,184.07	to	\$40,447.57	\$35,604.87
Architectural Lighting	\$73,374.28	to	\$115,564.49	\$94,652.82
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$20,658.16	to	\$36,210.00	\$28,352.20
Portable Bars	\$15,236.00	to	\$22,872.00	\$19,053.33
Prefunction Full Renovation Additional Cost Subtotal	\$462,685.63	to	\$687,291.83	\$576,639.29
Prefunction Full Renovation Additional Cost Per SF	\$74.03	to	\$109.97	\$92.26

annead Labhta

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Ballroom Softgoods Renovation

Assume a ballroom area of approximately 50' x 90' (4,500 SF) with 3 divisions. Ceiling 18' AFF, coffered.

	RANGE			AVERAGE
Demolition	\$7,924.42	to	\$10,539.48	\$9,187.05
Paint Articulated Drywall Ceiling	\$4,770.00	to	\$7,200.00	\$6,086.09
Carpet and Pad	\$23,471.51	to	\$28,404.17	\$25,758.32
Paint Doors and Trim	\$3,000.00	to	\$3,550.14	\$3,214.03
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$1,332.80	to	\$2,174.46	\$1,636.65
Protect / Remove / Reinstall All Light Fixtures	\$3,521.97	to	\$6,163.44	\$4,872.05
Vinyl Wallcovering (LY 54")	\$12,950.33	to	\$17,812.15	\$15,441.06
Operable Wallcovering	\$2,759.38	to	\$3,653.76	\$3,217.25
Ballroom Softgoods Renovation Cost Subtotal	\$59,730.41	to	\$79,497.61	\$69,412.49
Ballroom Softgoods Renovation Cost Per SF	\$13 27	to	\$17.67	\$15.42

Ballroom - Add for a Full Renovation				
	F	RANGE		AVERAGE
Additional Demolition	\$31,697.69	to	\$37,720.25	\$34,381.43
Artwork, Accessories, and Mirrors (Allowance, Installed)	\$4,415.61	to	\$6,632.17	\$5,524.23
Banquet Chairs	\$63,963.00	to	\$80,649.00	\$72,306.00
Articulated Drywall Ceiling (New)	\$45,630.00	to	\$61,337.25	\$55,689.69
Decorative Lighting	\$303,053.25	to	\$457,277.27	\$379,894.14
Electrical	\$50,188.01	to	\$69,338.69	\$59,565.24
HVAC	\$23,773.27	to	\$41,603.22	\$32,886.35
Life Safety	\$22,452.53	to	\$29,122.25	\$25,635.51
Architectural Lighting	\$52,829.48	to	\$83,206.43	\$68,150.03
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$8,146.88	to	\$14,280.00	\$11,181.15
Operable Walls (New, Manual)	\$60,155.55	to	\$87,435.00	\$69,599.16
Portable Bars	\$15,236.00	to	\$22,872.00	\$19,053.33
Tables (14" x 72", including Meeting Rooms)	\$30,529.20	to	\$33,124.80	\$31,806.40
Tables (72" rounds, including Meeting Rooms)	\$17,716.00	to	\$19,776.00	\$18,746.00
AV Infrastructure: Ceiling speakers and cabling; wall and floor input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; array of ceiling rigging points with CAT 6 AVnet cabling	\$188,387.00	to	\$329,677.25	\$282,580.50
and power (power by others); retractable projection screens. Portable equipment by	÷100,007.00	.0	φ020,077.20	<i>\$202,000.00</i>
others.				
Ballroom Full Renovation Additional Cost Subtotal	\$918,173.46	to	\$1,374,051.58	\$1,166,999.16
Ballroom Full Renovation Additional Cost Per SF	\$204.04	to	\$305.34	\$259.33

UPPER UPSCA

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor. Other assumptions and allowances are listed in each section below.

Meeting Rooms Softgoods Renovation

Assume 7 meeting rooms with areas approximately 30' x 40' each (1,200 SF each; 8,400 SF tot	al). Ceiling 12' AFF, co	offered.		
	R	ANGE		AVERAGE
Demolition	\$14,792.25	to	\$19,673.70	\$17,149.15
Carpet and Pad	\$43,623.10	to	\$52,809.59	\$47,881.24
Paint Articulated Drywall Ceiling	\$8,904.00	to	\$13,440.00	\$11,360.69
Paint Doors and Trim	\$3,150.00	to	\$3,727.65	\$3,374.73
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$5,109.89	to	\$7,791.00	\$5,861.22
Protect / Remove / Reinstall All Light Fixtures	\$4,746.00	to	\$6,644.40	\$5,758.48
Vinyl Wallcovering (LY 54")	\$30,217.44	to	\$41,561.69	\$36,029.13
Window Treatments (with Hardware and Installation)	\$47,196.66	to	\$70,831.04	\$59,013.85
Operable Wallcovering	\$15,247.21	to	\$20,255.72	\$17,811.28
Meeting Rooms Softgoods Renovation Cost Subtotal	\$172,986.54	to	\$236,734.79	\$204,239.78
Meeting Rooms Softgoods Renovation Cost Per SF	\$20.59	to	\$28.18	\$24.31

Meeting Rooms - Add for a Full Renovation

	R	AVERAGE		
Additional Demolition	\$78,892.02	ANGE to	\$91,120.29	\$84,098.90
				. ,
Banquet Chairs	\$119,397.60	to	\$150,544.80	\$134,971.20
Artwork, Accessories, and Mirrors (Installed)	\$27,546.26	to	\$41,371.89	\$34,477.66
Articulated Drywall Ceiling (New)	\$89,224.80	to	\$114,496.20	\$104,763.85
Decorative Lighting	\$33,374.65	to	\$51,602.48	\$42,540.27
Electrical	\$82,836.63	to	\$103,545.78	\$89,877.74
HVAC	\$39,446.01	to	\$93,191.20	\$77,057.78
Life Safety	\$41,911.39	to	\$54,361.54	\$47,852.94
Architectural Lighting	\$113,900.36	to	\$130,467.68	\$121,355.66
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$28,514.08	to	\$49,980.00	\$39,134.02
Millwork Serving Stations	\$35,595.00	to	\$58,138.50	\$48,804.70
Operable Walls (New, Manual)	\$168,435.54	to	\$244,818.00	\$194,877.66
AV Infrastructure: Ceiling speakers and cabling; input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; CAT 6 AVnet cabling; retractable projection screens built into ceiling; ceiling attachments for portable projectors. Portable equipment by others.	\$46,865.00	to	\$83,661.75	\$72,306.00
Meeting Rooms Full Renovation Additional Cost Subtotal	\$905,939.33	to	\$1,267,300.11	\$1,092,118.38
Meeting Rooms Full Renovation Additional Cost Per SF	\$107.85	to	\$150.87	\$130.01

uites. Jar Harris

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Board Room Softgoods Renovation

Assume two, 2-bay board rooms, each approximately 26' x 28' (1,456 SF). Ceiling 12' AFF, coffered.

RA				AVERAGE
Demolition	\$2,563.99	to	\$3,410.11	\$2,972.52
Carpet and Pad	\$7,561.34	to	\$9,153.66	\$8,299.41
Paint Articulated Drywall Ceiling	\$771.68	to	\$1,092.00	\$909.58
Paint Doors and Trim	\$600.00	to	\$710.03	\$638.01
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$963.52	to	\$1,425.60	\$1,119.78
Protect / Remove / Reinstall All Light Fixtures	\$226.00	to	\$474.60	\$366.12
Vinyl Wallcovering (LY 54")	\$6,660.17	to	\$9,160.54	\$7,941.11
Window Treatments (with Hardware and Installation)	\$3,848.08	to	\$5,774.18	\$4,810.79
Executive Chairs	\$18,099.20	to	\$23,593.60	\$20,846.40
Board Room Softgoods Renovation Cost Subtotal	\$41,293.98	to	\$54,794.31	\$47,903.72
Board Room Softgoods Renovation Cost Per SF	\$28.36	to	\$37.63	\$32.90

Board Room - Add for a Full Renovation

Board Room - Add for a Full Renovation					
		RANGE			AVERAGE
Additional Demolition	\$13,674.62	to	\$	515,794.18	\$14,577.14
Artwork, Accessories, and Mirrors (Installed)	\$2,353.68	to		\$3,562.00	\$2,962.81
Articulated Drywall Ceiling (New)	\$15,465.63	to	\$	619,846.01	\$18,159.07
Decorative Lighting	\$4,697.51	to		\$7,989.37	\$6,374.38
Electrical	\$29,615.04	to	\$	37,142.20	\$33,423.86
HVAC	\$6,837.31	to	\$	616,153.14	\$13,356.68
Life Safety	\$7,264.64	to		\$9,422.67	\$8,294.51
Architectural Lighting	\$26,652.68	to	\$	30,529.44	\$28,397.22
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$6,284.74	to	\$	611,016.00	\$8,625.46
Millwork Serving Stations	\$10,170.00	to	\$	616,611.00	\$13,944.20
Board Room Conference Table	\$11,247.60	to	\$	616,861.10	\$14,054.01
AV Infrastructure: Ceiling speakers and cabling; wall and floor input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; array of ceiling rigging points with CAT 6 AVnet cabling and power (power by others); retractable projection screens. Portable equipment by others.	\$ 21,001.70	to	\$ 4	42,160.99	\$ 36,137.55
Board Room Full Renovation Additional Cost Subtotal	\$155,265.15	to	\$2	227,088.10	\$198,306.89
Board Room Full Renovation Additional Cost Per SF	\$106.64	to	+-	\$155.97	\$136.20

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Exercise Facility Softgoods Renovation

Assume a four-bay facility of approximately 28' x 52' (1,456 SF). Ceiling 12' AFF.

RANGE				AVERAGE	
Demolition	\$2,563.99	to	\$3,410.11	\$2,972.52	
Artwork (Installed)	\$743.21	to	\$1,127.98	\$938.25	
Clock	\$62.99	to	\$92.38	\$80.17	
Hamper	\$402.73	to	\$522.21	\$462.47	
Towel Caddy	\$437.75	to	\$569.59	\$503.67	
Sport Flooring	\$21,840.00	to	\$29,120.00	\$25,508.56	
Mirrors	\$2,440.80	to	\$3,707.38	\$3,128.64	
Paint Drywall Ceiling	\$771.68	to	\$1,092.00	\$960.28	
Paint Doors and Trim	\$900.00	to	\$1,065.04	\$957.01	
Remove and Reinstall Exercise Equipment	\$3,521.97	to	\$5,916.90	\$4,740.57	
Vinyl Wallcovering (LY 54")	\$3,311.22	to	\$4,998.98	\$4,177.89	
Window Treatments (with Hardware and Installation)	\$595.34	to	\$902.28	\$748.81	
Exercise Facility Softgoods Renovation Cost Subtotal	\$37,591.68	to	\$52,524.86	\$45,178.83	
Exercise Facility Softgoods Renovation Cost Per SF	\$25.82	to	\$36.07	\$31.03	

Exercise Facility - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$13,674.62	to	\$15,794.18	\$14,577.14
Articulated Drywall Ceiling (New)	\$14,763.84	to	\$18,953.63	\$17,560.74
Exercise Equipment (Installed)	\$84,030.49	to	\$109,245.92	\$96,638.38
Electrical	\$14,358.35	to	\$17,947.94	\$15,578.81
HVAC	\$6,837.31	to	\$16,153.14	\$13,356.68
Life Safety	\$7,264.64	to	\$9,422.67	\$8,294.51
Architectural Lighting	\$19,742.73	to	\$22,614.40	\$21,034.98
Millwork Lockers	\$13,383.47	to	\$16,419.40	\$14,779.58
TVs and Mounts (42", including Programming Allowance)	\$5,676.34	to	\$6,337.82	\$5,997.83
Water Fountain	\$2,113.18	to	\$3,328.26	\$2,726.00
Sound System	\$2,773.55	to	\$6,309.82	\$4,682.67
Exercise Facility Full Renovation Additional Cost Subtotal	\$184,618.51	to	\$242,527.17	\$215,227.31
Exercise Facility Full Renovation Additional Cost Per SF	\$126.80	to	\$166.57	\$147.82

Outdoor Pool

Assume a 30' x 50' (1,500 SF) pool and a 15'-wide deck, approximately 3,300 SF surface.

		RANGE			AVERAGE		
ADA Lift		\$7,910.00	to	\$16,611.00	\$12,136.20		
Pool Furniture		\$50,429.00	to	\$75,643.00	\$63,036.00		
Pool Equipment		\$17,609.83	to	\$28,351.82	\$23,045.39		
Resurface Pool Bottom		\$13,500.00	to	\$33,000.00	\$21,163.22		
Resurface Pool Deck (Kool Deck)		\$26,400.00	to	\$36,300.00	\$29,807.15		
Signage (Life Safety, Pool Rules)		\$1,130.00	to	\$2,966.25	\$2,118.75		
	Outdoor Pool Renovation Cost Subtotal	\$116,978.83	to	\$192,872.07	\$151,306.72		
	Outdoor Pool Renovation Cost Per SF	\$24.37	to	\$40.18	\$31.52		

annea Tablet Lassan . Mildel.

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor Other assumptions and allowances are listed in each section below.

Indoor Pool

Assume a 30' x 50' (1,500 SF) pool and a 12'-wide deck, approximately 2,496 SF surface.

		R	ANGE		AVERAGE
ADA Lift		\$7,910.00	to	\$16,611.00	\$12,136.20
Architectural Lighting		\$61,750.27	to	\$70,732.12	\$65,792.10
Drywall Ceiling (New, from Scaffolding)		\$22,770.00	to	\$27,050.76	\$25,524.02
Paint Doors and Trim		\$600.00	to	\$710.03	\$638.01
Pool Deck Tile		\$27,048.69	to	\$35,974.76	\$31,358.45
Pool Equipment		\$17,609.83	to	\$28,351.82	\$23,045.39
Pool Furniture		\$11,542.28	to	\$17,309.38	\$14,426.17
Pool Pak HVAC		\$113,212.44	to	\$136,884.13	\$124,465.07
Replace Doors (Storefront)		\$1,760.98	to	\$2,588.64	\$2,173.05
Resurface Pool Bottom		\$13,500.00	to	\$33,000.00	\$21,163.22
Wall Tile		\$16,936.42	to	\$29,978.97	\$20,832.86
Decorative Water Feature (Allowance)		\$29,349.71	to	\$48,074.83	\$38,847.28
Signage (Life Safety, Pool Rules)		\$1,130.00	to	\$2,966.25	\$2,118.75
	Indoor Pool Renovation Cost Subtotal	\$325,120.62	to	\$450,232.70	\$382,520.58
	Indoor Pool Renovation Cost Per SF	\$81.36	to	\$112.67	\$95.73

Indoor Pool Renovation Cost Per SF	\$81.36	to	\$1
------------------------------------	---------	----	-----

Outdoor Amenities

		R	ANGE		AVERAGE
Stamped Concrete at Arrivals		\$53,752.96	to	\$68,678.32	\$64,688.43
Outdoor Furniture		\$56,026.72	to	\$84,039.07	\$70,033.06
Fire Pit		\$10,097.84	to	\$16,950.00	\$12,885.57
Outdoor Lighting		\$11,739.88	to	\$36,980.64	\$25,005.95
Patio Landscaping		\$13,500.87	to	\$24,037.41	\$18,895.34
Water Feature		\$76,309.25	to	\$91,835.25	\$83,758.21
Outdoor Audio System		\$7,396.13	to	\$12,943.22	\$10,231.31
(Outdoor Amenities Renovation Cost Subtotal	\$228,823.65	to	\$335,463.91	\$285,497.88

Outdoor Parking

Typically, hotels in this market segment do not have outdoor parking.

Structured Parking

Assume 347 parking spaces, 9' x 18', and 25'-wide aisles.				
	R	ANGE		AVERAGE
Concrete Sealer and Traffic-bearing Membrane	\$329,972.93	to	\$433,089.48	\$379,468.87
Lighting Upgrades	\$20,340.00	to	\$23,730.00	\$21,899.40
Paint Ceilings, Columns, etc.	\$83,372.39	to	\$175,082.02	\$135,063.27
Stripe Spaces	\$5,220.00	to	\$13,224.00	\$8,109.30
Structured Parking Renovation Cost Subtotal	\$438,905.32	to	\$645,125.49	\$544,540.85
Structured Parking Renovation Cost Per Space	\$1,264.86	to	\$1,859.15	\$1,569.28

Landscaping					
		R	ANGE		AVERAGE
Landscaping Allowance		\$70,439.31	to	\$98,615.03	\$84,292.37
	Landscaping Renovation Cost Subtotal	\$70,439.31	to	\$98,615.03	\$84,292.37

UPPER UPSCALE

Prototype Hotel: 192 guestrooms, 25 suites, 7 stories (6 with guestrooms), 31 bays/floor. Other assumptions and allowances are listed in each section below.

Common Additives				
	R	ANGE		AVERAGE
New RFID Key System	\$339.00	to	\$474.60	\$416.97
Elevator Cab Finishes	\$20,544.80	to	\$29,954.32	\$25,220.79
Elevator Modernization				
Traction, per Cab	\$192,299.31	to	\$240,053.64	\$214,563.30
Escalator Modernization	\$352,196.54	to	\$517,728.91	\$434,610.53
Electronic Signage Boards				
Basic System - One Lobby Screen (42" diag.)	\$17,609.83	to	\$25,393.37	\$21,467.55
Additional Lobby / Prefunction Screens	\$5,869.94	to	\$8,464.46	\$7,155.85
Additional Meeting Room Door Screen (18" diag.)	\$8,804.91	to	\$10,970.92	\$9,813.37
Four-Pipe Vertical Fan Coil Unit Direct Replacement with Drywall Repair	\$2,598.75	to	\$5,800.00	\$3,873.07
Laundry Equipment (Direct Equipment Replacement with Access)				
75# Washer	\$23,479.77	to	\$32,049.88	\$27,659.17
125# Dryer	\$35,219.65	to	\$44,376.76	\$39,516.45
Ironer / Folder	\$117,398.85	to	\$133,130.29	\$123,832.30
Porte Cochere - Re-image: Demolish and Replace	\$41,089.60	to	\$80,124.71	\$61,223.50
Guestroom ADA Modifications				
Bathtub Room	\$22,035.00	to	\$39,387.31	\$30,054.71
Roll-in Shower Room	\$23,730.00	to	\$45,200.00	\$33,310.01
Exterior Signage - Monument - New Graphics on Existing Sign	\$17,609.83	to	\$23,421.07	\$20,415.66
Exterior Signage - New Exterior Brand Sign in Existing Location	\$46,959.54	to	\$56,703.64	\$51,373.73
Power-operated, Bi-parting Entrance Doors (Inner and Outer at a Vestibule)	\$27,500.00	to	\$35,640.00	\$32,804.82
Fireplace - Natural Gas with Stone Hearth and Surrounding Wall (Public Area)	\$16,950.00	to	\$28,250.00	\$21,415.00
Add Screening for Buffet in Restaurant	\$11,865.00	to	\$56,500.00	\$38,081.00
Replace Guestroom Entry Door and Hardware	\$882.78	to	\$1,243.00	\$976.36
Replace Guestroom Connecting Doors and Hardware	\$1,630.00	to	\$2,486.00	\$1,927.99
Replace Corridor Service Doors and Hardware	\$1,469.00	to	\$1,898.40	\$1,684.83
Replace Guestroom Closet Door with Pair of Swing Doors and Hardware	\$790.00	to	\$891.00	\$831.86
Replace Guestroom Bath Door with Barn Door and Hardware	\$1,105.00	to	\$1,310.00	\$1,208.37
Incremental Add for LVT in Guestroom Instead of Carpet	\$985.14	to	\$1,673.32	\$1,395.32

annen Lanes



Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor Other assumptions and allowances are listed in each section below.

Guestroom Softgoods Renovation

Assume guestroom area of approximately 17' x 24' and 7' x 10' entry / closet area (578 SF). Ceilings 9' AFF. Painted drywall and coffered.

	R	ANGE		AVERAGE
Demolition	\$630.00	to	\$1,056.59	\$804.79
FF&E Installation	\$262.73	to	\$438.63	\$346.76
Artwork, Mirrors, and Accessories (Installed Package)	\$1,240.68	to	\$1,898.48	\$1,560.37
Full-height Framed Dressing Mirror	\$221.73	to	\$300.34	\$258.45
Decorative Pillow	\$128.13	to	\$166.86	\$147.61
Carpet and Pad	\$1,131.42	to	\$1,324.22	\$1,213.91
Desk Lamp	\$201.88	to	\$260.59	\$231.41
Floor Lamp	\$351.23	to	\$465.56	\$408.22
End Table Lamp	\$675.68	to	\$869.32	\$772.50
Nightstand or Bracket Lamp (2)	\$438.78	to	\$574.74	\$506.76
Welcome Light (in Existing Location)	\$692.68	to	\$915.42	\$812.18
Desk Chair (including Fabric)	\$407.88	to	\$537.66	\$472.77
Lounge Chair (including Fabric)	\$1,858.12	to	\$2,420.50	\$2,138.97
Ottoman (including Fabric)	\$859.02	to	\$1,126.82	\$992.92
Sleeper Sofa (including Fabric)	\$1,834.43	to	\$2,394.75	\$2,114.59
Paint Textured or Drywall Ceiling	\$383.19	to	\$574.78	\$486.16
Paint Trim (Base and Crown)	\$480.36	to	\$763.00	\$677.88
Paint Entry Doors, Closet Doors, Frames, and Grilles	\$340.00	to	\$655.40	\$436.19
Vinyl Wallcovering (LY 54")	\$2,118.61	to	\$2,891.67	\$2,514.44
Window Treatments (Sheer, Blackout, Hardware, Installed)	\$792.07	to	\$1,196.86	\$994.29
Guestroom Softgoods Renovation Cost Per Key	\$15,048.61	to	\$20,832.20	\$17,891.17

Guestroom - Add for a Full Renovation

	Р	ANCE		
		ANGE		AVERAGE
Additional Demolition	\$115.00	to	\$300.00	\$215.60
Casegoods Installation	\$713.00	to	\$869.10	\$791.62
Bedsets (Box Spring, Mattress, and Frame)	\$959.31	to	\$1,237.77	\$1,098.54
Headboard	\$1,387.41	to	\$2,079.57	\$1,733.49
Nightstands	\$1,049.06	to	\$1,378.14	\$1,213.34
Dresser	\$3,994.34	to	\$5,178.84	\$4,586.25
Desk	\$1,359.60	to	\$1,767.48	\$1,563.54
Side Table	\$1,250.42	to	\$1,615.04	\$1,433.07
Coffee Table	\$1,305.01	to	\$1,691.26	\$1,498.31
Credenza	\$2,281.45	to	\$2,965.37	\$2,623.41
Closet Shelf Unit	\$496.55	to	\$657.27	\$571.29
Refrigerator Cabinet / Welcome Center	\$1,710.77	to	\$2,193.77	\$1,951.98
Mini Refrigerator	\$247.20	to	\$267.80	\$257.50
Crown Molding	\$872.00	to	\$1,165.21	\$961.08
Drapery Valance - Painted Wood	\$244.02	to	\$575.25	\$335.30
Wall Base	\$1,507.60	to	\$2,559.29	\$1,984.26
Entry Area Hard Surface Flooring	\$1,582.00	to	\$2,408.60	\$2,032.08
TV and Mount (HD LCD, including Programming Allowance)	\$2,569.34	to	\$2,920.48	\$2,743.20
Guestroom Full Renovation Additional Cost Per Key	\$23,644.07	to	\$31,830.24	\$27,593.84

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor. Other assumptions and allowances are listed in each section below.

Guest Bathroom Softgoods Renovation

Assume guest bathroom area of 10' x 10' (5-fixture). Ceilings 9' AFF. Painted drywall and coffered.

	R	ANGE		AVERAGE
Demolition	\$202.00	to	\$350.00	\$296.61
Artwork (Installed)	\$470.84	to	\$707.92	\$589.88
Lighted Mirror	\$1,409.78	to	\$1,897.62	\$1,642.70
Makeup Mirror	\$240.83	to	\$263.80	\$252.66
Night Light	\$75.00	to	\$100.57	\$85.43
Paint Ceiling	\$53.00	to	\$75.00	\$65.95
Vinyl Wallcovering (LY 54")	\$470.24	to	\$630.17	\$553.87
Paint Door and Trim	\$85.00	to	\$138.31	\$103.94
Regrout Floor Tile	\$160.00	to	\$400.00	\$258.59
Regrout Wall Tile	\$140.00	to	\$350.00	\$226.27
Guest Bathroom Softgoods Renovation Cost Per Key	\$3,306,69	to	\$4,913,39	\$4.075.90

Guest Bathroom - Add for a Full Renovation

	R	ANGE		AVERAGE
Additional Demolition	\$550.00	to	\$956.25	\$733.74
Architectural Lighting	\$364.00	to	\$714.00	\$504.74
Replace Bathroom Door and Hardware	\$880.49	to	\$1,173.99	\$1,040.16
Electrical Upgrades (Add One GFI Outlet)	\$109.00	to	\$200.00	\$156.03
Tub-to-Shower Conversion (New Pan, Tile Surround, Valve, and Shower Head)	\$3,700.00	to	\$4,815.92	\$4,261.58
Shower Valve and Head, Tub Diverter, Tub Drain	\$1,408.79	to	\$1,643.58	\$1,544.15
Tub Surround (Tile)	\$1,358.83	to	\$2,276.95	\$1,725.17
Lavatory	\$704.39	to	\$813.60	\$746.92
Faucet (and Connections)	\$3,323.90	to	\$5,954.32	\$4,379.03
Vanity Top	\$2,343.90	to	\$3,509.52	\$2,931.05
Vanity Base	\$1,539.60	to	\$2,329.10	\$1,936.69
Toilet Accessories	\$410.53	to	\$606.02	\$492.99
Tile Flooring	\$2,054.48	to	\$2,876.27	\$2,321.56
Toilet and Seat	\$646.46	to	\$757.00	\$711.64
Guest Bathroom Full Renovation Additional Cost Per Key	\$19,394.37	to	\$28,626.52	\$23,485.46

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor Other assumptions and allowances are listed in each section below.

Corridors

Per room with each unit 17' long and half of a 6'-wide corridor; 37 bays per floor.

	R	ANGE		AVERAGE
Demolition	\$52.80	to	\$65.12	\$57.10
Artwork (Installed)	\$19.49	to	\$29.02	\$24.26
Carpet and Pad	\$255.06	to	\$324.58	\$290.49
Millwork Base	\$170.95	to	\$251.47	\$192.17
Ceiling-mounted Lighting	\$183.02	to	\$244.22	\$215.76
Sconces	\$309.26	to	\$415.48	\$366.26
Elevator Lobby Furniture (Allowance)	\$81.09	to	\$121.65	\$101.37
Ice Machine	\$198.60	to	\$218.47	\$208.53
Millwork (Allowance for Elevator Lobby)	\$101.14	to	\$192.41	\$152.77
Paint Ceiling	\$21.60	to	\$33.75	\$28.60
Signage Package (Room Numbers, Wayfinding, Complete)	\$226.00	to	\$308.49	\$270.75
Vinyl Wallcovering (LY 54")	\$274.92	to	\$407.37	\$342.90
Window Treatments (with Hardware and Installation)	\$24.39	to	\$36.83	\$30.61
Corridors Renovation Cost Per Key	\$1,918.31	to	\$2,648.85	\$2,281.58

Lobby Softgoods Renovation

Assume a 4,000 SF area. Ceiling 12' AFF, coffered.

	R	ANGE		AVERAGE
Demolition	\$5,635.14	to	\$6,903.05	\$6,308.51
Artwork and Artifacts (Installed)	\$15,176.28	to	\$23,467.85	\$19,404.84
Area Rugs	\$28,381.00	to	\$42,573.52	\$35,476.59
Millwork (Refinish)	\$4,695.95	to	\$5,793.63	\$5,173.77
Millwork Screen Walls (Refinish)	\$10,565.90	to	\$13,682.84	\$11,964.12
Paint Drywall Ceiling	\$3,840.00	to	\$6,000.00	\$5,084.95
Paint Doors and Trim	\$1,125.00	to	\$1,610.88	\$1,369.18
Vinyl Wallcovering (LY 54", 40% Openings)	\$3,718.23	to	\$4,955.54	\$4,351.41
Window Treatments (with Hardware and Installation)	\$7,473.68	to	\$11,220.82	\$9,347.25
Seating Groups	\$50,156.43	to	\$65,280.80	\$57,720.74
Lobby Softgoods Renovation Cost Subtotal	\$130,767.61	to	\$181,488.92	\$156,201.33
Lobby Softgoods Renovation Cost Per SF	\$32.69	to	\$45.37	\$39.05

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor. Other assumptions and allowances are listed in each section below.

Lobby - Add for a Full Renovation

·	R	ANGE		AVERAGE
Additional Demolition	\$46,959.54	to	\$53,252.12	\$49,532.92
Decorative Lighting	\$33,240.84	to	\$47,422.77	\$40,250.39
Electrical	\$63,234.80	to	\$86,092.44	\$74,423.61
Hard Surface Flooring	\$117,398.85	to	\$164,358.38	\$143,829.57
HVAC	\$46,959.54	to	\$64,099.77	\$55,318.34
Life Safety	\$19,957.80	to	\$25,886.45	\$22,787.12
Architectural Lighting	\$70,439.31	to	\$103,545.78	\$86,922.11
Front Desk (New Pods, in Existing Location)	\$63,280.00	to	\$113,000.00	\$89,563.80
Front Desk Equipment	\$14,674.86	to	\$17,627.44	\$16,004.98
Concierge Desk	\$11,273.43	to	\$15,368.00	\$13,373.89
Bell Stand	\$17,451.72	to	\$20,603.50	\$18,725.40
Millwork Running Trim (Stained Hardwood Crown and Base)	\$8,119.08	to	\$10,500.00	\$8,989.16
Millwork Screen Walls (New)	\$52,829.48	to	\$77,659.34	\$65,191.58
Articulated Drywall Ceiling (New)	\$40,560.00	to	\$54,522.00	\$49,501.95
Sound System	\$12,326.88	to	\$25,886.45	\$19,353.20
Drywall Partitions	\$11,016.00	to	\$15,664.14	\$13,921.78
Business Center (Millwork / Finishes / Seating)	\$25,579.97	to	\$39,034.09	\$32,194.83
Lobby Full Renovation Additional Cost Subtotal	\$655,302.09	to	\$934,522.66	\$799,884.60
Lobby Full Renovation Additional Cost Per SF	\$163.83	to	\$233.63	\$199.97

Marketplace / Sundries Shop

Typically, hotels in this market segment do not have marketplaces.

Public Restrooms Softgoods Renovation

Assume four restrooms, totaling 1,920 SF. Each with 5 lavs and 7 fixtures, upgraded. Ceiling 12' AFF, coffered.

	RANGE			
Demolition	\$1,183.38	to	\$1,775.07	\$1,360.89
Artwork and Artifacts (Installed)	\$10,939.12	to	\$16,481.04	\$13,729.94
Backlit Mirror	\$6,880.00	to	\$9,270.00	\$8,020.00
Paint Drywall Ceiling	\$3,052.80	to	\$4,320.00	\$3,856.18
Paint Doors and Trim	\$580.00	to	\$880.84	\$730.57
Vinyl Wallcovering (LY 54")	\$6,843.20	to	\$9,156.47	\$8,027.18
Decorative Vanity Lighting	\$5,498.30	to	\$7,986.40	\$6,749.62
Public Restrooms Softgoods Renovation Cost Subtotal	\$34,976.80	to	\$49,869.83	\$42,474.38
Public Restrooms Softgoods Renovation Cost Per SF	\$18.22	to	\$25.97	\$22.12

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor Other assumptions and allowances are listed in each section below.

Public Restrooms - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$18,032.46	to	\$23,667.61	\$20,737.33
Toilet Partitions	\$58,534.00	to	\$79,385.10	\$67,852.03
Toilet Accessories	\$8,716.86	to	\$11,622.49	\$9,930.25
Replace Doors	\$9,989.20	to	\$14,061.72	\$11,553.92
Toilets / Urinals	\$13,510.00	to	\$25,200.00	\$19,585.94
Architectural Lighting	\$18,934.09	to	\$23,667.61	\$20,543.48
Tile Flooring	\$56,351.45	to	\$78,892.02	\$63,677.13
Tile Walls	\$23,667.61	to	\$32,120.32	\$26,440.10
Motion-sensing Flush Valves	\$17,080.00	to	\$22,288.00	\$18,830.47
Motion-sensing Faucets	\$12,000.00	to	\$18,908.00	\$15,825.84
Vanity Top, Sinks	\$16,380.00	to	\$33,900.00	\$23,415.69
Millwork Vanity Base	\$18,772.00	to	\$26,103.00	\$22,672.95
Public Restrooms Full Renovation Additional Cost Subtotal	\$271,967.67	to	\$389,815.87	\$321,065.14
Public Restrooms Full Renovation Additional Cost Per SF	\$141.65	to	\$203.03	\$167.22

Restaurant Softgoods Renovation

Assume a 120-seat restaurant area of approximately 32' x 100' (3,200 SF). Ceiling 12' AFF, coffered.

	R	ANGE		AVERAGE
Demolition	\$7,513.53	to	\$9,467.04	\$8,430.18
Artwork (Installed)	\$10,235.50	to	\$15,406.49	\$12,842.17
Carpet and Pad (80% of Floor Area)	\$17,008.20	to	\$20,178.11	\$18,490.51
Millwork Buffet, Host Station (Refinish)	\$7,043.93	to	\$10,354.58	\$8,692.21
Millwork Screen Walls (Refinish)	\$5,282.95	to	\$8,752.08	\$7,045.10
Millwork Running Trim (Refinish - Hardwood Crown, Chair, and Base)	\$1,376.54	to	\$2,098.80	\$1,578.94
Reupholster Banquettes	\$17,826.50	to	\$27,118.50	\$22,472.50
Paint Drywall Ceiling	\$3,072.00	to	\$4,800.00	\$4,067.96
Paint Doors and Trim	\$870.00	to	\$1,321.27	\$1,095.85
Vinyl Wallcovering (LY 54", 40% Openings)	\$5,645.64	to	\$7,554.09	\$6,622.42
Window Treatments (with Hardware and Installation)	\$4,438.27	to	\$6,656.89	\$5,547.58
Dining Chairs (With Arms)	\$58,075.00	to	\$74,639.00	\$66,357.00
Dining Chairs (No Arms)	\$10,463.60	to	\$13,736.00	\$12,093.07
Restaurant Softgoods Renovation Cost Subtotal	\$148,851.66	to	\$202,082.86	\$175,335.49
Restaurant Softgoods Renovation Cost Per SF	\$46.52	to	\$63.15	\$54.79
Restaurant Softgoods Renovation Cost Per Seat	\$1,240.43	to	\$1,684.02	\$1,461.13

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor. Other assumptions and allowances are listed in each section below.

Restaurant - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$15,027.05	to	\$19,723.01	\$17,281.11
Banquettes	\$6,815.09	to	\$11,634.66	\$9,159.79
Decorative Lighting	\$24,196.94	to	\$37,067.43	\$30,832.76
Architectural Lighting	\$46,959.54	to	\$65,085.92	\$55,844.28
Electrical	\$31,556.81	to	\$39,446.01	\$34,239.14
Hard Surface Flooring (20% of Floor Area)	\$18,783.82	to	\$26,297.34	\$21,225.71
HVAC	\$24,418.96	to	\$33,810.87	\$28,053.63
Life Safety	\$15,966.24	to	\$20,709.16	\$18,229.69
Millwork, Host Station (New, in Existing Location)	\$12,482.40	to	\$20,668.48	\$15,183.70
Millwork Screen Walls (New)	\$41,089.60	to	\$49,307.52	\$44,787.66
Millwork Running Trim (Hardwood Crown, Chair, and Base)	\$8,993.79	to	\$13,464.00	\$11,237.47
Articulated Drywall Ceiling (New)	\$32,448.00	to	\$43,617.60	\$39,601.56
Sound System	\$6,379.16	to	\$14,512.59	\$10,770.15
Tables	\$18,910.80	to	\$24,555.20	\$21,726.13
Drywall Partitions	\$17,107.20	to	\$22,581.50	\$20,314.76
Restaurant Full Renovation Additional Cost Subtotal	\$321,135.39	to	\$442,481.28	\$378,487.54
Restaurant Full Renovation Additional Cost Per SF	\$100.35	to	\$138.28	\$118.28
Restaurant Full Renovation Additional Cost Per Seat	\$2,676.13	to	\$3,687.34	\$3,154.06

Bar / Lounge Softgoods Renovation

Assume a 52-seat bar / lounge area of approximately 30' x 40' (1,200 SF). Ceiling 12' AFF, coffered.

	R	ANGE		AVERAGE
Demolition	\$2,817.57	to	\$3,550.14	\$3,161.32
Artwork, Accessories, and Mirrors (Installed)	\$11,126.64	to	\$16,706.73	\$13,919.34
Bar / Back Bar (Refinish)	\$2,054.48	to	\$3,020.09	\$2,535.23
Carpet and Pad (60%)	\$4,806.44	to	\$5,730.64	\$5,230.93
Millwork Running Trim (Refinish)	\$747.60	to	\$1,245.83	\$940.49
Paint Drywall Ceiling	\$576.00	to	\$900.00	\$762.74
Paint Doors and Trim	\$145.00	to	\$220.21	\$182.64
Vinyl Wallcovering (LY 54")	\$4,989.83	to	\$6,676.60	\$5,853.15
Reupholster Banquettes	\$9,671.76	to	\$14,661.16	\$12,153.67
Dining Chairs (With Arms)	\$25,553.00	to	\$32,841.16	\$29,197.08
Dining Chairs (No Arms)	\$9,417.24	to	\$12,362.40	\$10,883.76
Bar Stools	\$6,211.50	to	\$9,423.30	\$7,817.40
Seating Group	\$18,873.25	to	\$24,547.45	\$21,710.36
Bar / Lounge Softgoods Renovation Cost Subtotal	\$96,990.31	to	\$131,885.70	\$114,348.09
Bar / Lounge Softgoods Renovation Cost Per SF	\$80.83	to	\$109.90	\$95.29
Bar / Lounge Softgoods Renovation Cost Per Seat	\$1,865.20	to	\$2,536.26	\$2,199.00

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor Other assumptions and allowances are listed in each section below.

Bar / Lounge - Add for a Full Renovation

	RANGE			AVERAGE
Additional Demolition	\$8,136.00	to	\$11,390.40	\$9,803.88
Bar Die and Top (New in Existing Location)	\$56,500.00	to	\$88,987.50	\$74,297.50
Back Bar (New in Existing Location)	\$56,500.00	to	\$88,987.50	\$74,297.50
Bar Equipment	\$46,959.54	to	\$64,099.77	\$55,318.34
Articulated Drywall Ceiling (New)	\$12,168.00	to	\$16,356.60	\$14,850.58
Banquettes	\$7,000.00	to	\$25,425.00	\$12,966.53
Communal Table Chairs	\$11,991.67	to	\$17,987.51	\$14,993.92
Communal Table	\$17,643.84	to	\$28,567.56	\$23,424.36
Decorative Lighting	\$10,467.04	to	\$16,460.22	\$13,664.38
Electrical	\$11,833.80	to	\$14,792.25	\$12,839.68
Hard Surface Flooring (40%)	\$14,087.86	to	\$19,723.01	\$15,919.28
HVAC	\$9,157.11	to	\$12,679.08	\$10,520.11
Life Safety	\$5,987.34	to	\$7,765.93	\$6,836.13
Architectural Lighting	\$17,609.83	to	\$24,407.22	\$20,941.61
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$4,769.43	to	\$7,356.30	\$6,242.95
Other Seating and Tables (Allowance)	\$6,039.80	to	\$9,053.64	\$7,546.72
Sound System	\$9,568.74	to	\$21,768.88	\$16,155.22
TVs - 50" LCD HD	\$2,044.56	to	\$2,339.36	\$2,183.39
Tables	\$6,954.56	to	\$7,663.20	\$7,308.88
Drywall Partitions	\$15,120.00	to	\$19,958.40	\$17,954.96
Bar / Lounge Full Renovation Additional Cost Subtotal	\$330,539.13	to	\$505,769.33	\$418,065.92
Bar / Lounge Full Renovation Additional Cost Per SF	\$275.45	to	\$421.47	\$348.39
Bar / Lounge Full Renovation Additional Cost Per Seat	\$6,356.52	to	\$9,726.33	\$8,039.73

Kitchen

Assume a kitchen area of approximately 60' x 70' (4,200 SF), including banquet prep and upgraded and increased equipment.

	1 1 1 10	'	,		
		R	ANGE		AVERAGE
Selective Demolition		\$34,408.50	to	\$39,368.07	\$36,621.20
Vinyl-coated Tile Ceiling (2' x 4' Tiles and New Grid)		\$19,950.00	to	\$37,422.00	\$26,629.04
Fluorescent Lighting (2' x 4')		\$15,531.87	to	\$25,886.45	\$18,793.56
Paint Door Frames and Trim		\$1,305.00	to	\$1,981.90	\$1,643.78
Paint Walls		\$1,187.20	to	\$1,680.00	\$1,477.35
Quarry Tile Flooring		\$48,972.00	to	\$64,271.08	\$58,154.95
Replace Doors		\$13,735.66	to	\$31,018.50	\$23,839.71
Kydex-paneled Walls		\$3,080.00	to	\$4,017.72	\$3,446.74
Kitchen Renov	ation Cost Subtotal	\$138,170.23	to	\$205,645.72	\$170,606.34
Kitchen Reno	vation Cost Per SF	\$19.19	to	\$28.56	\$23.70

Kitchen Equipment					
		RANGE			AVERAGE
Select Kitchen Equipment		\$164,070.76	to	\$216,376.51	\$189,232.65
	Kitchen Equipment Cost Subtotal	\$164,070.76	to	\$216,376.51	\$189,232.65
	Kitchen Equipment Cost Per SF	\$22.79	to	\$30.05	\$26.28

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor. Other assumptions and allowances are listed in each section below.

Prefunction Softgoods Renovation

Assume prefunction areas are approximately 15' to 20'-wide (3,100 SF). Ceiling 12' AFF, double coffered.

	R	RANGE		
Demolition	\$7,278.73	to	\$9,171.20	\$8,166.73
Paint Articulated Drywall Ceiling	\$3,286.00	to	\$4,650.00	\$4,089.10
Carpet and Pad	\$22,712.00	to	\$25,251.61	\$24,076.15
Paint Doors and Trim (Service Doors and Exits)	\$435.00	to	\$660.63	\$547.93
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$2,189.60	to	\$3,572.33	\$2,688.79
Protect / Remove / Reinstall All Light Fixtures	\$1,760.98	to	\$3,081.72	\$2,436.03
Vinyl Wallcovering (LY 54")	\$19,116.67	to	\$25,577.08	\$22,424.22
Window Treatments (with Hardware and Installation)	\$5,152.06	to	\$7,722.94	\$6,437.16
Seating Groups	\$54,695.70	to	\$71,157.75	\$62,927.25
Prefunction Softgoods Renovation Cost Subtotal	\$116,626.74	to	\$150,845.26	\$133,793.35
Prefunction Softgoods Renovation Cost Per SF	\$37.62	to	\$48.66	\$43.16

Prefunction - Add for a Full Renovation

	RANGE			AVERAGE	
Additional Demolition	\$24,521.00	to	\$30,344.74	\$27,437.25	
Artwork, Accessories, and Mirrors (Allowance, Installed)	\$61,518.81	to	\$92,310.66	\$76,914.22	
Articulated Drywall Ceiling (New)	\$31,434.00	to	\$42,254.55	\$38,364.01	
Decorative Lighting	\$126,807.95	to	\$193,381.55	\$159,009.43	
Electrical	\$27,295.23	to	\$36,302.66	\$31,644.27	
HVAC	\$36,393.64	to	\$49,677.32	\$42,871.71	
Life Safety	\$15,467.30	to	\$20,062.00	\$17,660.01	
Architectural Lighting	\$54,590.46	to	\$80,247.98	\$67,364.63	
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$13,384.16	to	\$23,460.00	\$18,369.03	
Portable Bars	\$15,236.00	to	\$22,872.00	\$19,053.33	
Prefunction Full Renovation Additional Cost Subtotal	\$406,648.55	to	\$590,913.45	\$498,687.90	
Prefunction Full Renovation Additional Cost Per SF	\$131.18	to	\$190.62	\$160.87	

Ballroom Softgoods Renovation

Assume a ballroom area of approximately 60' x 80' (4,800 SF) with 3 divisions. Ceiling 18' AFF, double coffered.

	RANGE			AVERAGE	
Demolition	\$11,270.29	to	\$14,200.56	\$12,645.26	
Paint Articulated Drywall Ceiling	\$5,088.00	to	\$7,680.00	\$6,491.82	
Carpet and Pad	\$27,562.60	to	\$33,083.99	\$30,132.82	
Paint Doors and Trim	\$3,000.00	to	\$3,550.14	\$3,214.03	
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$1,332.80	to	\$2,174.46	\$1,636.65	
Protect / Remove / Reinstall All Light Fixtures	\$3,521.97	to	\$6,163.44	\$4,872.05	
Vinyl Wallcovering (LY 54")	\$14,960.87	to	\$20,016.84	\$17,549.39	
Operable Wallcovering	\$3,597.86	to	\$4,698.85	\$4,161.17	
Ballroom Softgoods Renovation Cost Subtotal	\$70,334.38	to	\$91,568.30	\$80,703.20	
Ballroom Softgoods Renovation Cost Per SF	\$14.65	to	\$19.08	\$16.81	

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor Other assumptions and allowances are listed in each section below.

Ballroom - Add for a Full Renovation				
	R	RANGE		
Additional Demolition	\$33,810.87	to	\$40,234.93	\$36,673.52
Artwork, Accessories, and Mirrors (Allowance, Installed)	\$5,644.40	to	\$8,466.60	\$7,055.84
Banquet Chairs	\$84,048.00	to	\$110,745.60	\$97,561.60
Articulated Drywall Ceiling (New)	\$48,672.00	to	\$65,426.40	\$59,402.34
Decorative Lighting	\$375,850.41	to	\$562,080.10	\$469,078.08
Electrical	\$70,439.31	to	\$97,628.88	\$83,766.42
HVAC	\$56,351.45	to	\$76,919.72	\$66,382.00
Life Safety	\$23,949.36	to	\$31,063.73	\$27,344.54
Architectural Lighting	\$84,527.17	to	\$124,254.94	\$104,306.53
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$8,146.88	to	\$14,280.00	\$11,181.15
Operable Walls (New, Manual)	\$72,186.66	to	\$104,922.00	\$83,519.00
Portable Bars	\$15,236.00	to	\$22,872.00	\$19,053.33
Tables (14" x 72", including Meeting Rooms)	\$48,667.50	to	\$52,066.50	\$50,367.00
Tables (72" rounds, including Meeting Rooms)	\$24,349.20	to	\$27,006.60	\$25,667.60
AV Infrastructure: Ceiling speakers and cabling; wall and floor input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; array of ceiling rigging points with CAT 6 AVnet cabling and power (power by others); retractable projection screens. Portable equipment by others.	\$249,749.25	to	\$437,060.93	\$374,624.39
Ballroom Full Renovation Additional Cost Subtotal	\$1,201,628.45	to	\$1,775,028.94	\$1,515,983.35
Ballroom Full Renovation Additional Cost Per SF	\$250.34	to	\$369.80	\$315.83

Meeting Rooms Softgoods Renovation

Assume 6 meeting rooms with areas approximately 20' x 25' each (500 SF each; 3,000 SF total). Ceiling 12' AFF, double coffered.

	RANGE			AVERAGE	
Demolition	\$7,043.93	to	\$8,875.35	\$7,903.29	
Carpet and Pad	\$17,151.08	to	\$20,590.62	\$18,751.17	
Paint Articulated Drywall Ceiling	\$3,180.00	to	\$4,800.00	\$4,057.39	
Paint Doors and Trim	\$3,150.00	to	\$3,727.65	\$3,374.73	
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$2,815.65	to	\$4,293.00	\$3,229.65	
Protect / Remove / Reinstall All Light Fixtures	\$5,424.00	to	\$8,542.80	\$7,200.36	
Vinyl Wallcovering (LY 54")	\$19,235.40	to	\$25,735.94	\$22,563.50	
Window Treatments (with Hardware and Installation)	\$47,103.96	to	\$70,631.22	\$58,868.62	
Operable Wallcovering	\$9,476.97	to	\$12,412.94	\$10,979.13	
Meeting Rooms Softgoods Renovation Cost Subtotal	\$114,580.99	to	\$159,609.52	\$136,927.84	
Meeting Rooms Softgoods Renovation Cost Per SF	\$38.19	to	\$53.20	\$45.64	

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor. Other assumptions and allowances are listed in each section below.

Meeting Rooms - Add for a Full Renovation					
	RANGE			AVERAGE	
Additional Demolition	\$35,219.65	to	\$39,939.09	\$37,149.69	
Banquet Chairs	\$49,440.00	to	\$66,126.00	\$57,886.00	
Artwork, Accessories, and Mirrors (Installed)	\$33,956.40	to	\$50,979.60	\$42,484.96	
Articulated Drywall Ceiling (New)	\$35,061.00	to	\$40,891.50	\$39,178.46	
Decorative Lighting	\$39,149.35	to	\$63,003.21	\$51,220.98	
Electrical	\$29,584.51	to	\$36,980.64	\$32,099.19	
HVAC	\$22,892.77	to	\$31,697.69	\$26,300.28	
Life Safety	\$14,968.35	to	\$19,414.83	\$17,090.34	
Architectural Lighting	\$44,024.57	to	\$61,018.05	\$52,354.02	
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$15,711.84	to	\$27,540.00	\$21,563.65	
Millwork Serving Stations	\$49,923.86	to	\$66,565.15	\$57,893.19	
Operable Walls (New, Manual)	\$96,248.88	to	\$139,896.00	\$111,358.66	
AV Infrastructure: Ceiling speakers and cabling; input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; CAT 6 AVnet cabling; retractable projection screens built into ceiling; ceiling attachments for portable projectors. Portable equipment by others.	\$55,795.10	to	\$97,632.67	\$83,692.65	
Meeting Rooms Full Renovation Additional Cost Subtotal	\$521,976.28	to	\$741,684.42	\$630,272.05	
Meeting Rooms Full Renovation Additional Cost Per SF	\$173.99	to	\$247.23	\$210.09	

Board Room Softgoods Renovation

Assume two, 2-bay board rooms, each approximately 26' x 28' (1,456 SF) with upgraded finishes. Ceiling 12' AFF, double coffered.

	RANGE			AVERAGE
Demolition	\$3,418.65	to	\$4,307.50	\$3,835.73
Carpet and Pad	\$8,323.99	to	\$9,993.31	\$9,100.57
Paint Articulated Drywall Ceiling	\$771.68	to	\$1,092.00	\$909.58
Paint Doors and Trim	\$600.00	to	\$710.03	\$638.01
Millwork Running Trim (Refinish - Stained Hardwood Crown, Chair, and Base)	\$963.52	to	\$1,425.60	\$1,119.78
Protect / Remove / Reinstall All Light Fixtures	\$226.00	to	\$474.60	\$366.12
Vinyl Wallcovering (LY 54")	\$7,694.16	to	\$10,294.38	\$9,025.40
Window Treatments (with Hardware and Installation)	\$5,873.06	to	\$8,829.16	\$7,350.77
Executive Chairs	\$25,654.00	to	\$33,128.00	\$29,384.27
Board Room Softgoods Renovation Cost Subtotal	\$53,525.06	to	\$70,254.58	\$61,730.21
Board Room Softgoods Renovation Cost Per SF	\$36.76	to	\$48.25	\$42.40

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor Other assumptions and allowances are listed in each section below.

Board Room - Add for a Full Renovation					
	RANGE			AVERAGE	
Additional Demolition	\$17,093.27	to	\$19,383.77	\$18,029.98	
Artwork, Accessories, and Mirrors (Installed)	\$2,967.56	to	\$4,466.34	\$3,722.26	
Articulated Drywall Ceiling (New)	\$17,016.27	to	\$19,846.01	\$19,014.61	
Decorative Lighting	\$7,033.34	to	\$11,941.70	\$9,533.89	
Electrical	\$29,615.04	to	\$37,142.20	\$33,423.86	
HVAC	\$11,110.63	to	\$15,383.94	\$12,764.40	
Life Safety	\$7,264.64	to	\$9,422.67	\$8,294.51	
Architectural Lighting	\$28,844.90	to	\$39,979.03	\$34,302.35	
Millwork Running Trim (Stained Hardwood Crown, Chair, and Base)	\$6,284.74	to	\$11,016.00	\$8,625.46	
Millwork Serving Stations	\$39,939.09	to	\$53,252.12	\$46,314.55	
Board Room Conference Table	\$15,701.32	to	\$22,960.00	\$19,428.29	
AV Infrastructure: Ceiling speakers and cabling; wall and floor input/output plates and cabling; control plates and cabling and processors; rack in AV room with audio processing and amplification; array of ceiling rigging points with CAT 6 AVnet cabling and power (power by others); retractable projection screens. Portable equipment by others.	\$24,091.70	to	\$42,160.99	\$36,137.55	
Board Room Full Renovation Additional Cost Subtotal	\$206,962.49	to	\$286,954.76	\$249,591.72	
Board Room Full Renovation Additional Cost Per SF	\$142.14	to	\$197.08	\$171.42	

Exercise Facility Softgoods Renovation

Assume an exercise facility of approximately 28' x 65' (1,820 SF). Ceiling 12' AFF.

	RANGE			
Demolition	\$4,273.32	to	\$5,384.38	\$4,794.66
Artwork (Installed)	\$1,987.00	to	\$2,985.20	\$2,491.07
Clock	\$183.58	to	\$259.61	\$226.53
Hamper	\$933.18	to	\$1,211.28	\$1,071.89
Towel Caddy	\$1,009.40	to	\$1,306.04	\$1,157.72
Sport Flooring	\$27,300.00	to	\$36,400.00	\$31,885.70
Mirrors	\$2,440.80	to	\$3,707.38	\$3,128.64
Paint Drywall Ceiling	\$964.60	to	\$1,365.00	\$1,200.35
Paint Doors and Trim	\$900.00	to	\$1,065.04	\$957.01
Remove and Reinstall Exercise Equipment	\$5,282.95	to	\$7,765.93	\$6,519.16
Vinyl Wallcovering (LY 54")	\$4,443.52	to	\$6,466.68	\$5,481.59
Window Treatments (with Hardware and Installation)	\$640.66	to	\$954.81	\$797.56
Exercise Facility Softgoods Renovation Cost Subtotal	\$50,359.00	to	\$68,871.36	\$59,711.87
Exercise Facility Softgoods Renovation Cost Per SF	\$27.67	to	\$37.84	\$32.81

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor. Other assumptions and allowances are listed in each section below.

Exercise Facility - Add for a Full Renovation					
	R	ANGE		AVERAGE	
Additional Demolition	\$21,366.59	to	\$24,229.71	\$22,537.48	
Articulated Drywall Ceiling (New)	\$18,454.80	to	\$23,692.03	\$21,950.92	
Exercise Equipment (Installed)	\$88,973.46	to	\$115,661.79	\$102,317.80	
Electrical	\$17,947.94	to	\$22,434.92	\$19,473.51	
HVAC	\$13,888.28	to	\$19,229.93	\$15,955.50	
Life Safety	\$9,080.80	to	\$11,778.33	\$10,368.14	
Architectural Lighting	\$26,708.24	to	\$37,017.62	\$31,761.44	
Millwork Lockers	\$26,414.74	to	\$30,693.93	\$28,256.73	
TVs and Mounts (42", including Programming Allowance)	\$5,676.34	to	\$6,337.82	\$5,997.83	
Water Fountain	\$3,521.97	to	\$5,177.29	\$4,346.11	
Sound System	\$3,189.58	to	\$7,256.29	\$5,385.07	
Exercise Facility Full Renovation Additional Cost Subtotal	\$235,222.73	to	\$303,509.67	\$268,350.52	
Exercise Facility Full Renovation Additional Cost Per SF	\$129.24	to	\$166.76	\$147.45	

Outdoor Pool

Assume a 50' x 75' (3,750 SF) pool and a 20'-wide deck, approximately 6,600 SF surface.

		R	ANGE		AVERAGE
ADA Lift		\$7,910.00	to	\$16,611.00	\$12,136.20
Pool Furniture		\$52,779.00	to	\$79,168.00	\$65,973.67
Pool Equipment		\$23,479.77	to	\$36,980.64	\$30,288.90
Resurface Pool Bottom		\$33,750.00	to	\$82,500.00	\$52,908.05
Resurface Pool Deck (Kool Deck)		\$52,800.00	to	\$72,600.00	\$59,614.31
Signage (Life Safety, Pool Rules)		\$1,130.00	to	\$2,966.25	\$2,118.75
	Outdoor Pool Renovation Cost Subtotal	\$171,848.77	to	\$290,825.89	\$223,039.88
	Outdoor Pool Renovation Cost Per SF	\$16.60	to	\$28.10	\$21.55

Indoor Pool

Assume a 50' x 75' (3,750 SF) pool and a 12'-wide deck, approximately 3,576 SF surface.

		R	ANGE		AVERAGE
ADA Lift		\$7,910.00	to	\$16,611.00	\$12,136.20
Architectural Lighting		\$132,205.77	to	\$183,237.20	\$157,219.11
Drywall Ceiling (New, from Scaffolding)		\$45,045.00	to	\$53,513.46	\$50,493.17
Paint Doors and Trim		\$900.00	to	\$1,065.04	\$957.01
Pool Deck Tile		\$66,212.95	to	\$92,698.13	\$74,820.63
Pool Equipment		\$23,479.77	to	\$36,980.64	\$30,288.90
Pool Furniture		\$20,108.09	to	\$30,172.74	\$25,140.25
Pool Pak HVAC		\$223,963.74	to	\$270,792.52	\$246,224.38
Replace Doors (Storefront)		\$1,760.98	to	\$2,588.64	\$2,173.05
Resurface Pool Bottom		\$33,750.00	to	\$82,500.00	\$52,908.05
Wall Tile		\$61,930.24	to	\$84,048.18	\$69,184.92
Decorative Water Feature (Allowance)		\$41,089.60	to	\$75,193.96	\$58,593.76
Signage (Life Safety, Pool Rules)		\$1,130.00	to	\$2,966.25	\$2,118.75
	Indoor Pool Renovation Cost Subtotal	\$659,486.14	to	\$932,367.77	\$782,258.19
	Indoor Pool Renovation Cost Per SF	\$90.02	to	\$127.27	\$106.78

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor Other assumptions and allowances are listed in each section below.

Outdoor Amenities					
		R	ANGE		AVERAGE
Stone Paving at Arrivals		\$72,493.79	to	\$106,759.58	\$85,080.53
Outdoor Furniture		\$61,302.96	to	\$91,953.43	\$76,628.36
Fire Pit		\$13,500.00	to	\$35,595.00	\$23,379.00
Outdoor Lighting		\$21,718.79	to	\$47,458.48	\$35,084.64
Patio Landscaping		\$22,892.77	to	\$33,898.92	\$28,381.17
Water Feature		\$88,049.13	to	\$104,162.13	\$95,615.49
Outdoor Audio System		\$12,326.88	to	\$25,886.45	\$19,353.20
	Outdoor Amenities Renovation Cost Subtotal	\$292 284 32	to	\$445 713 98	\$363 522 40

Outdoor Parking

Typically, hotels in this market segment do not have outdoor parking.

Structured Parking

Assume 352 parking spaces, 9' x 18', and 25'-wide aisles.

	R	ANGE		AVERAGE
Concrete Sealer and Traffic-bearing Membrane	\$361,505.79	to	\$474,476.36	\$415,731.66
Lighting Upgrades	\$20,340.00	to	\$23,730.00	\$21,899.40
Paint Ceilings, Columns, etc.	\$91,339.62	to	\$191,813.20	\$147,970.18
Stripe Spaces	\$5,280.00	to	\$13,376.00	\$8,202.51
Structured Parking Renovation Cost Subtotal	\$478,465.41	to	\$703,395.55	\$593,803.76
Structured Parking Renovation Cost Per Space	\$1,359.28	to	\$1,998.28	\$1,686.94

		RANGE			RANGE AVERA	AVERAGE
Landscaping Allowance		\$105,658.96	to	\$147,922.55	\$126,438.56	
	Landscaping Renovation Cost Subtotal	\$105,658.96	to	\$147,922.55	\$126,438.56	

Prototype Hotel: 200 guestrooms, 20 suites, 6 stories (5 with guestrooms), 37 bays/floor. Other assumptions and allowances are listed in each section below.

Common Additives				
	R/	ANGE		AVERAGE
New RFID Key System	\$339.00	to	\$474.60	\$416.97
Elevator Cab Finishes	\$29,349.71	to	\$38,213.32	\$33,587.81
Elevator Modernization				
Traction, per Cab	\$173,985.09	to	\$215,375.23	\$193,160.08
Escalator Modernization	\$352,196.54	to	\$517,728.91	\$434,610.53
Electronic Signage Boards				
Basic System - One Lobby Screen (42" diag.)	\$29,349.71	to	\$48,074.83	\$38,847.28
Additional Lobby / Prefunction Screens	\$9,783.24	to	\$16,024.94	\$12,949.09
Additional Meeting Room Door Screen (18" diag.)	\$8,804.91	to	\$10,970.92	\$9,813.37
Four-Pipe Vertical Fan Coil Unit Direct Replacement with Drywall Repair	\$2,598.75	to	\$5,800.00	\$3,873.07
Laundry Equipment (Direct Equipment Replacement with Access)				
75# Washer	\$23,479.77	to	\$32,049.88	\$27,659.17
125# Dryer	\$35,219.65	to	\$44,376.76	\$39,516.45
Ironer / Folder	\$117,398.85	to	\$133,130.29	\$123,832.30
Porte Cochere - Re-image: Demolish and Replace	\$58,699.42	to	\$130,664.91	\$96,102.69
Guestroom ADA Modifications				
Bathtub Room	\$36,276.24	to	\$48,485.72	\$40,519.04
Roll-in Shower Room	\$42,375.00	to	\$54,240.00	\$46,431.70
Exterior Signage - Monument - New Graphics on Existing Sign	\$17,609.83	to	\$23,421.07	\$20,415.66
Exterior Signage - New Exterior Brand Sign in Existing Location	\$46,959.54	to	\$56,703.64	\$51,373.73
Power-operated, Bi-parting Entrance Doors (Inner and Outer at a Vestibule)	\$27,500.00	to	\$35,640.00	\$32,804.82
Fireplace - Natural Gas with Stone Hearth and Surrounding Wall (Public Area)	\$19,775.00	to	\$29,662.50	\$25,368.50
Replace Guestroom Entry Door and Hardware	\$1,130.00	to	\$1,720.43	\$1,462.79
Replace Guestroom Connecting Doors and Hardware	\$1,900.00	to	\$3,277.00	\$2,327.59
Replace Corridor Service Doors and Hardware	\$1,582.00	to	\$2,195.03	\$1,919.31
Replace Guestroom Closet Door with Pair of Swing Doors and Hardware	\$790.00	to	\$891.00	\$831.86
Replace Guestroom Bath Door with Barn Door and Hardware	\$1,105.00	to	\$1,310.00	\$1,208.37




INDUSTRY INSIGHTS



Determining the budget for a project is just one step in the renovation process. It is also important to develop a thorough and achievable project schedule to help make the project a reality. We have put together the following conceptual schedules to serve as a guide when creating your own project schedule.

- Full-service Hotel
- Select Service Hotel Prototype Design
- Select Service Hotel Custom Design

These schedules are not intended to be one size fits all. Each project is unique. However, these durations can assist you and be a check point when developing your project-specific schedule.




FULL SERVICE HOTEL Sample Renovation Schedule



SELECT SERVICE HOTEL Sample Renovation Schedule | Prototype Design



SELECT SERVICE HOTEL Sample Renovation Schedule | Custom Design



FREIGHT AND WAREHOUSE PRICING

Provided by Audit Logistics

ESTIMATED PERCENTAGES FOR FREIGHT AND WAREHOUSING

ECONOMY				EXTENDED STAY			
	Freight	Warehousing		Freight	Warehousing		
Guestrooms	10.50%	6.50%	Guestrooms	10.50%	5.50%		
Public Space	n/a	n/a	Public Space	14.75%	n/a		
MIDSCALE				UPSCALE			
	Freight	Warehousing		Freight	Warehousing		
Guestrooms	8.00%	4.00%	Guestrooms	6.25%	3.50%		
Public Space	10.50%	n/a	Public Space	8.50%	3.50%		
	UPPER UPSCAI	LE		LUXURY			
	Freight	Warehousing		Freight	Warehousing		
Guestrooms	5.50%	3.00%	Guestrooms	5.00%	3.00%		
Guestioonis		3.00%	Public Space	6.75%	3.00%		

These percentages are intended to provide a baseline idea for these costs when completing your budget. There are several considerations that can influence this percentage including:


- 1. Vendor Selection
 - Factory FOB
 - Country of Origin
 - Packing Techniques
- 2. Schedule and Lead Times
 - Expedited Shipping
 - Storage Duration
- 3. Fuel Surcharges
- 4. Final FF&E Budget
- 5. Duty and Tariff Charges
- 6. Special Project Dispensations
- 7. Natural Disasters, Acts of War, or Terror

FREIGHT AND WAREHOUSE PRICING


Provided by Audit Logistics

VARIABLES

FUEL PRICES | Fuel prices are experiencing a decline based on COVID-19 and reduced consumption globally. Once travel begins to increase, prices are anticipated to increase back to pre-COVID-19 prices.



RECORD DECREASE IN INTERNATIONAL SHIPPING | Asia-Pacific containers are holding steady during COVID-19 as shipping companies reduce capacity. International air-freight costs are at an all-time high as airlines decrease capacity.



ALTERNATE PORTS OF ENTRY | Utilization of alternative ports for casegoods entering the U.S. can reduce costs significantly. Lead time for transit from Asia increases approximately 2 weeks to travel through Panama Canal. CO2 emissions and fuel consumption are reduced as well as the risk of damage.




WAREHOUSE RATES | Warehouse rates will remain stable, but could see up to a 20% decrease in some markets due to COVID-19 business disruption.






SPONSOR RECOGNITION



SPONSOR RECOGNITION

Contact Pages





BOULDER I CHICAGO I DALLAS I LONDON

World Leader in F&E and OS&E Purchasing

www.benjaminwest.com 303.530.3885

AUDIT | LOGISTICS

Freight, Warehouse & Installation Management

Cross Logistics off Your List

You have a whole project to worry about. It's our job to make sure it stays on schedule.

One Call and it's Done: 303.951.9000

You have a lot on your plate. It's our job to get you the things you need.



Contact Pages



SELECT SERVICE



FULL SERVICE





- ☆ Pre Construction / Project Development Services
- 🛠 Turn-Key Interior & Exterior Renovations
- 😒 SUSTAINovation® Renovations
- ☆ Complete Project Oversight from Concept to Completion
- 🛠 Maintenance, Repair & Emergency Services

Our Clients Expect the Best and We Deliver!

www.ADDASTAR.COM 732.751.2522



From grand public spaces to intimate, beautifully appointed guestrooms, Continental works behind the scenes to make sure each project goes fluidly. Since 2003, our team has mastered a variety of hotel renovation projects—equally at home handling high impact public spaces, luxury suites and guestrooms, and renovated corridors and meeting spaces around the country.

We love what we do and it shows. Call Continental Contractors today to find out how consistent quality and versatility will help you delight your guests.


Annapolis, MD 410.263.6514 tel

Redondo Beach, CA 410.374.7526 tel

continentalcontractors.com

SPONSOR RECOGNITION

Contact Pages





Reliance Construction is a bold and innovative company dedicated solely to hotel and restaurant renovations. We do awesome work that we are extremely proud of, yet it's the relationships we build that humble us the most.

Over the years , we have developed extraordinary relationships with architects, designers, vendors, and subcontractors and we consider each one an essential part of the Reliance Team. Together, we form a finely tuned orchestra that constructs masterpieces — at least we think so.

From the renovation of a single suite to multi-million dollar public space, guestrooms. restaurants, and entertainment venues, Reliance Construction ensures that your renovation experience is as seamless as possible.



GLOSSARY OF TERMS

GLOSSARY OF TERMS

provided by Audit Logistics

AMS Automated Manifest System | An application that expedites the clearance of cargo for the subsequent release of containers when imported to U.S.A. through electronic submission of cargo manifests in lieu of bulk paper manifests.

Americans with Disabilities Act of 2010 (ADA) | The Americans with Disabilities Act of 1990 established the clear and comprehensive prohibition of discrimination on the basis of disability. Hotels in the United States are required to adhere to the ADAAG (The Americans with Disabilities Act Accessibility Guidelines), which outline the minimum standards to make places of lodging accessible to those of disabilities. In 2010, the Department of Justice issued revised regulations that all hotels must comply with since March 15, 2012.

Arrival Notice | An advisory that the carrier or forwarder sends to the consignee advising of goods coming forward for delivery. Pertinent information such as bill of lading number, container number, total charges due from consignee, etc. are included and sent to consignee prior to vessel arrival. This is done gratuitously by the carrier or forwarder to ensure smooth delivery, but there is no obligation by the carrier or forwarder to do so. The responsibility to monitor the transit and present himself to take timely delivery still rests with the consignee.

Automated Manifest System (AMS) | An application that expedites the clearance of cargo for the subsequent release of containers when imported to the U.S. through electronic submission of cargo manifests in lieu of bulk paper manifests.

Average Daily Rate (ADR) | The average daily rate charged by a hotel for one room for one day; calculated by dividing the total room revenue by the actual rooms occupied.

Awkward Cargo | Cargo of irregular size that can either be containerized (packaged in container) or non-containerized (without equipment associated with) during transportation. It requires prior approval on a case-by-case basis before confirmation of booking. **Axle Load** | Maximum load permitted to be carried on each axle of a motor vehicle.

A8A Manifest | A form issued by a licensed Customs broker which allows CCRA to monitor in-bound shipments as they move through Canada.

A/E Fees | Architecture and Engineering fees for a project that are part of the soft costs of a project budget



Bay | A term used to describe an area that is defined by the building's structural system. Each structural bay forms the basic unit size for a single guestroom.

Berth | The place beside a pier, quay, or wharf where a vessel can be loaded or unloaded.

Block Train | Railcars grouped in a train by destination so that segments (blocks) can be uncoupled and routed to different destinations as the train moves through various junctions. This eliminates the need to break up a train and sort individual railcars at each junction.

Bonded Carrier | A carrier licensed by U.S. Customs to carry Customs-controlled merchandise between Customs points.

Bonded Warehouse | A warehouse authorized by Customs for storage of goods on which payment of duties is deferred until the goods are removed.

Booking | Arrangement with a steamship company for the acceptance and artage of freight.

Booking Number | A reference number for bookings registered with a carrier. It should be unique without duplication for a three-year period.

Box | Common term for an ocean-going freight container.

Brand | The trade name of a hotel. Most major hotel companies have groups of hotel brands, each brand targeting a different industry segment. (e.g. Parent company Marriott owns many hotel brands: Fairfield Inn, Courtyard, TownePlace Suites, etc.)

Broker | An individual, partnership, or corporation that arranges transportation service for client companies.

Break-bulk Cargo | Goods shipped loose in the vessel hold and not in a container.

Broken Stowage | The spare volume of a container of the cargo hold of a vessel where no cargo is stowed. It is a reflection of the bad stowage of the container or the vessel.

Budget | An itemized forecast of the expenses expected for a renovation or construction project. A complete budget should contain all construction and installation costs, FF&E costs, systems costs, professional fees, operating supplies and equipment costs, pre-opening expenses, freight, tax, warehousing, land costs, and a contingency amount.

Bulk Carriers | Vessels carrying dry, liquid, grain, not packaged, bundled, or bottled cargo and loaded without marks and number or count.

Bull Rings | Cargo-securing devices mounted in the floor of containers which allow lashing and securing of cargoes.

Bunker Adjustment Factor (BAF)/Bunker Surcharge (BSC) | Surcharges assessed by the carrier to freight rates to reflect current cost of bunker.

Bunker | Heavy oil used as fuel for ocean vessels.

С —

Canada Customs and Revenue Agency (CCRA) | Canadian government Customs authority.

Capital or Capitalized Expense (CapEx) | Capital expenditures for this study are broadly defined as all improvements made to the physical building of a hotel that would be capitalized as opposed to expensed for accounting purposes.

Cargo Manifest | A manifest that lists only cargo, without freight and charges.

Carrier | Any individual, company or corporation engaged in transporting cargoes.

Carriers Owned Containers (COC) | The containers used for the transportation of cargoes belonging to the property of the carriers.

Casegoods / Hardgoods | Hard furniture such as dressers, chests, nightstands, headboards, tables, etc.

C-corporation | A business that is a completely separate entity from its owners, unlike a partnership. C-corporations are taxed under Subsection C of the Internal Revenue Code. Most major companies are treated as C-corporations for Federal tax purposes.

Cells | The construction system employed in container vessels that permits containers to be stowed in a vertical line, with each container supporting the one above it inside the cargo hold.

Cellular Vessel | A vessel designed with internal ribbing to permit the support of stacked containers. See "Containership."

Certificate of Origin | Document certifying the country of origin of goods, which is normally issued or signed by the relevant government department, Chamber of Commerce, or embassy of the exporting country.

CFR | A pricing term indicating that the cost of the goods and freight charges are included in the quoted price.

CFS/CFS | A kind of cargo movement by container. Delivered loose at origin point with vanning by carrier, devanned by carrier at destination, and picked up loose at destination

Chassis | A wheeled flat-bed constructed to accommodate containers moved over the road. Also termed as "Trailers."

Closing | The published deadline for export cargo or containers to be accepted for a sailing of the carrier. CY closing is applicable to FCLs and CFS closing is applicable to LCLs. Normally, CFS closing is around 24 hours ahead of CY closing, depending on the complexities of export Customs clearance formalities at the country. See "Late-Come." **Connecting Carrier Agreement (CCA)** | An agreement of freight rates for connections between feeder ports and the ports of call of vessels.

Consolidated Cargo | Cargo containing shipments of two or more shippers, usually shipped by a firm called a consolidator. The consolidator takes advantage of lower FCL rates, and savings are passed on to shippers.

Consolidation | The combination of many small shipments into one container.

Consolidator | A person or firm performing a consolidation service of small lots of cargo for shippers.

Consortium | A group of carriers pooling resources, normally container vessels, in a trade lane to maximize their resources efficiently.

Construction Management | A construction delivery method in which the Construction Manager solicits bids from and holds all contracts with the individual subcontractors that are performing the construction work on a project. A Construction Manager generally works either for a flat fee or for a percentage of the total construction cost.

Container | A van-type body that can be relatively easily interchanged between trucks, trains, and ships.

Container Freight Station (CFS) | Consolidation depots where parcels of cargo are grouped and loaded into containers. Alternatively, inbound cargo in a container are devanned for deliveries to consignees as LCLs.

Container Load Plan (CLP) | A document prepared to show all details of cargo loaded in a container, e.g. weight (individual and total), measurement, markings, shippers, consignees, the origin and destination of goods, and location of cargo within the container. A Container Load Plan is either prepared by the cargo consolidator or the shipper that ships its cargo on FCL terms.

Container Number | The unique identification of a container.

Container Seal Number | A number embossed on high-security seals for closing up containers which will serve identification purposes.

Container Size | The length of a container i.e. 20', 40' and 45' (feet).

Containership | An ocean vessel specifically designed to carry ocean cargo containers. It is fitted with vertical cells for maximum capacity.

Container Terminal | A facility which allows container vessels to berth alongside for the operations of loading and unloading of containers. Shippers deliver their export containers to the Container Terminal awaiting for loading onto container vessels whilst consignees at ports take delivery of containers from the Container Terminal after they are unloaded from the container vessels.

Container Type | Containers are classified under different types, e.g. dry cargo, reefer, open top, flat-rack, open-side, etc.

Container Yard (CY) | A facility inside or outside the Container Terminal that accepts laden export containers from shippers or laden import containers for delivery to consignees.

Contingency | Part of the budget that is reserved for unforeseen conditions. Commonly calculated as a percentage of total project cost, but can also be a set amount.

Controlled Atmosphere (CA) | An atmosphere in which oxygen, carbon dioxide, and nitrogen concentrations are regulated, as are tempurature and humidity.

Cost and Freight (C&F) A term of trading in which the buyer of the goods pays an amount that covers the cost of the goods plus the cost of transporting the goods from origin to the port of discharge or final destination.

Cost, Insurance, and Freight (CIF) A term of trading in which the buyer of the goods pays for the cost of the goods, the cost of transporting the goods from origin to the port of discharge or final destination, and the insurance premium for a maritime insurance policy for the value of the order.

Cost Per Key | The total renovation cost for the hotel divided by the number of "keys" (or rooms) in the hotel. Different owners and consultants may calculate this in different ways.

Cost Per Square Foot | The total renovation cost for the hotel divided by the Gross Square Footage (GSF) of the hotel.

Cube the Shipment | Measure the total cubic feet of the shipment.

Currency Adjustment Factor (CAF) | An ancillary charge on ocean freight to compensate for exchange rate fluctuations.

Customs Bonded Warehouse | A publicly - or privately - owned warehouse where dutiable goods are stored pending payment of duty or removal under bond. The storage or delivery of goods are under the supervision of customs officers, and if the warehouse is privately-owned, the keeper has to enter into a bond as indemnity in respect of the goods deposited, which may not be delivered without a release from Customs.

Customs Broker | A private business that provides documentation and entry preparation services required by CCRA and U.S. Customs on behalf of an importer/ exporter of record. Hired by an importer to carry out Customs-related responsibilities and covered by power of attorney to act on behalf of the importer/exporter of record.

Customs House | A government office where import duties, etc. on foreign shipments are handled.

Customs House Broker | An individual or firm licensed to enter and clear goods through Customs.

Customs Self Assessment (CSA) | A joint Canada/ U.S. border initiative aimed at speeding up the Customs process on low-risk shipments.

Customs-Trade Partnership Against Terrorism (C-TPAT) | A joint government and trade community initiative in developing, enhancing, and maintaining effective security processes throughout the global supply chain.

Customs Valuation | The determination of the value imported goods for the purpose of collecting ad valorem duties.

Cut-off Time | Latest possible time the cargo of container may be delivered to the vessel or designated point. See "Closing."

Cwt. | Hundredweight (100 pounds in the U.S., 112 pounds in the U.K.).

CY/CFS | Cargo loaded in a full container by a shipper at origin, delivered to a CFS facility at destination, and then devanned by the carrier for loose pickup.

CY/CY | Cargo loaded by the shipper in a full container at origin and delivered to the carrier's terminal at destination for pickup intact by consignee.

D_____

Dangerous and Hazardous (D&H) | See "Dangerous Goods."

Dangerous Goods | The term used by I.M.C.O. for hazardous materials that are capable of posing a significant risk to health, safety, or property while being transported.

Deadweight (D.W.) | The number of tons of cargo, stores, and bunker fuel a ship can carry and transport. See "Deadweight Tonnage."

Deadweight Tonnage (D/W) | The number of total weight tons of cargo, stores, and bunker fuel that a vessel can carry and transport. It is the difference between the number of tons of water a vessel displaces "light" and the number of tons it displaces when submerged to "load line."

Dedicated Unit Train | A unit train operated by various railroads for exclusive usage.

Delivered Duty Paid (DDP) | In DDP, the shipper clears the goods for export and is responsible for making them available to the buyer at the named place of destination, cleared for import, and paid duty and tax.

Delivered Duty Unpaid (DDU) | In DDU, the shipper clears the goods for export and is responsible for making them available to the buyer at the named place of destination, not cleared for import.

Delivery Order | A document authorizing delivery to a nominated party of cargo in the care of a third party. The document is issued by a carrier or a forwarder on surrender of a bill of lading and then used by the merchant to transfer title by endorsement.

Destination Delivery Charge (DDC) | A charge assessed by the carrier for the handling of a full container at destinations. The term is more commonly used in the U.S. trade.

Detention (Demurrage) | Charges raised by the carrier or the forwarder for detaining a container/trailer at customer premises for a period longer than that provided in the tariff of the carrier or the forwarder.

Devanning | The removal of cargo from a container. Also known as unstuffing, unloading, or stripping.

Differential Rate | An amount added to or deducted from the base rate to make a rate to or from some other point or via another route.

Dock Receipt | A document used to acknowledge receipt of cargo or container at a CFS, a CY, or a Container Terminal. When delivery of an expert shipment is completed, the operator's agent in exchange for the ocean or house of bill of lading.

Door-to-Door | Through transportation of a container and its cargo from consignor's premises to consignee's premises.

Double-deck Load | A second tier of cargo placed on top of the first tier.

Double Stack Train (DST) | Rail or train capable of carrying two 40' containers, one on top of the other.

Drayage | Charge made for local hauling by dray or truck; road transportation between the nearest ocean port or railway terminal and the stuffing/destuffing place.

Dry Cargo | Cargo that does not require temperature control.

Dry-Bulk Container | A container constructed to carry grain, powder, and other free-flowing solids in bulk.

Dunnage | Lumber or other material used to brace materials in carrier's equipment or containers.

Dwell Time | Expressed in terms of number of days that a container changed from one status to another, e.g. from inbound load to empty available to outbound load. The shorter the dwell time, the more efficient the container utilization will be.

F

Empty Depot | A container yard used for the storage of empty containers.

Ex Works | An INCOTERMS term of sale in which the buyer is responsible for taking delivery of the goods at the premises of the factory. Also known as "F.C.A."

Export Declaration | A government document permitting designated goods to be shipped out of the country.

FCA | Free Carrier. See "Ex-Works."

FCL/FCL | See "CY/CY."

FCL/LCL | See "CY/CFS."

Federal Maritime Commission (FMC) | U.S. government agency responsible for the regulation of all maritime activities.

FF&E (Furniture, Fixtures, & Equipment) | Pieces of movable furniture, fixtures, or other equipment that have no permanent connection to the structure of a building or utilities.

Final Destination | The place at which the carrier or the forwarder actually turns over the container or cargo to the consignee of its agent. It is the end of liability of carriers or forwarders.

Flash Point | A temperature at which certain flammable cargo will trigger and spontaneously ignite. It is an IMCO standard information requirement for dangerous goods.

F.O.B. Destination | Changes the location where title and risk pass. Under this arrangement, title and risk remain with the seller until they have delivered the freight to the delivery location specified in the contract.

F.O.B. Origin | Title and risk pass to the buyer at the moment of the seller's delivery to the carrier. The parties may agree to have title and risk pass at a different time or to allocate freight charges by a written agreement.

Force Majeure | Force of nature. Accidents or incidents caused by the forces of nature, which are beyond the power of people to control.

Foreign Exchange Controls | Government restrictions on the use of currency, bank drafts, or other payment types to regulate imports, exports, and trade balances.

Forty Foot (40') Equivalent Unit (FEU) | Commonly describes a 40-foot container or two TEUs.

Free Along Side (FAS) | A basis of pricing meaning the price of goods alongside a transport vessel at a specified location. The buyer is responsible for loading the goods onto the transport vessel and paying all of the cost of shipping beyond that location.

Free and Secure Trade (FAST) | A joint Canada/U.S. border security agreement, of which C-TPAT and PIP are the main initiatives.

Free In and Out (FIO) | A term used in ship-chartering whereby the owner of the ship is not responsible for any charges incurred in the ports of loading or unloading.

Free On Board (FOB) | The seller agrees to deliver merchandise, free of all transportation expense, to the place specified by the contract. Once delivery is complete, the title to all the goods and the risk of damage becomes the buyer's.

Free Storage Period (FSP) | A carrier offers a period of time, normally three to five days, at destinations whereby imported containers or cargo are allowed to be taken for delivery by consignees free of any storage charge. After the FSP, there will be an overtime storage charge or demurrage levied by the carriers to the consignee. When bulk shipments are involved, the carriers are prepared to negotiate a longer FSP with the consignees.

Freight | (a) The price paid to the carrier for the transportation of goods or merchandise by sea or air from one place to another. (b) Also used to denote goods that are in the process of being transported from one place to another.

Freight All Kind (FAK) | A system whereby freight is charged per container, irrespective of the nature of the cargo, and not according to a tariff.

Freight Collect | The freight and charges agreed upon by the shipper and carrier are payable at the destination.

Freight Forwarder | A freight forwarder combines less-than-truckload (LTL) or less-than-carload (LCL) shipments into carload or truckload lots. Freight forwarders are designated as common carriers. They also issue bills of lading and accept responsibility for cargo. The term may also refer to the company that fills railroad trains with trailers.

Freight Prepaid | Freight and charges are required to be paid by a shipper before an original bill of lading is released.

Fuel Adjustment Factor (FAF) | An ancillary charge on ocean freight shipments to account for fluctuations in fuel costs.

Full Berth Terms (FBT) | Indicates that the cost of loading and discharge is included in the steamship rate quoted. Ship owner pays these.

Full Container Load (FCL) | An arrangement whereby the shipper packs cargo into a container provided by the carrier or the forwarder before.

Functional Currency | The currency of the primary economic environment of an entity. For ODFL, this is U.S. dollars.



General Agreement on Tariff and Trade (GATT) | An international multi-lateral agreement embodying a code of practice for fair trading in international commerce.

General Average | An unwritten, non-statutory, international maritime law that is universally recognized and applied. It is founded on the principle that vessel and goods are parties to the same venture and share exposure to the same perils, which may require sacrifice or the incurring of extraordinary expense on the part of one for the benefit of the whole venture. It is an arrangement that will be applied when the vessel encounters serious accidents caused by force majeure.

G.R.I. | General Rate Increase.

Gross Tonnage | Applies to vessels, not to cargo. Determined by dividing by 100 the contents, in cubic feet, of the vessel's closed-in spaces.

Gross Weight | Entire weight of goods, packaging, and container, ready for shipment.

Н

Hague Rules | These rules, set by the 1924 International Convention on Carriage of Goods by Sea, govern liability for loss or damage to goods carried by sea under a bill of lading.

Hague-Visby Rules | 1968 Revision of Hague Rules.

Hamburg Rules | A new set of rules that radically alters the liability that shipowners have to bear for loss or damage of goods in the courts of those nations where the rules apply, adopted in March 1978 at an international conference in Hamburg.

Harmonized Commodity Description and Coding A multi-purpose international goods-System classifications for manufacturers. transporters, exporters, importers, customs officials, statisticians, and others in classifying goods moving in international trade under a single commodity code. Developed under the auspices of the Customs Cooperations Council (CCC), an international customs organization in Brussels, this code is a hierarchically-structured product nomenclature containing approximately 5,000 headings and subheadings describing the articles moving in international trade. It is organized into 99 chapters arranged in 22 sections. Sections encompass an industry (e.g. Section XI, Textiles and Textile Articles), and chapters encompass the various materials and products of the industry (e.g. Chapter 50, Silk; Chapter 55, Manmade Staple Fibres; Chapter 57, Carpets). The basic code contains four-digit headings and six-digit subheadings. (The U.S. will add digits for tariff and statistical purposes.) In the U.S., duty rates will be at the eight-digit level; statistical suffixes will be at the ten-digit level.

Haulier | The participating carrier responsible for drayage of containers.

Heavy Lift | Articles too heavy to be lifted by a ship's tackle.

Heavy-Lift Charge | A charge made for lifting articles too heavy to be lifted by a ship's tackle.

High Cube (HC or HQ) | Any container that exceeds 8'-6" (102") in height, usually 9'-6".

Hold | It is the part of the ship below deck where the cargo is stored.

House Bill of Lading (HB/L) | Bill of lading issued by a forwarder or an NVOCC operator

House-to-House (H/H) | See "CY/CY"

House-to-Pier (H/P) | See "CY/CFS"

Hull Underwriter | The person with whom the ship hull, machinery apparel, and tackle is insured.

HVAC | Heating, Ventilation, and Air Conditioning system

Import License | A document required and issued by some national governments authorizing the importation of goods into their individual countries.

Import Permit | Usually required for items that might affect public health, morals, animal life, vegetation, etc. Examples include foodstuffs, feedstuffs, pharmaceuticals (human and veterinary), medical equipment, seeds, plants, and various written material (including tapes, cassettes, movies, TV tapes, or TV movies). In some countries, an import permit is the same as an import license.

In Bond | A term indicating that an imported shipment was not cleared by Customs at the border and is moving under a surety bond.

In Transit | In passage from one place to another.

Inbound | Inward bound. Direction of vessel or cargo going to port of discharge or final destination.

Incentive Fees | Management fees that are contingent upon achieving certain pre-defined levels of profitability.

Incoterms | A set of uniform rules codifying the interpretation of trade terms defining the rights and obligations of both buyer and seller in an international transaction, thereby enabling an otherwise complex basis of a sale contract to be accomplished in three letters. Incoterms are drafted by the International Chamber of Commerce.

Inland Clearance Depot | A CFS with Customs clearance facilities.

Insulated Container | A container insulated on the walls, roof, floor, and doors to reduce the effect of external temperatures on the cargo.

Insulated Tank Container | The frame of a container constructed to hold one or more thermally insulated tanks for liquids.

Integrated Project Delivery (IPD) | A collaborative system where the design team, contractor, and purchasing agent are all retained for the project at the beginning to create efficiencies and manage tight schedules.

Interchange | Transfer of a container from one party to another.

Interior Points Intermodal (IPI) | A term used by ocean carriers to describe door-to-door delivery service.

Intermodal | Pertaining to transportation involving more than one form of carrier: truck, ship, and rail.

Intermodal Transport | Moving ocean freight containers by various transportation modes. The fact that the containers are of the same size and have common handling characteristics permits them to be transferred from truck to railroad to air carrier to ocean carrier.

International Maritime Consultative Organization (IMCO) | A forum in which most major maritime nations participate and through which recommendations for the carriage of dangerous goods, bulk commodities, and maritime regulations become internationally acceptable.

International Maritime Dangerous Goods (IMDG) Code | The IMCO recommendations for the carriage of dangerous goods by sea.

International Organization for Standardization (ISO) | ISO is a worldwide federation of national standards bodies from some 130 countries, one from each country. It is a non-governmental organization established in 1947 to promote the development of standardization facilitating international trade. ISO's work results in international agreements, which are published as International Standards.

Invoice | Documentation supplying Customs with the type of goods, quantity, price of each type, and terms of sale. The type of invoice required is determined by the shipment's value.

Keel | The main center-line structural member, running fore and aft along the bottom of a ship, sometimes referred to as the backbone.

Key | A term used to describe a single sellable guestroom. It may be composed of one or more structural bays. In order to qualify as a "key," it must have at least one bed and one bathroom, consisting of at least one toilet, sink, and tub or shower.

Knot | A unit of speed. The term "knot" means velocity in nautical miles per hour whether of a vessel or current. One nautical mile is roughly equivalent to 1.15 statute miles or 1.85 kilometers.

Lashing | Support for cargoes inside a container or a cargo hold to ensure they are secured and will not be subject to rolling during the voyage from origin to destination.

Late-Come | A term used in the liner industry when extensions are being given to the shippers against the official CY or CFS closing date and time, which carriers publish to the trade.

LCL/FCL | See "CY/CFS."

LCL/LCL | See "CY/CFS."

Less than Container Load (LCL) | Cargo in quantity less than required for the application of a container load rate.

Letter of Indemnity | Guarantee from the shipper or consignee to indemnify carriers or forwarders for costs and/or loss, if any, in order to obtain favorable action by carriers or forwarders. It is customary practice for carriers and forwarders to demand letters of indemnity from consignees for taking delivery of cargo without surrendering a bill of lading that has been delayed or is lost.

Lien | A legal claim upon goods for the satisfaction of some debt or duty.

Lift-On/Lift-Off (LO-LO) | A container ship onto which containers are lifted by crane.

Lighter | An open or covered barge towed by a tugboat and used mainly in harbors and inland waterways.

Lighterage | Refers to the carriage of cargo by lighter and the charge assessed therefor.

Liner | Vessel plying a regular trade/defined route against a published sailing schedule.

Liner Terms | Freight includes the cost of loading onto and discharging from the vessel.

Lloyd's Registry | An organization maintained for the surveying and classing of ships so that insurance underwriters and others may know the quality and condition of the vessels offered for insurance or employment.

Load Factor | Percent of loaded containers against total capacity of vessel or allocation.

Locking Bar | Device that secures container doors at top and bottom.

Long Ton | 2,240 pounds.

Longshoreman | Workers employed in the terminals or quays to load and unload ships. They are also known as "stevedores."

Loose | Without packing.

Low-Bed | A trailer or semi-trailer with no sides and with the floor of the unit close to the ground.

Luxury Hotel | A hotel that offers the highest level of service, facilities, guest amenities, and design and often includes special features for guests such as a spa, tennis courts, or golf course.

M ------

Manifest | A document that lists in detail all the bills of lading issued by a vessel or its agent or master, i.e. a detailed summary of the total cargo or containers loaded in a vessel. Used principally for customs purposes, it is also called a Bill of Lading.

Maquiladoras | Duty-free (for U.S. import) manufacturing plants located in Mexico.

Marine Insurance | Broadly, insurance covering loss or damage of goods at sea. Marine insurance typically compensates the owner of merchandise for losses sustained from fire, shipwreck, piracy, and various other causes but excludes losses that can be legally recovered.

Marks and Numbers | Markings placed on packages for export for identification purposes, generally a triangle, square, circle, diamond, or cross with letters and/or numbers and port discharge. They are of important use before containerization.

Master Bill of Lading (MB/L) | See "Ocean Bill of Lading."

Master Lease | Master Lease is one form of a shortterm lease, which refers to the leasing of the containers by carriers from those leasing companies.

Master Lease Leasing Cost | Master lease leasing cost includes container rental, depot lift-on/life-off charge, on/off hire drayage, drop-off charge, off-hire repair cost, etc. Due to off-hire quota limitation, the average on-hire period is around 73 days for 20'GP and 40'GP, and 102 days for 40'HQ.

Mate's Receipt | A receipt signed by a mate of the vessel, acknowledging receipt of cargo by the vessel. The individual in possession of the mate's receipt is entitled to the bill of lading, which in due course is issued in exchange for that receipt.

Maximum Payload | Maximum cargo that can be loaded into a container either by weight or volume.

Maximum Rate | The highest freight rate permitted by a regulatory body to apply between points.

Measurement Ton | One cubic meter. One of the alternative bases of Freight Tariff.

Microbridge | A land bridge movement in which cargo originating from/destined to an inland point is railed or trucked to/from the water port for a shipment to/from a foreign country. The carrier is responsible for cargo and costs from origin to destination. Also known as I.P.I. or Through Service.

Mini-Bridge | Cargo moving from/to an inland destination on one bill of lading from/to a foreign port through two U.S. ports.

Mini Landbridge (MLB) | An intermodal system for transporting containers from/to a foreign country by water to/from a U.S. ocean port other than the arrival port, by rail, at through rates and documents.

Minimum Charge | The lowest charge that can be assessed to transport a shipment.

MT (M/T) | (a) Metric Ton or Cubic Meter; (b) Empty container; (c) Multimodal Transport

Ν

Negotiable Bill of Lading | Original bill of lading endorsed by shipper that is used for negotiating with banks.

Negotiating Bank | A bank named in the credit; examines the documents and certifies to the issuing bank that the terms are complied with.

Net Tonnage | A vessel's gross tonnage minus deductions of space occupied by accommodation for crew, by machinery, for navigation, and by the engine room and fuel. A vessel's net tonnage expresses the space available for passengers and cargo.

Net Operating Income (NOI) | Income after management fees and fixed charges (i.e. rent, property, and other taxes and insurance) but before replacement reserves and does not include items such as interest, depreciation, amortization, and income taxes. Income after reserves is now referred to as Adjusted Net Operating Income (but still does not include interest, depreciation, amortization, and income taxes).

Net Weight | Weight of the goods alone without any immediate wrappings, e.g. the weight of the contents of a tin can without the weight of the can. Also called actual net weight.

Non-negotiable Bill of Lading | Copy of the original bill of lading, which cannot be negotiated with banks.

Non-vessel Owning / Operating Common Carrier (NVOCC) | (a) A cargo consolidator of small shipments in ocean trade, generally soliciting business and arranging for or performing containerization functions at the port. (b) A carrier issuing a bill of lading for carriage of goods on a vessel that he neither owns nor operates. **North American Free Trade Agreement (NAFTA)** | The joint Canada, Mexico, and United States treaty to reduce tariffs and trade barriers to promote crossborder economic activity.

Ocean Bill of Lading (Ocean B/L) | A bill of lading issued by the ocean-going carriers.

Ocean Route | The all-water transportation portion of a route.

O.C.P. Rate | Overland Common Point rates are generally lower than local tariff rates. They were established by the U.S. West coast steamship companies in conjunction with railroads serving the western U.S. ports so that cargo originating from or destined to the American Midwest and East would be competitive with all-water rates via the U.S. Atlantic and Gulf ports. O.C.P. rates are also applicable to eastern Canada.

On Board | Cargoes or containers landed onto the cargo hold or the cells of carriers.

On Board Bill of Lading | A Bill of Lading in which a carrier acknowledges that cargo have been placed on board a certain vessel. The on-board date on the bills of lading is the date on which liabilities of the carrier start.

On Deck | A special stowage instruction to confine that the cargo stowage must be on deck rather than under deck.

One-Way Lease | The lease of containers that covers the outbound voyage only, after which the containers are returned to the lease holder at or near the agreed destination.

Open-Top Container | A container fitted with a solid removable roof or with a tarpaulin roof that can be loaded or unloaded from the top.

Operator | The entity that manages the day-today functions of the hotel and offers the guestrooms for sale. Some hotel owners are also operators of their hotels, others contract with hotel management companies to operate hotels on their behalf.

Origin Receiving Charge (O.R.C.) | A terminal handling charge levied at ports of loading.

OS&E | Operating Supplies and Equipment.

Overheight Cargo | Cargo that exceeds 9-1/2 feet in height. They normally have to be stowed in an opentop container.

P _____

Packing List | A document provided by the shipper detailing the packaging of the goods, including their weight and measurement, assortment, etc.

Participating Carrier (Tariff) | A carrier that is a party, under concurrence, to a tariff issued by another transportation line or by a tariff's publishing agent.

Partners in Protection (PIP) | A CCRA initiative designed to enlist the cooperation of private industry in efforts to enhance border security and increase awareness of customs compliance issues.

Perishable Cargo | Cargo subject to decay or deterioration, normally fresh food and vegetables, etc.

Pier-to-House (P/H) | See "CY/CFS."

Pier-to-Pier (P/P) | See "CY/CFS."

PIP | See "Property Improvement Plan."

Place of Acceptance | See "Place of Receipt."

Place of Delivery | See "Final Destination."

Place of Receipt (P.O.R.) | Location where cargo enters the care and custody of the carrier. Same as Place of Acceptance. It is the starting port of carrier's liability upon receipt of cargo from shippers.

Port | (a) Harbor with piers or dock. (b) Left side of a ship when facing the bow. (c) Opening in a ship's side for handling freight.

Port of Arrival | Location where imported merchandise is off-loaded from the importing aircraft or vessel.

Port of Call | A port where a vessel discharges or receives traffic.

Port of Entry | A port where cargo and containers destined elsewhere are actually discharged from a vessel.

Port of Discharge (POD) | The port at which cargo or containers are unloaded from a vessel. When transshipment is needed, there can be a number of PODs during the course of shipment until it reaches the final POD.

Port of Loading (P.O.L.) | The port at which cargo or containers are loaded onto vessels.

Pre-Arrival Processing System (PAPS) | An electronic system that allows U.S. Customs to review and pre-release shipments for import into the U.S.

Pre-Arrival Review System (PARS/INPARS) | Available both at the border and inland (INPARS). An electronic system that allows CCRA to review and prerelease shipments for import into Canada.

Private Company | A company whose shares are not traded on the open market.

Product Improvement Plan / Property Improvement Plan (PIP) | A document, usually created by a hotel brand, that details the improvements that must be made to a hotel property to obtain or maintain that hotel brand flag. PIPs are usually created upon transfer of ownership and renewal of license agreements.

Project Management | A type of firm that works directly on behalf of the owner, managing all the portions of the design and construction work, and that generally holds no subcontracts.

Property Condition Assessment | A detailed inspection of a property's existing conditions often done as part of a property transfer or as a due diligence project.

Public Company | A company that has issued securities through a public offering, and whose securities are traded on the open market.

Purchasing Agent | An individual who is responsible for sourcing, quotations, negotiations, planning, coordinating, tenders, material inward etc. for the project's FF&E and OS&E.

Q

Quarantine | The period during which a vessel is detained in isolation until free from any contagious disease among the passengers or crew. The word is now applied to the sanitary regulations, which are the modern substitute for quarantine. During the quarantine period, the Q flag is hoisted.

Quarantine Buoy | One of the yellow buoys at the entrance of a harbor indicating the place where vessels must anchor for the exercise of quarantine regulations.

Quarantine Declaration | A document signed by the captain and the ship's doctor before the port health officer when a ship arrives at the quarantine station. It gives the name of the ship, tonnage, number of crew, first port of voyage and date of sailing, intermediate ports called, number of passengers for the port at which the vessel is arriving, number of transit passengers, cases of infectious diseases during voyage, deaths, nature of cargo, and name of agents. The port health officer then proceeds with the medical inspection of passengers and crew. Also called 'Entry Declaration.'

Quarantine Dues | A charge against all vessels entering a harbor to provide for the maintenance of medical control service. Also called "Quarantine Fees."

Quarantine Flag (Q Flag) | A yellow flag used as a sanitary signal. It is displayed by all vessels entering a harbor, and also when a contagious or infectious disease exists on board or when the vessel has been placed in quarantine.

Quarantine Harbor | A place where vessels in quarantine are stationed when arriving from contaminated ports.

Quarantine Station | A medical control center located in an isolated spot ashore where patients with contagious diseases from a vessel in quarantine are taken. It is also used for passengers and crews of vessels arriving from suspected ports while fumigation or any other disinfection is carried out onboard ship.

R

Real Estate Investment Trusts (REITs) | A company that purchases and manages a portfolio of real estate or real estate loans to earn profit for its shareholders, using money invested by its shareholders.

Received-for-Shipment Bill of Lading | A term used in contrast to shipped bill of lading or on-board bill of lading. This kind of bill of lading is normally issued to acknowledge receipt of shipment before cargo loading or before the official original bill of lading is issued. Nowadays, not many shippers ask for this kind of bill of lading.

Reefer | The generic name of a temperature-controlled container. The containers, which are insulated, are specially-designed to allow temperature-controlled air circulation within the container. A refrigeration plant is built into the rear of the container.

Relative Humidity % | The ratio of the actual amount of water vapor in the air to the maximum it can hold at a given temperature, multiplied by 100.

Relay | To transfer cargo from one ship to another of the same ownership.

Release Note | A receipt signed by a customer acknowledging the delivery of cargo.

Release Notification System (RNS) | The electronic notification system that provides customers, customs agencies, and customers' broker representatives with proactive notification of shipment acceptance, review, and release.

Repairs and Maintenance (R&M) | Preventative maintenance and normal repairs to equipment due to wear and tear. These repairs need to be done whether or not a property is being upgraded, renovated, or repositioned. For instance, replacing a filter on the HVAC system is an R&M item; replacing the entire HVAC system is a capital expense.

Return on Investment (ROI) | The monetary benefits derived from having spent money on developing or renovating a hotel.

RevPAR | Room Revenue Per Available Room, expressed as the product of the occupancy rate times the attained average daily rate.

Revenue Ton (R/T) | The greater weight of measurement of cargo where 1 ton is either 1,000 kilos or 1 cubic meter (for metric system). Also known as "Bill of Lading Ton" or "Freight Ton." It is used to calculate freight charges.

Roll-on/Roll-off (Ro/Ro) | A feature designed in the specially constructed vessel in both the loading and discharging ports.

Route | The plan of movements of a vessel from the first port of call to her final destination.

S

Said to Contain (STC) | A standard clause used to protect carriers, NVOCC operators, or forwarders when cargo are stuffed into the container by shippers, their agents, or other third parties. See also "Shipper's Load and Count."

Salvage | Property that has been recovered from a wrecked vessel or the recovery of the ship herself.

Salvage Clause | A marine insurance policy clause that states the proportion of salvage charges for which underwriters are liable.

Salvage Lien | A maritime lien that exists when a ship or goods come into the possession of one who preserves them from the perils at sea. All salvage services carry with them a maritime lien on the items saved.

Salvage Value | The value of which salvage is awarded. It generally means the value of ship and cargo when they have been brought to a place of safety by the salvors.

S-corporation | A form of corporation, allowed by the IRS for most companies with 75 or fewer shareholders, which enables the company to enjoy the benefits of incorporation, but be taxed as if it were a partnership.

Scope of Services | The itemized description of all services to be rendered by a consultant.

Scope of Work | The itemized description of all renovation or construction tasks in a capital project.

Seal | A metal strip and lead fastener used for locking containers, freight cars, or truck doors. Seals are numbered for record and security purposes.

Seal Record | A record of the number, condition, and marks of identification on seals made at various times and places, referring to the movement of the container between origin and destination.

Select Service Hotel | A hotel that offers only some of the facilities, services, and guest amenities typically offered by Full Service hotels, if offered at all. This product type largely reflects rooms-only operations, typically with nonexistent or very limited food and beverage options and meeting facilities.

Service Contract | The Shipping Act of 1984 of the U.S. allows a contract between a shipper or a shippers' association) and an ocean common carrier, NVOCC operator, or a Shipping Conference in which the shipper makes a commitment to provide a certain minimum quantity of cargo or freight revenue over a fixed time period, and the ocean common carrier, NVOCC operator, or conference commits to a certain rate or rate schedule and a defined service level (such as assured space, transit time, port rotation, or similar service features). The contract may also specify provisions in the event of nonperformance on the part of either party.

Ship Chandler | An individual or company selling equipment and supplies for ships.

Ship Owner | One of the persons in whom the title of property of a ship or ships is vested.

Ship Planning | A function in the operations of container vessels where containers have to be planned for loading onto vessels, taking into consideration the size and weight of containers, transshipment and discharging port rotation, types of cargo, etc. The officer responsible for such function is called a "Ship Planner."

Shipped Bill of Lading | A bill of lading issued only after the cargo has actually been shipped on board the vessel, as distinguished from the Received-for-Shipment bill of lading. Also see "On-board Bill of Lading."

Shipped On-board | Endorsement on a bill of lading confirming loading of cargoes or containers on a vessel.

Shipper | The person for whom the owners of a ship agree to carry goods to a specified destination and at a specified price. Also called "Consignor." The conditions under which the transportation is effected are stipulated in the bill of lading.

Shipper Owned Container (SOC) | The container used for cargo shipment is owned by the shipper.

Shipper's Export Declaration (SED) | A form often required prior to exporting a product. See "Overview of the Shipper's Export Declaration (SED)" for more information.

Shipper's Load and Count | Shipments loaded and sealed by shippers and not checked or verified by the carriers or forwarders. Neither the carriers nor the forwarders will assume any liability for shortages of cargo as long as the container seal remains intact at the time of devanning.

Shipping Order | A set of documents of carriers or forwarders that allows the shippers to book shipping space with them. There are a number of copies with the same form and contents but with different names – the 1st copy is called Shipping Order, and the remainder are called Shipping Order Copy or Dock Receipt – and for different purposes such as space control, surveyor, and sworn measurer, confirmation of receipt of cargo/ containers, etc. As EDI is more popular nowadays and used by both the shipper and Customs, a hard copy Shipping Order is no longer widely used.

Shipside Delivery | A special cargo handling instruction for cargo to be delivered right away at shipside after discharge.

Shop Drawings | Drawings of contractor- or vendorsupplied items (i.e. light fixtures, furniture) utilized in a renovation or a construction project. Shop drawings are submitted to the design team for review to verify a product's consistency with the item specified by the designer.

Shut-out | Cargo or containers that are not loaded on-board the intended vessel in line with the Shipping Order confirmed with the carrier.

Slot | Space on board a vessel occupied by a container.

Softgoods | This term can be defined differently by different firms. One common definition is that softgoods consist of everything in the guestroom that is not a casegood (i.e. softgoods would include lighting, wallcovering, artwork, etc.). Others would define softgoods as only the "soft" or fabric items in the room: window treatments and bed treatments, carpet and pad, and soft seating.

Stability | The force that holds a vessel upright or returns it to upright if keeled over. Weights on the lower hold increase stability. A vessel is still if it has high stability; tender if it has low stability.

Stack Car | An articulated five-platform railcar that allows containers to be double-stacked. A stack car holds ten 40-foot equivalent units.

Standard International Trade Classification (SITC) | A standard numerical code used by the United Nations to classify commodities used in international trade.

Stevedore | See "Longshoreman."

Store-Door Delivery (STOR/DOR) | Delivery of goods to the consignee's place of business or warehouse by motor vehicle. Refers to a complete package of delivery services performed by a carrier from origin to final consumption point, whether that be retail, wholesale, or other final distribution facility.

Store-Door Pickup | Picking up an empty container from a carrier, delivering it to a merchant, and returning the laden container; the portion of store-door pickup performed by the carrier's trucker.

Stowage | A marine team referring to loading freight into the ship's holds.

Straight Bill of Lading | A term for non-negotiable bill of lading.

Stripping | The unloading of a container.

Stuffing | The loading of a container.

Supply Air | Cooled or warmed air leaving the evaporator delivered to the interior of the container. Supply air is sometimes called delivery air.

Surcharge | An extra or additional charge.



T-floor | Interior floor in a reefer, so named because of the longitudinal T-shaped rails that support the cargo and form an plenum for air flow beneath the cargo.

Tail | The rear of a container.

Tank Container | A specially constructed container for transporting liquids and gases in bulk.

Tare Weight | The weight of packing material, or in car-load shipments, the weight of the empty freight car or the weight of the container.

Tariff | A publication setting forth the charges, rates, and rules of transportation companies.

Terminal | An assigned area in which containers are prepared for loading into a vessel or are stacked immediately after discharge from the vessel.

Terminal Handling Charge (THC) | A charge of carriers for recovering the costs of handling FCLs at container terminals at origin or destination.

Terminal Receiving Charge (TRC) | A charge assessed by the terminal for cargo being delivered for export.

Through Rate | The total rate from the point of origin to the final destination.

Through Service (Thru Service) | A combination of transportation by sea and land services to/from the point of origin to the final destination.

Time Charter | A charter party hiring a vessel for a specified period of time in which the ship owner provides the vessel, bunkers, and crew while the charterer supplies the cargo.

Time Volume Agreement (TVA) | A contract between a carrier and shipper specifying the movement of a number of containers over time.

Tonnage | Generally refers to freight handled.

Total Revenue | Total income for a hotel from all sources, such as room charges, FF&E income, meeting space rental income, etc.

Towage | The charge made for towing a vessel.

Tramp | A freighter vessel that does not run in any regular trade lane, but takes cargo wherever the shippers desire.

Transship | To transfer goods from one transportation line (trade line) to another or from one ship to another.

Transshipment Hub | A port that is employed by a carrier for transshipping its carriers from one transportation line (trade lane) to another.

Transit Cargo | Goods onboard, which upon their arrival at a certain port are not to be discharged at that port.

Transit Port | A port where cargo received is merely en route and from which they have to be transferred and dispatched to their ultimate destination by coasters, barge, and so on. Also called "Transshipment Port."

Twenty Foot (20') Equivalent Unit (TEU) | Commonly describes 20-foot container.

UCP500 | Revised and updated version of UCP operating from January 1, 1994.

UN | United Nations.

UNCTAD | United Nations Conference on Trade and Development

UNCTAD MMO | UNCTAD Multi-Modal Transport Convention

Underwriter | In marine insurance, one who subscribes his name to the policy indicating his acceptance of the liability mentioned therein, in consideration of which he receives a premium.

Uniform Customs and Practice of Documentary Credit (UCP) | The "Bankers Bible" on Documentary Credit Interpretation issued by the International Chamber of Commerce (I.C.C.).

Unit Load | Packages loaded on a pallet, in a crate, or any other way that enables them to be handled at one time as a unit.

Unit Train | A train of a specified number of railcars, perhaps 100, wherein the cars remain in a unit for a designated destination of until a change in routing is made.

Vanning | A term sometimes used for stowing cargo in a container.

VAT, Mexico | Valued-Added Tax on the portion of service provided by the Mexican carrier. The invoicing party is due to collect and remit this tax.

Vessel's Manifest | Statement of a vessel's cargo or containers (revenue, consignee, marks, etc.)

Voyage Charter | A charter party hiring a vessel for a particular voyage in which the ship owner provides the vessel, bunkers, and crew while the charterer supplies the cargo.

Voyage Direction | The sector of a round trip voyage normally denoted by the direction of the sailing.

Voyage Number | The numeric identification of a trip undertaken by a vessel on a fixed trade lane.

W =

War Risk | Insurance coverage for loss of goods resulting from any act of war.

Waybill (WB) | A document prepared by a transportation line at the point of a shipment. Shows the point of the origin, destination, route, consigner, consignee, description of shipment, and amount charged for the transportation service. A waybill is forwarded with the shipment or sent by mail to the agent at the transfer point or waybill destination. Unlike a bill of lading, a waybill is not a document of title.

Weight Cargo | A cargo on which the transportation charge is assessed on the basis of weight.

Wharfage | A charge assessed by a pier or dock owner against freight handled over the pier or dock or against a steamship company using the pier or dock.

JN+A and HVS DESIGN

7361 Calhoun Place, Suite 310 Rockville, MD 20855 ph: 301.670.1635 | ph: 240.683.7123 info@nehmer.com | designinfo@hvs.com nehmer.com | hvsdesign.com

Warren G. Feldman, AIA, ISHC | CEO | wfeldman@nehmer.com Scott P. Rosenberg, AIA, MRICS, LEED AP, BD+C | President | srosenberg@nehmer.com Christine Shanahan, NCIDQ, ASID | Principal | cshanahan@hvs.com